

<b>TREE SURVEY SCHEDULE</b>			
<b>Client:</b>	Danly UK Ltd		<b>Site:</b> High Meadow Close, Pinner, Middlesex HA5 2HD
<b>Date:</b>	5th February 2025		<b>Consultant:</b> Alexa Monk Tech Cert (Arbor A), NCH Arb
<b>Tagged:</b>	No		<b>Weather:</b> Dry

Notes:-

1. It may be advised that some trees should have the ivy removed to enable a re-survey to be carried out. This would also alleviate the tree from becoming suppressed; carrying additional weight that increases the chance of windthrow due to a larger dense crown area; and only receiving restricted light. Unless otherwise stated, in order to prevent regrowth, it is only necessary to remove a 300mm section of ivy and clear around the base.
2. It may be advised that it was only possible to estimate the diameter of some trees because of ivy smothering, dense vegetation, or trees located off-site with no access.
3. The estimated remaining contribution in years, and the tree grading category have been calculated for the current situation and may alter where further investigation works are advised.
4. Some trees or groups may have been given an interim grade. The reason for the interim grading is addressed in the timescales given as this may have a bearing on health and safety and/or any development proposals.
5. Tree Groups have been assessed with estimated and representative data.
6. This is not a Tree Works Schedule. Any preliminary management recommendations are listed in the interests of health and safety and should be carried out by a prudent tree owner.
7. Any management recommendations are suggested for reasons of health and safety only, regardless of development proposals at this stage. However, the defects requiring remedial tree surgery are by their very nature potential wildlife habitats, including protected species which needs consideration prior to any tree surgery works commencing.

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Branch Spread (m)				H't of Crown AGL (m)				Age	Physio- logical Condition	Structural Condition and Relevant Comments	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
1	Ash	14	S	340	7.0	8.0	6.0	6.0	4.0	3.0	5.0	5.0	EM	Good	Fair, off site tree. Unable to verify health and safety of basal area due to no access and 2m high wooden panel fence. Leans north. Bifurcated at 3m above ground level with minor dead wood in crown.	Gain access and re-survey within 1month	20+	Int B1
2	Hazel	5	MS	110 x 6	1.0	3.0	4.0	1.0	2.5	2.5	2.5	2.5	SM	Fair	Fair, multi stemmed at ground level. Coppice stool. Previously crown reduced on west side	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/Multi-Stemmed (S or MS)	Stem Diam (mm)	Branch Spread (m)				H't of Crown AGL (m)				Age	Physiological Condition	Structural Condition and Relevant Comments	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
					N	E	S	W	N	E	S	W						
3	Hazel	7	MS	100 x 8	2.0	3.0	3.0	1.0	3.0	3.0	3.0	3.0	SM	Fair	Fair, multi stemmed at ground level. Coppice stool. Previously crown reduced on west side	None required at time of survey	10+	C1
4	Holly	7	MS	110 100 100	2.0	2.0	1.0	0.5	3.0	3.0	3.0	3.0	SM	Fair	Fair, trifurcated at ground level. Previously crown reduced on west side.	None required at time of survey	10+	C1
5	Hawthorn	6	MS	200 190 140 110	2.0	2.5	2.0	0.0	3.0	3.0	3.0	0.0	SM	Fair	Fair, multi stemmed at ground level. Ivy on trunks with minor dead wood in crown.	None required at time of survey	10+	C1
6	Horse Chestnut	15	S	460	6.0	5.0	5.0	5.0	3.0	5.0	3.0	2.0	EM	Good	Fair, ivy on trunk. Bifurcated at 2m above ground level then again at 2.5m. Minor bark wounds in crown.	Sever ivy at base leaving a 300mm gap to prevent or limit re-growth within 12 months.	40+	B1