



**DM DRAINAGE LTD**  
 1 THE STABLES, LONG GREEN  
 BRAINTREE ESSEX CM77 8DL  
 Tel: (01376) 349624  
 Fax:  
 Email: info@dmdrainage.co.uk

## Inspection report

Date : <b>04/04/2016</b>	Job number : <b>0494</b>	Weather : <b>Dry</b>	Sewer category:	Section number : <b>3</b>	PLR suffix : <b>X</b>
Present :	Vehicle : <b>PR5 2 CAM</b>	Camera : <b>CRAWLER</b>	Preset :	Cleaned : <b>yes</b>	Operator : <b>D PARRISH</b>

Place : <b>HAYES</b>	Location details:	U/S MH : <b>S17</b>
Road : <b>NESTLE FACTORY</b>	Catchment:	U/S Depth :
Location Inspection <b>Footpath or verge</b> <b>S17 (D/S) S18</b>	Tape number : <b>001</b>	D/S MH : <b>S18</b>
	Pipe length :	D/S Depth :

Use: <b>Surface water</b>	Pipe shape : <b>Circular</b>
Year laid :	Pipe size : <b>450 mm</b>
Purpose : <b>Specific problems on sewer related to structural or service condition defects</b>	Pipe material : <b>Concrete</b>
Total length :	Lining :

Comment :

1:390	Position	Code	Observation	Photo	Grade
	0.00	ST	Start of Survey Remarks: S17		(Misc) 0
	0.00	WL	Water level, 5 % height/diameter		(Serv) 0
	24.50	JN	Junction at 10 o'clock, dia 150 mm		(Constr) 0
	25.30	JN	Junction at 02 o'clock, dia 150 mm		(Constr) 0
	32.40	JN	Junction at 10 o'clock, dia 150 mm		(Constr) 0
	47.90	MH	Manhole Remarks: S18		(Constr) 0
	47.90	FH	Finish Survey Remarks: S18		(Misc) 0

<b>Structural Defects</b>					<b>Constructional Features</b>				
<b>Service Defects</b>					<b>Miscellaneous Features</b>				
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1