

PHOTOGRAPHS RELATING TO MIDDLESEX SUITE EXTERNAL REPAIRS



2.11.1



2.10.1



2.10.1



2.10.1





2.10.1



2.10.1

 07.08.2019	 07.08.2019	
3.01.6.1	3.01.6.1	2.11.1
		
2.11.1	3.01.6.1	2.11.1

		
		
2.04.1 – 2.04.4	2.04.1 – 2.04.4	2.04.1 - 2.04.3 – 2.04.4



2.04.6

3.01.6.1





R4 - 2.05

R5 - 2.06



2.07

2.07



3.01.5.1



3.01.5.1




3.01.5.1



3.01.2.1



07.08.2019




07.08.2019



3.01.3.3




3.01.3.3




3.01.3.3



3.01.3.3



3.01.4.1 – 3.01.6.3



3.01.6.3

		
3.01.3.4	3.01.3.4	2.08