

Photos of the existing site – ventilation equipment



Photo of the southern elevation of the catering block

Existing extract fan to be removed and window reinstated

Location of proposed louvre on the top half of the sash window

Existing louvre to be replaced with new high performance louvre



Photo of the western elevation of the catering block

Location of proposed ductwork on the upper half of the sash window.