




Broken wall



185 bedroom left window wall after failed damp treatment and plastering



185 bedroom window sill after failed damp treatment course and plastering

