

## SITE PHOTOGRAPHS

THE OLD WORKHOUSE  
BREAKSPEAR ROAD NORTH  
HAREFIELD  
MIDDLESEX

FEBRUARY 2024




ROAD VIEW OF THE OLD WORKHOUSE.



FRONT VIEW OF HOUSE WITH DILAPIDATED TIMBER CONSERVATORY.



FRONT VIEW OF HOUSE WITH DILAPIDATED TIMBER CONSERVATORY.



DILAPIDATED TIMBER CONSERVATORY TO FRONT OF HOUSE.



PAINTED BRICKWORK TO REAR AND COURTYARD ELEVATIONS.



PAINTED SOFT, ERODED BRICKWORK TO REAR COURTYARD WING.



CAT-SLIDE ADDITION WITH LEANING CHIMNEY STACK ON EAST SIDE OF HOUSE.



INAPPROPRIATE ENGINEERING BRICKS INSTALLED IN STACK, POOR CEMENT TILE ABUTMENT AND POINTING ON EAST SIDE OF HOUSE.




INAPPROPRIATE ENGINEERING BRICKS INSTALLED IN CHIMNEY STACK ON WEST SIDE OF HOUSE.



COURTYARD VALLEY AND ROOFLIGHT.




COURTYARD ROOFLIGHT.



LAMINATED AND ERODED TILING TO COURTYARD ROOF SLOPES.



COURTYARD VALLEY AND ADJACENT TILING.



DORMER WITH CRACKED RENDER AND WINDOW REQUIRING OVERHAULING, NEW GLAZED CASEMENT WINDOW AND REDECORATION .



DORMER WITH CRACKED RENDER AND WINDOW REQUIRING OVERHAULING AND REDECORATION.



POOR CEMENT POINTING AND ERODED BRICKWORK TO INFILLED WINDOW OPENING ON EAST SIDE OF HOUSE.