

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 01:

This photograph shows a general view of the front elevation of the property.



PHOTOGRAPH 02:

This photograph shows main stepped cracking at the right hand side of the front elevation between ground and first floor windows.



PHOTOGRAPH 03:

This photograph shows a crack which is tapered in nature below the left hand side of the front right hand sitting room window.



PHOTOGRAPH 04:

This photograph shows a general view of the right hand side elevation to the property and the Policyholder's fir tree.

Barclays House, 20-24 Upper Market Street, Eastleigh, Hampshire, SO50 9FD

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 05:

This photograph shows a general view of the rear garden.



PHOTOGRAPH 06:

This photograph shows a general view of the right hand side elevation to the property.



PHOTOGRAPH 07:

This photograph shows a general rear elevation view of the property.



PHOTOGRAPH 08:

This photograph shows old cracking vertically above the right hand side sitting room on the rear elevation at the left hand side of the doorframe.

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 09:

This photograph shows the right hand side elevation and view of the single storey outbuilding provision.



PHOTOGRAPH 10:

This photograph shows vertical separation midway on the rear section of the outbuilding at the junction of the right hand return walling.



PHOTOGRAPH 11:

This photograph shows rotten fascia boarding above the rear central crack on the rear of the outbuilding.



PHOTOGRAPH 12:

This photograph shows cracking to the right hand top rendered section on the single storey outbuilding.

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 13:

This photograph shows cracking to the right hand side of the single storey playroom extension with tapered vertical cracking centrally below the window.



PHOTOGRAPH 14:

This photograph shows the right hand side wall junction to the rear single storey playroom extension with the main rear wall of the house at high level.



PHOTOGRAPH 15:

This photograph shows a general view of the left hand flank wall to the property.



PHOTOGRAPH 16:

This photograph shows a general view of the left hand side elevation, Utility room.

Barclays House, 20-24 Upper Market Street, Eastleigh, Hampshire, SO50 9FD

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 17:

This photograph is taken to the front wall of the single storey extension, right hand side stepped cracking.



PHOTOGRAPH 18:

This photograph shows a stepped crack to the front wall of the single storey side extension midway on the left hand side of the wall.



PHOTOGRAPH 19:

This photograph is a general view of the right hand side sitting room.



PHOTOGRAPH 20:

This photograph shows cracking local to the top left hand head of the rear French door opening.

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 21:

This photograph shows a horizontal fresh crack to the front right hand corner of the property approximately 1m above ground finish floor level.



PHOTOGRAPH 22:

This photograph shows the main cracking in the front sitting room wall right hand head of the window.



PHOTOGRAPH 23:

This photograph shows tapered vertical cracking below the front sitting room window left hand side.



PHOTOGRAPH 24:

This photograph shows a general view of the kitchen area.

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 25:

This photograph shows a general view of the left hand side utility room.



PHOTOGRAPH 26:

This photograph shows vertical separation in the utility room front right hand corner.



PHOTOGRAPH 27:

This photograph shows separation cracking in the utility room front head of the incoming door.



PHOTOGRAPH 28:

This photograph shows a general view of the rear playroom.

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 29:

This photograph shows crack damage to the right hand side wall of the playroom to the head of the window.



PHOTOGRAPH 30:

This photograph shows vertical cracking to the left hand side of the cupboard door in the playroom rear walling.



PHOTOGRAPH 31:

This photograph is taken of the rear left hand corner wall separation cracking in the rear playroom.



PHOTOGRAPH 32:

This photograph shows water staining to the front left hand corner ceiling in the playroom.

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 33:

This photograph shows vertical separation cracking which is tapered in nature to the front wall of the playroom further away in from the left hand corner.



PHOTOGRAPH 34:

This photograph shows vertical separation cracking in the rear left hand corner of the right hand side cupboard off the rear playroom extension.



PHOTOGRAPH 35:

This photograph is taken at first floor level on the landing area front door opening into the central bedroom.



PHOTOGRAPH 36:

This photograph is taken in the front right hand corner bedroom showing cracking below the front left hand side of the window.

OUR REF: L/2019/57462/S/LLB/sp/BC

REF: 35618710350

POLICYHOLDER: Mrs D Ramaiya

ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 37:

This photograph shows cracking in the front right hand bedroom top right hand corner of front window.



PHOTOGRAPH 38:

This photograph shows cracking to the rear wall in the rear right hand bedroom below the left hand side of the window.



PHOTOGRAPH 39:

This photograph shows localised cracking to top right hand corner of walling within the rear right hand corner bedroom.



PHOTOGRAPH 40:

This photograph shows the location of trial pit/borehole 01 to the front right hand corner of the property.

OUR REF: L/2019/57462/S/LLB/sp/BC
REF: 35618710350
POLICYHOLDER: Mrs D Ramaiya
ADDRESS: 2 Ebury Close, Northwood, Middlesex, HA6 2PF



PHOTOGRAPH 41:

This photograph shows the location of trial pit/borehole 02 standing to the left hand side front corner of the single storey side extension.



PHOTOGRAPH 42:

This photograph shows borehole 03 standing midway in the front garden to the property.