

Site Investigation Report

Auger Ref:

97316.5.TSI



Job Information

Client	Crawford & Co
Client ref	SU1903345
Visit date	26/03/2021
Report date	31/03/2021

Job Summary

- ✓ 1 trial hole undertaken. [Read more.](#)



Job Information

Overview

Brief	Auger were commissioned by Crawford & Co to undertake a site investigation within the area of concern at the property.
Trial Hole Findings	When carrying out TH1 we encountered water at a depth of 1.0m, however, we were able to auger past this point to collect samples.

Photographs


Trial Hole 1


Fig 1.1: Trial Hole 1 Location - Next to original trial hole location



Other Photos

Fig 7.1: Root samples collected




FRONT OF PROPERTY

This drawing should be used for diagrammatic purposes only. Auger are not responsible or liable for any 3rd party works undertaken using the details outlined in this drawing. Confirmation of the drainage configuration can only be confirmed by excavation or detailed technical survey.

LEGEND									
	= Manhole		= Blockage		= Lines not for repair		= Lines to be repaired		= Assumed water mains feed
	= Inspection Chamber		= swp/w/c		= Walls		= Fences		= Building Outline
	= Inspection Pot		= rwg		= rwp		= Steps		= Trial hole
					= gate / door		= Borehole		= Hedge
							= Tree		



Trial Hole Log No.1

Location: Front right corner of property

Job Ref: 97316.5.TSI

Depth (m)	Symbolic Log	Strata Description	Insitu Tests		Soil Sample	Root Sample
			SV(19)			
0.0						
0.0		200mm				
0.0		Ground Level				
0.0		Gravel				
0.0		Brickwork				
0.0		Concrete				
0.5						
1.0						
1.0			70kpa			Root @ 1m
1.2						Root @ 1.2m
1.5			60kpa			Root @ 1.5m
1.8						Root @ 1.8m
2.0		Moist stiff mottled silty CLAY	60kpa			Root @ 2.1m
2.5			90kpa			
3.0		TRIAL HOLE TERMINATED	110kpa			
3.0			110kpa			
3.5						