



7.2 Photographs



**Lounge, Room ID G03,
Wall Intrusion
(No Suspected Materials Seen)**



**Lounge, Room ID G03,
Floor Intrusion
(No Suspected Materials Seen)**




**11/1/3B/31/PC4, Bedroom, Room ID G04,
Damp Proof Course Under Sleeper Wall
(No Asbestos Detected)**



**Bedroom, Room ID G04,
Floor Intrusion
(No Suspected Materials Seen)**



**Bedroom, Room ID G04,
Wall Intrusion
(No Suspected Materials Seen)**



**Bedroom, Room ID G04,
Chimney Intrusion
(No Suspected Materials Seen)**