



OPTION 1 WITH A GABLE OVER PORCH AND PROJECTED FIRST FLOOR



FINALISED PROPOSED ELEVATION WITH A COMPLIMENTARY PORCH ROOF AND PEDIMENT.



OPTION 2 WITH A LEAN TO ROOF OVER PORCH AND CURVED BAYWINDOW

IN OPTION 1 NON ALIGNMENT OF THE LEAN TO ROOF OVER GROUND FLOOR BAY WINDOW AND THE PORCH ROOF DOES NOT LEAD TO A COHESIVE DESIGN AND HENCE WAS DISCARDED.

IN OPTION 2 THE EXISTING PORCH BEING BEYOND THE BAY WINDOW MADE IT IMPOSSIBLE TO HAVE THE LEAN TO ROOF CONTINUE OVER THE BAY WINDOW.HENCE THE LEAN TO ROOF BEING ONLY OVER THE PORCH DID NOT APPEAR COHESIVE AND SO THE DESIGN WAS DISCARDED.ALSO THE RELATIONSHIP BETWEEN THE PITCHED GABLE AND CURVED BAY WINDOW CREATED AN AWKWARD JUNCTION.