

**GATE PIER TO SOUTH EAST OF CEDARS HOUSE HILLINGDON.
PHOTOGRAPHS**



General view east side of wall looking south



East face of pier, looking west



East face of pier looking north



North face of pier



North face of pier



North face of pier prior to collapse. Spirit level is set plumb.



West face of pier prior to collapse. Spirit level is set plumb.



Base of west face of pier, looking north.



West face of pier looking north, prior to collapse taken at about 1000 above ground level.



West face of pier following collapse



West side of pier following collapse. Note the brick rubble core within the wall and the continuation of the pattern of holes in the brickwork into this area.