



FOR LARGER CRACKS LIKE THIS, BRICKWORK SHOULD BE LOCALLY REBUILT USING SIMILAR BRICKS AND LIME MORTAR

SMALLER CRACKS LIKE THIS SHOULD BE REPAIRED WITH HELIFIX TIES

INDICATIVE SCOPE OF REMEDIAL WORKS TO REAR ELEVATION

1892/260/SK04