APPENDICES

APPENDIX 1 – FIGURES

Project Name	Tavistock Building, Uxbridge	**Client**	Bradbrooks
Title	Site Location Plan	**Project No.**	P9651J926



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 1: Vehicle access to site.



Photo 2: Existing building on site.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 3: Undercroft parking.



Photo 4: Undercroft parking.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 5: Parking area to rear of building.



Photo 6: Undercroft parking.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 7: Office building on site.



Photo 8: Building on site and adjacent commercial site.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 9: Neighbouring commercial site.



Photo 10: Building on site.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 11:Undercroft parking area.



Photo 12: Parking area to the rear of the building.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 13: Rear of the building on site.



Photo 14: Possible substation in undercroft parking area.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 15: Undercroft car park.



Photo 16: Undercroft car park.



Project Name	Tavistock House	**Client**	Bradbrook Consulting
Title	Photographs of Site	**Project**	P9651J926

Photo 17: Possible substation on site.



Photo 18: Uncovered parking area to side of building.



APPENDIX 2 – GROUNDSURE REPORTS

Specialists in the investigation & reclamation of brownfield sites

Jomas Associates Ltd

Lakeside House, 1 Furzeground Way,
Stockley Park, UB11 1BD

Report Reference: HMD-377-3257334

Your Reference: P96514J926-1

Report Date 24 Aug 2016

Report Delivery Method: Email - pdf

Groundsure Geo Insight

Address: TAVISTOCK HOUSE, 5, ROCKINGHAM ROAD, UXBRIDGE, UB8 2UB

Dear Sir/ Madam,

Thank you for placing your order with Groundsure. Please find enclosed the **Groundsure Geo Insight** as requested.

If you need any further assistance, please do not hesitate to contact our helpline on +44843 289 2187 quoting the above report reference number.

Yours faithfully,

Jomas Associates Ltd

Enc.
Groundsure Geoinsight

Groundsure Geo Insight

Address:	**TAVISTOCK HOUSE, 5, ROCKINGHAM ROAD, UXBRIDGE, UB8 2UB**
Date:	**24 Aug 2016**
Reference:	**HMD-377-3257334**
Client:	**Jomas Associates Ltd**

NW N NE

W E



SW S SE

Aerial Photograph Capture date:	20-Apr-2013
Grid Reference:	504988,183879
Site Size:	0.08ha

Contents Page

Overview of Findings 5
1 Geology 8
1.1 Artificial Ground Map 8
1 Geology 9
1.1 Artificial Ground 9
1.1.1Artificial/ Made Ground 9
1.1.2 Permeability of Artificial Ground 9
1.2 Superficial Deposits and Landslips Map 10
1.2 Superficial Deposits and Landslips 11
1.2.1 Superficial Deposits/ Drift Geology 11
1.2.2 Permeability of Superficial Ground 11
1.2.3 Landslip 11
1.2.4 Landslip Permeability 12
1.3 Bedrock and Faults Map 13
1.3 Bedrock, Solid Geology & Faults 14
1.3.1 Bedrock/ Solid Geology 14
1.3.2 Permeability of Bedrock Ground 14
1.3.3 Faults 14
1.4 Radon Data 15
1.4.1 Radon Affected Areas 15
1.4.2 Radon Protection 15
2 Ground Workings Map 16
2 Ground Workings 17
2.1 Historical Surface Ground Working Features derived from Historical Mapping 17
2.2 Historical Underground Working Features derived from Historical Mapping 18
2.3 Current Ground Workings 18
3 Mining, Extraction & Natural Cavities Map 19
3 Mining, Extraction & Natural Cavities 20
3.1 Historical Mining 20
3.2 Coal Mining 20
3.3 Johnson Poole and Bloomer 20
3.4 Non-Coal Mining 20
3.5 Non-Coal Mining Cavities 21
3.6 Natural Cavities 21
3.7 Brine Extraction 21
3.8 Gypsum Extraction 21
3.9 Tin Mining 22
3.10 Clay Mining 22
4 Natural Ground Subsidence 23
4.1 Shrink-Swell Clay Map 23
4.2 Landslides Map 24
4.3 Ground Dissolution Soluble Rocks Map 25
4.4 Compressible Deposits Map 26
4.5 Collapsible Deposits Map 27
4.6 Running Sand Map 28
4 Natural Ground Subsidence 29
4.1 Shrink-Swell Clays 29
4.2 Landslides 29
4.3 Ground Dissolution of Soluble Rocks 30

4.4 Compressible Deposits....30
4.5 Collapsible Deposits....30
4.6 Running Sands....31
5 Borehole Records Map....32
5 Borehole Records....33
6 Estimated Background Soil Chemistry....35
7 Railways and Tunnels Map....36
7 Railways and Tunnels....37
7.1 Tunnels....37
7.2 Historical Railway and Tunnel Features....37
7.3 Historical Railways....38
7.4 Active Railways....38
7.5 Railway Projects....38

Overview of Findings

The Groundsure Geo Insight provides high quality geo-environmental information that allows geo-environmental professionals and their clients to make informed decisions and be forewarned of potential ground instability problems that may affect the ground investigation, foundation design and possibly remediation options that could lead to possible additional costs.

The report is based on the BGS 1:50,000 Digital Geological Map of Great Britain, BGS Geosure data; BRITPITS database; Shallow Mining data and Borehole Records, Coal Authority data including brine extraction areas, PBA non-coal mining and natural cavities database, Johnson Poole and Bloomer mining data and Groundsure's unique database including historical surface ground and underground workings.

For further details on each dataset, please refer to each individual section in the report as listed. Where the database has been searched a numerical result will be recorded. Where the database has not been searched '-' will be recorded.

Section 1:Geology		
1.1 Artificial Ground	1.1.1 Is there any Artificial Ground/ Made Ground present beneath the study site?	No
	1.1.2 Are there any records relating to permeability of artificial ground within the study site* boundary?	No
1.2 Superficial Geology and Landslips	1.2.1 Is there any Superficial Ground/Drift Geology present beneath the study site?	Yes
	1.2.2 Are there any records relating to permeability of superficial geology within the study site boundary?	Yes
	1.2.3 Are there any records of landslip within 500m of the study site boundary?	No
	1.2.4 Are there any records relating to permeability of landslips within the study site boundary?	No
1.3 Bedrock, Solid Geology & Faults	1.3.1 For records of Bedrock and Solid Geology beneath the study site* see the detailed findings section.	
	1.3.2 Are there any records relating to permeability of bedrock within the study site boundary?	Yes
	1.3.3 Are there any records of faults within 500m of the study site boundary?	No
1.4 Radon data	1.4.1 Is the property in a Radon Affected Area as defined by the Health Protection Agency (HPA) and if so what percentage of homes are above the Action Level?	The property is in a Radon Affected Area, as between 1 and 3% of properties are above the Action Level
	1.4.2 Is the property in an area where Radon Protection Measures are required for new properties or extensions to existing ones as described in publication BR211 by the Building Research Establishment?	No radon protective measures are necessary

Section 2:Ground Workings	On-site	0-50m	51-250	251-500	501-1000
2.1 Historical Surface Ground Working Features from Small Scale Mapping	0	11	10	Not Searched	Not Searched
2.2 Historical Underground Workings from Small Scale Mapping	0	0	0	0	0
2.3 Current Ground Workings	0	0	0	0	8

Section 3: Mining, Extraction & Natural Cavities	On-site	0-50m	51-250	251-500	501-1000
3.1 Historical Mining	0	0	0	0	0
3.2 Coal Mining	0	0	0	0	0
3.3 Johnson Poole and Bloomer Mining Area	0	0	0	0	0
3.4 Non-Coal Mining	0	0	0	1	1
3.5 Non-Coal Mining Cavities	0	0	0	0	0
3.6 Natural Cavities	0	0	0	0	0
3.7 Brine Extraction	0	0	0	0	0
3.8 Gypsum Extraction	0	0	0	0	0
3.9 Tin Mining	0	0	0	0	0
3.10 Clay Mining	0	0	0	0	0

Section 4: Natural Ground Subsidence	On-site
4.1 Shrink Swell Clay	Very Low
4.2 Landslides	Very Low
4.3 Ground Dissolution of Soluble Rocks	Negligible
4.4 Compressible Deposits	Moderate
4.5 Collapsible Deposits	Negligible
4.6 Running Sand	Low

Section 5: Borehole Records	On-site	0-50m	51-250
5 BGS Recorded Boreholes	0	1	13

Section 6: Estimated Background Soil Chemistry	On-site	0-50m	51-250
6 Records of Background Soil Chemistry	3	3	12


Section 7: Railways and Tunnels	On-site	0-50m	51-250	251-500
7.1 Tunnels	0	0	0	Not Searched
7.2 Historical Railway and Tunnel Features	0	0	0	Not Searched
7.3 Historical Railways	0	0	0	Not Searched
7.4 Active Railways	0	0	0	Not Searched

Section 7: Railways and Tunnels	On-site	0-50m	51-250	251-500
7.5 Railway Projects	0	0	0	0

1 Geology

1.1 Artificial Ground Map

NW N NE



W E

SW S SE

Artificial Ground Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.

Site Outline

500
1000
Search Buffers (m)

Made Ground (undivided)

Disturbed Ground (undivided)

Worked Ground (undivided)

Landscaped Ground (undivided)

Infilled Ground

Reclaimed Ground

1 Geology

1.1 Artificial Ground

1.1.1Artificial/ Made Ground

The following geological information represented on the mapping is derived from 1:50,000 scale BGS Geological mapping, Sheet No:255

Are there any records of Artificial/Made Ground within 500m of the study site boundary? No


Database searched and no data found.

1.1.2 Permeability of Artificial Ground

Are there any records relating to permeability of artificial ground within the study site boundary? No

Database searched and no data found.

1.2 Superficial Deposits and Landslips Map



Superficial Deposits and Landslips Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.

Site Outline

500
1000
Search Buffers (m)

1.2 Superficial Deposits and Landslips

1.2.1 Superficial Deposits/ Drift Geology

Are there any records of Superficial Deposits/ Drift Geology within 500m of the study site boundary? Yes

ID	Distance (m)	Direction	LEX Code	Description	Rock Description
1	0.0	On Site	ALV	ALLUVIUM	CLAY, SILT, SAND AND GRAVEL [UNLITHIFIED DEPOSITS CODING SCHEME]
2	208.0	E	TPGR	TAPLOW GRAVEL FORMATION	SAND AND GRAVEL [UNLITHIFIED DEPOSITS CODING SCHEME]
3	343.0	E	LHGR	LYNCH HILL GRAVEL MEMBER	SAND AND GRAVEL [UNLITHIFIED DEPOSITS CODING SCHEME]

1.2.2 Permeability of Superficial Ground

Are there any records relating to permeability of superficial ground within the study site boundary? Yes

Distance (m)	Direction	Flow Type	Maximum Permeability	Minimum Permeability
0.0	On Site	Intergranular	High	Very Low
0.0	On Site	Intergranular	High	Very Low

1.2.3 Landslip

Are there any records of Landslip within 500m of the study site boundary? No

Database searched and no data found.

This Geology shows the main components as discrete layers, these are: Artificial / Made Ground, Superficial / Drift Geology and Landslips. These are all displayed with the BGS Lexicon code for the rock unit and BGS sheet number. Not all of the main geological components have nationwide coverage.

1.2.4 Landslip Permeability


Are there any records relating to permeability of landslips within the study site* boundary? No

Database searched and no data found.

---

* This includes an automatically generated 50m buffer zone around the site

1.3 Bedrock and Faults Map



Bedrock and Faults Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.

Site Outline

500
1000
Search Buffers (m)

1.3 Bedrock, Solid Geology & Faults

The following geological information represented on the mapping is derived from 1:50,000 scale BGS Geological mapping, Sheet No:255

1.3.1 Bedrock/ Solid Geology

Records of Bedrock/ Solid Geology within 500m of the study site boundary:

ID	Distance (m)	Direction	LEX Code	Description	Rock Age
1	0.0	On Site	LMBE-CLSISA	Lambeth Group - Clay, Silt And Sand	No Details
2	44.0	S	LC-CLSISA	London Clay Formation - Clay, Silt And Sand	No Details

1.3.2 Permeability of Bedrock Ground

Are there any records relating to permeability of bedrock ground within the study site* boundary? Yes

Distance (m)	Direction	Flow Type	Maximum Permeability	Minimum Permeability
0.0	On Site	Mixed	Moderate	Very Low
0.0	On Site	Mixed	Moderate	Very Low
44.0	S	Mixed	Moderate	Very Low
46.0	S	Mixed	Moderate	Very Low

1.3.3 Faults

Are there any records of Faults within 500m of the study site boundary? No

Database searched and no data found.

The geology map for the site and surrounding area are extracted from the BGS Digital Geological Map of Great Britain at 1:50,000 scale.

This Geology shows the main components as discrete layers, these are: Bedrock/ Solid Geology and linear features such as Faults. These are all displayed with the BGS Lexicon code for the rock unit and BGS sheet number. Not all of the main geological components have nationwide coverage.

* This includes an automatically generated 50m buffer zone around the site

1.4 Radon Data

1.4.1 Radon Affected Areas

Is the property in a Radon Affected Area as defined by the Health Protection Agency (HPA) and if so what percentage of homes are above the Action Level? The property is in a Radon Affected Area, as between 1 and 3% of properties are above the Action Level


---

1.4.2 Radon Protection

Is the property in an area where Radon Protection are required for new properties or extensions to existing ones as described in publication BR211 by the Building Research Establishment? No radon protective measures are necessary


---

2 Ground Workings Map



Ground Workings Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.



2 Ground Workings

2.1 Historical Surface Ground Working Features derived from Historical Mapping

This dataset is based on Groundsure's unique Historical Land Use Database derived from 1:10,560 and 1:10,000 scale historical mapping.

Are there any Historical Surface Ground Working Features within 250m of the study site boundary? Yes

The following Historical Surface Ground Working Features are provided by Groundsure:

ID	Distance (m)	Direction	NGR	Use	Date
1A	23.0	W	505097 182450	Canal	1897
2A	23.0	W	505097 182450	Canal	1932
3D	24.0	W	504991 183018	Canal	1913
4B	24.0	W	504954 183544	Canal	1974
5B	24.0	W	504954 183544	Canal	1987
6B	24.0	W	504954 183544	Canal	1955
7	25.0	W	505139 182074	Canal	1864
8	26.0	W	504990 182997	Canal	1935
9C	27.0	W	504988 183019	Canal	1938
10C	27.0	W	504988 183019	Canal	1913
11D	32.0	W	504983 183023	Canal	1895
12E	106.0	NW	504916 184116	Unspecified Wharf	1938
13E	106.0	NW	504916 184116	Unspecified Wharf	1913
14F	167.0	N	505291 185672	Canal	1932
15F	167.0	N	505291 185672	Canal	1897
16	214.0	N	504954 184112	Unspecified Wharf	1932
17G	224.0	N	505097 184123	Mortuary	1935
18G	224.0	N	505097 184123	Mortuary	1913
19G	226.0	N	505096 184138	Mortuary	1932
20G	233.0	N	505105 184121	Mortuary	1938

ID	Distance (m)	Direction	NGR	Use	Date
21G	233.0	N	505105 184121	Mortuary	1913

2.2 Historical Underground Working Features derived from Historical Mapping

This data is derived from the Groundsure unique Historical Land Use Database. It contains data derived from 1:10,000 and 1:10,560 historical Ordnance Survey Mapping and includes some natural topographical features (Shake Holes for example) as well as manmade features that may have implications for ground stability. Underground and mining features have been identified from surface features such as shafts. The distance that these extend underground is not shown.

Are there any Historical Underground Working Features within 1000m of the study site boundary? No

Database searched and no data found.

2.3 Current Ground Workings


This dataset is derived from the BGS BRITPITS database covering active; inactive mines; quarries; oil wells; gas wells and mineral wharves; and rail deposits throughout the British Isles.

Are there any BGS Current Ground Workings within 1000m of the study site boundary? Yes

The following Current Ground Workings information is provided by British Geological Survey:

ID	Distance (m)	Direction	NGR	Commodity Produced	Pit Name	Type of working	Status
Not shown	520.0	SE	505449 183613	Sand & Gravel	Cowley Road Gravel Pits	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Ceased
Not shown	601.0	SE	505500 183545	Sand & Gravel	Cowley Road Grvael Pits	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Ceased
Not shown	603.0	SE	505554 183632	Sand & Gravel	Cowley Road Gravel Pits	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Ceased
Not shown	648.0	SW	504567 183358	Sand & Gravel	The Culvert Gravel Pit	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Ceased
Not shown	772.0	SE	505475 183260	Sand & Gravel	Chiltern View Gravel Pit	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Ceased
Not shown	844.0	NW	504300 184400	Sand & Gravel	New Denham Quarry	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Active
Not shown	907.0	SE	505680 183274	Clay & Shale	Chiltern View Brickfield	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Ceased
Not shown	959.0	SW	504180 183325	Sand & Gravel	Iver Heath	A surface mineral working. It may be termed Quarry, Sand Pit, Clay Pit or Opencast Coal Site	Ceased

3 Mining, Extraction & Natural Cavities Map



Mining, Extraction and Natural Cavities Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.



3 Mining, Extraction & Natural Cavities

3.1 Historical Mining

This dataset is derived from Groundsure unique Historical Land-use Database that are indicative of mining or extraction activities.

Are there any Historical Mining areas within 1000m of the study site boundary? No

Database searched and no data found.

3.2 Coal Mining

This dataset provides information as to whether the study site lies within a known coal mining affected area as defined by the coal authority.

Are there any Coal Mining areas within 1000m of the study site boundary? No

Database searched and no data found.

3.3 Johnson Poole and Bloomer

This dataset provides information as to whether the study site lies within an area where JPB hold information relating to mining.

Are there any JPB Mining areas within 1000m of the study site boundary? No

The following information provided by JPB is not represented on mapping: Database searched and no data found.

3.4 Non-Coal Mining

This dataset provides information as to whether the study site lies within an area which may have been subject to non-coal historic mining.

Are there any Non-Coal Mining areas within 1000m of the study site boundary? Yes

The following non-coal mining information is provided by the BGS:

ID	Distance (m)	Direction	Name	Commodity	Assessment of likelihood
1	343.0	E	Not available	Chalk	Small scale underground mining may have occurred; mine adits, shafts and tunnels may be present. Potential for localised difficult ground conditions are at a level where they should be considered

ID	Distance (m)	Direction	Name	Commodity	Assessment of likelihood
Not shown	836.0	W	Not available	Chalk	Small scale underground mining may have occurred; mine adits, shafts and tunnels may be present. Potential for localised difficult ground conditions are at a level where they should be considered

3.5 Non-Coal Mining Cavities

This dataset provides information from the Peter Brett Associates (PBA) mining cavities database (compiled for the national study entitled "Review of mining instability in Great Britain, 1990" PBA has also continued adding to this database) on mineral extraction by mining.

Are there any Non-Coal Mining cavities within 1000m of the study site boundary? No

Database searched and no data found.

3.6 Natural Cavities

This dataset provides information based on Peter Brett Associates natural cavities database.

Are there any Natural Cavities within 1000m of the study site boundary? No

Database searched and no data found.

3.7 Brine Extraction

This data provides information from the Coal Authority issued on behalf of the Cheshire Brine Subsidence Compensation Board.

Are there any Brine Extraction areas within 1000m of the study site boundary? No

Database searched and no data found.

3.8 Gypsum Extraction

This dataset provides information on Gypsum extraction from British Gypsum records.

Are there any Gypsum Extraction areas within 1000m of the study site boundary? No

Database searched and no data found.

3.9 Tin Mining

This dataset provides information on tin mining areas and is derived from tin mining records. This search is based upon postcode information to a sector level.

Are there any Tin Mining areas within 1000m of the study site boundary? No

Database searched and no data found.

3.10 Clay Mining

This dataset provides information on Kaolin and Ball Clay mining from relevant mining records.


Are there any Clay Mining areas within 1000m of the study site boundary? No

Database searched and no data found.

---

4 Natural Ground Subsidence

4.1 Shrink-Swell Clay Map




Shrink Swell Clay Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.



4.2 Landslides Map




Landslides Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.



4.3 Ground Dissolution Soluble Rocks Map




© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.

Ground Dissolution Soluble Rocks Legend



4.4 Compressible Deposits Map




Compressible Deposits Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.



4.5 Collapsible Deposits Map



Collapsible Deposits Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.



4.6 Running Sand Map



Running Sand Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.



4 Natural Ground Subsidence

The National Ground Subsidence rating is obtained through the 6 natural ground stability hazard datasets, which are supplied by the British Geological Survey (BGS).

The following GeoSure data represented on the mapping is derived from the BGS Digital Geological map of Great Britain at 1:50,000 scale.

What is the maximum hazard rating of natural subsidence within the study site*[*] boundary? Moderate

4.1 Shrink-Swell Clays

The following Shrink Swell information provided by the British Geological Survey:

ID	Distance (m)	Direction	Hazard Rating	Details
1	0.0	On Site	Very Low	Ground conditions predominantly low plasticity. No special actions required to avoid problems due to shrink-swell clays. No special ground investigation required, and increased construction costs or increased financial risks are unlikely due to potential problems with shrink-swell clays.
2	0.0	On Site	Very Low	Ground conditions predominantly low plasticity. No special actions required to avoid problems due to shrink-swell clays. No special ground investigation required, and increased construction costs or increased financial risks are unlikely due to potential problems with shrink-swell clays.

4.2 Landslides

The following Landslides information provided by the British Geological Survey:

ID	Distance (m)	Direction	Hazard Rating	Details
1	0.0	On Site	Very Low	Slope instability problems are unlikely to be present. No special actions required to avoid problems due to landslides. No special ground investigation required, and increased construction costs or increased financial risks are unlikely due to potential problems with landslides.
2	0.0	On Site	Very Low	Slope instability problems are unlikely to be present. No special actions required to avoid problems due to landslides. No special ground investigation required, and increased construction costs or increased financial risks are unlikely due to potential problems with landslides.

* This includes an automatically generated 50m buffer zone around the site

4.3 Ground Dissolution of Soluble Rocks

The following Ground Dissolution information provided by the British Geological Survey:

ID	Distance (m)	Direction	Hazard Rating	Details
1	0.0	On Site	Negligible	Soluble rocks are present, but unlikely to cause problems except under exceptional conditions. No special actions required to avoid problems due to soluble rocks. No special ground investigation required, and increased construction costs or increased financial risks are unlikely due to potential problems with soluble rocks.
2	0.0	On Site	Negligible	Soluble rocks are present, but unlikely to cause problems except under exceptional conditions. No special actions required to avoid problems due to soluble rocks. No special ground investigation required, and increased construction costs or increased financial risks are unlikely due to potential problems with soluble rocks.

4.4 Compressible Deposits

The following Compressible Deposits information provided by the British Geological Survey:

ID	Distance (m)	Direction	Hazard Rating	Details
1	0.0	On Site	Moderate	Significant potential for compressibility problems. Do not drain, load or de-water ground near the property without technical advice. For new build, consider possibility of compressible ground in ground investigation, construction and building design. Consider effects of groundwater changes. Extra construction costs are likely. For existing property, possible increase in insurance risk from compressibility, especially if water conditions or loading of the ground change significantly.
2	0.0	On Site	Moderate	Significant potential for compressibility problems. Do not drain, load or de-water ground near the property without technical advice. For new build, consider possibility of compressible ground in ground investigation, construction and building design. Consider effects of groundwater changes. Extra construction costs are likely. For existing property, possible increase in insurance risk from compressibility, especially if water conditions or loading of the ground change significantly.

4.5 Collapsible Deposits

The following Collapsible Rocks information provided by the British Geological Survey:


ID	Distance (m)	Direction	Hazard Rating	Details
1	0.0	On Site	Negligible	No indicators for collapsible deposits identified. No actions required to avoid problems due to collapsible deposits. No special ground investigation required, or increased construction costs or increased financial risk due to potential problems with collapsible deposits.
2	0.0	On Site	Negligible	No indicators for collapsible deposits identified. No actions required to avoid problems due to collapsible deposits. No special ground investigation required, or increased construction costs or increased financial risk due to potential problems with collapsible deposits.

4.6 Running Sands

The following Running Sands information provided by the British Geological Survey:

ID	Distance (m)	Direction	Hazard Rating	Details
1	0.0	On Site	Low	Possibility of running sand problems after major changes in ground conditions. Normal maintenance to avoid leakage of water-bearing services or water bodies (ponds, swimming pools) should reduce likelihood of problems due to running sand. For new build, consider possibility of running sand into trenches or excavations if water table is high or sandy strata are exposed to water. Avoid concentrated water inputs to site. Unlikely to be an increase in construction costs due to potential for running sand. For existing property, no significant increase in insurance risk due to running sand problems is likely.
2	0.0	On Site	Low	Possibility of running sand problems after major changes in ground conditions. Normal maintenance to avoid leakage of water-bearing services or water bodies (ponds, swimming pools) should reduce likelihood of problems due to running sand. For new build, consider possibility of running sand into trenches or excavations if water table is high or sandy strata are exposed to water. Avoid concentrated water inputs to site. Unlikely to be an increase in construction costs due to potential for running sand. For existing property, no significant increase in insurance risk due to running sand problems is likely.

5 Borehole Records Map



Borehole Records Legend

© Crown copyright and database rights 2016.
Ordnance Survey license 100035207.

Site Outline

Borehole Locations

125
250
Search Buffers (m)

5 Borehole Records

The systematic analysis of data extracted from the BGS Borehole Records database provides the following information.

Records of boreholes within 250m of the study site boundary: 14

ID	Distance (m)	Direction	NGR	BGS Reference	Drilled Length	Borehole Name
1	41.0	SW	504950 183830	TQ08SW30	36.88	THE DOLPHIN
2	73.0	SE	505030 183800	TQ08SE35	91.44	WATERWORKS UXBRIDGE
3	79.0	SE	505040 183800	TQ08SE238	33.53	UXBRIDGE PUMPING STATION, NO 1
4	95.0	W	504880 183880	TQ08SW28	121.92	BELL PUNCH CO LTD
5	97.0	SW	504910 183790	TQ08SW507	-1.0	RIVERSIDE WAY UXBRIDGE 2
6	105.0	SE	505080 183810	TQ08SE239	33.53	UXBRIDGE PUMPING STATION, NO 2
7	106.0	N	505000 184000	TQ08SE262	35.81	HURDLE YARD, UXBRIDGE
8	127.0	SW	504900 183760	TQ08SW506	-1.0	RIVERSIDE WAY UXBRIDGE 1
9	136.0	SE	505090 183770	TQ08SE237	91.44	UXBRIDGE PUMPING STATION
10	143.0	SE	505090 183760	TQ08SE38	106.68	WATERWORKS UXBRIDGE
11	181.0	E	505180 183960	TQ08SE36	60.96	WATERWORKS UXBRIDGE
12	195.0	SE	505100 183700	TQ08SE247	30.48	UXBRIDGE PUMPING STATION
13	203.0	NE	505170 184020	TQ08SE37	60.96	WATERWORKS UXBRIDGE
14	247.0	NE	505110 184120	TQ08SE39	61.56	WATERWORKS UXBRIDGE

The borehole records are available using the hyperlinks below: Please note that if the donor of the borehole record has requested the information be held as commercial-in-confidence, the additional data will be held separately by the BGS and a formal request must be made for its release.

#1: scans.bgs.ac.uk/sobi_scans/boreholes/575931
#2: scans.bgs.ac.uk/sobi_scans/boreholes/576368
#3: scans.bgs.ac.uk/sobi_scans/boreholes/576571
#4: scans.bgs.ac.uk/sobi_scans/boreholes/575929
#6: scans.bgs.ac.uk/sobi_scans/boreholes/576572
#7: scans.bgs.ac.uk/sobi_scans/boreholes/12082597
#9: scans.bgs.ac.uk/sobi_scans/boreholes/576570
#10: scans.bgs.ac.uk/sobi_scans/boreholes/576371
#11: scans.bgs.ac.uk/sobi_scans/boreholes/576369

#12: scans.bgs.ac.uk/sobi_scans/boreholes/576580
#13: scans.bgs.ac.uk/sobi_scans/boreholes/576370
#14: scans.bgs.ac.uk/sobi_scans/boreholes/576372