



Windows overlooked by the corridor – currently with no treatments



Windows overlooked by the corridor – currently with incorrectly applied reflective foil. Allows passers by to see in but staff cannot see out.



Sample of proposed frosting – this one with The Confederation Logo – which will help patients locate the clinic



All views from inside the office