



HUTCHEON EXAMINATION SERVICES LIMITED

Providing
Statutory Engineering Examinations



Client J Mould (Reading)
Address 1 Pingewood Close,
Reading,
Berkshire,
RG30 3XT

Contract No. 01/03/05/DIR
Report No. 1273911
Sub Location. Transfer Station
Berrys Lane
Reading
Berkshire
RG30 3XD

Report of Regular Thorough Examination in accordance with the requirements of:
Lifting Operations and Lifting Equipment Regulations 1998 (LOLER)
Provision and Use of Work Equipment Regulations 1998 (PUWER)

| | |
|--|---|
| Description of Lifting Equipment | Diesel Hydraulic 360° Tracked Excavator |
| Serial / Plant / Registration Numbers | HCMJAG53T00060276 / 3035 / - |
| Name of Manufacturer | Hitachi |
| Model | ZX490LCH-6 |
| Date of Manufacture | 2017 |
| Safe working loads or capacity for the configuration examined | Full lifting duties displayed in the cab, from the certified lifting point on the quick hitch (Unknown), lifting limit warning device switched on; no bucket fitted Seen fitted with 7.0m boom, 3.40m dipper arm, Geith fully-automatic twin-lock hydraulic quick hitch serial No. 932045 and Dehaco hydraulic demolition grab serial No. 3086089. |
| Certificates of Conformity & / or Test | None seen |
| Defects which are, or could become a danger to persons, including any required repairs to be completed: | None. |
| A(1) Immediately | |
| A(2) By a specified date | |
| If none, state (None) | |
| Other Defects and observations | The operators entry steps are distorted. The quick hitch data plate is missing. The nearside main boom ram outer seal is detached. Hours: 5351.1 |

I certify that the equipment described in this report was thoroughly examined on **26/07/2023** and that subject to satisfactory repair of any defects recorded at this examination, is safe to operate.

Competent Person:

Date of last examination: 31/08/2022

Date of next examination: 26/07/2024

Mr J Thomas-O'Brien, EngTech, MSOE,
MBES

Date of report: 27/07/2023

Qualification:

Engineer Surveyor

Page 1 of 1