



<p>Generally: Bath stone colour and texture etc to match existing. Red hatch is where new bath stone facing is required.</p> <p>Rainwater Goods - all existing cast iron works to be retained in place unless full salvage is possible, if not all lost, including pipes, hoppers and brackets works are to be prioritised on the south elevation.</p>	<p>colony</p> <p>Project: Gateway at Hillingdon Uxbridge Cemetery Uxbridge Road, UB10 0JF</p> <p>Drawing Name: Proposed North Elevation</p> <p>Collaborating with: Total Construction & Hillingdon Council</p> <p>Job: 1048 Drawing: 05-11 Revision: -</p> <p>Drawn By: HS Status: planning Checked By: SH</p>	<p>Project: Gateway at Hillingdon Uxbridge Cemetery Uxbridge Road, UB10 0JF</p> <p>Drawing Name: Proposed North Elevation</p> <p>Collaborating with: Total Construction & Hillingdon Council</p> <p>Job: 1048 Drawing: 05-11 Revision: -</p> <p>Drawn By: HS Status: planning Checked By: SH</p>	<p>RIBA Chartered Practice</p> <p>Colony Architects Ltd. The Wine Store, Brewery Court, Theale, Reading, RG7 5AJ +44 (0)118 380 0328 hello@colonyarchitects.com colonyarchitects.com</p>
NOTES	1:50 01 02 03 04 05 06		