

T1 Crack Willow: (T10 on TPO) Located on land adjacent Amberley Way


- Remove as close to ground level as practicable.


This tree recently suffered a stem loss due to extensive hollowing.
There is evidence of previous historic stem failures.
There is audible decay present in all the stems.
I believe this tree poses a risk and I believe the tree will carry on failing once in leaf.











Some of the cavities present.

Tree Solutions has not carried out any work in Amberley Way.
We were asked specifically by Chaneys Chartered Surveyors to give an opinion on this one specific tree.