




FRONT ELEVATION

Marley Acme single camber mixed brindle clay plain roof tiles  
to all slopes and ground floor side addition.

Black half-round pvc-u guttering and down-pipes to all elevations  
with gutters supported off black half-round top fix rafter brackets.

NOTES.


1. Allow for replacing felted flat roof, laid to falls to outlets and code 5 lead abutment flashings.
2. Black pvc-u half-round rainwater gutters supported off black half-round top fix steel rafter brackets.
3. Black pvc-u rainwater down-pipes to discharge into new gullies that are connected to existing surface water drainage system or new soakaways located minimum 5 meters away from the nearest building.




SIDE ELEVATION

Marley Acme single camber mixed brindle clay plain roof tiles  
to all slopes and ground floor side addition.

Black half-round pvc-u guttering and down-pipes to all elevations  
with gutters supported off black half-round top fix rafter brackets.



A		19.2.2025		Revised notes	
ORCHARD ASSOCIATES 32 WHITEHALL ROAD HARROW ON THE HILL MIDDLESEX					
MR R. SYMONS					
39 NICHOLAS WAY NORTHWOOD MIDDLESEX					
PROPOSED ELEVATIONS					
1:50 at A1		326	104	A	
Jan. 2025					