

5 Coniston Gardens



The property has not been occupied for more than 2 years and it has not been modified or refurbished in more than 20 years. The house required complete restoration with full electrical, drainage, gas and other utilities as well as structural upgrades. The property itself will benefit from the extra bedroom and space to allow for the current owner family safe and comfortable use.









