



Property Risk Inspection

LIMITED

Our Ref: 175285

Statement of Reasons for Tree Preservation Order Application to fell and treat stump of one Oak tree (T2) at: 73 Ladygate Lane, Ruislip HA4 7QX in relation to subsidence at 75 Ladygate Lane, Ruislip HA4 7QX

TPO Ref: TPO 534 (T1 on schedule)

1. The above tree works are proposed as a remedy to the differential foundation movement at the insured property and to ensure the long-term stability of the building.
2. The above tree works are proposed to limit the extent and need for expensive and disruptive engineering repair works at the insured property. In this instance the estimated repair costs are likely to vary between **£10,000** and **£100,000**, depending upon whether the tree/s can be removed or must remain.
3. The above tree works are proposed to limit the extent and need for costly CO2e emissions relating to alternative engineering repair works at the insured property. A typical underpinning scheme can include a carbon cost of more than **6000 kg** CO2e and soil stabilisation or root barriers more than **4000 kg** CO2e. A typical tree might capture between **15-40kg** CO2e per annum and would therefore take centuries to mitigate the cost in CO2e on any alternative. We also confirm that the applicant has included this scheme and application in its tree planting and carbon capture off-set scheme for trees causing subsidence to low rise buildings which has already seen some **11,000** trees planted and additionally **220 tonnes** of carbon captured.
4. The above tree works are proposed to limit the duration of any claim period and therefore allow the landowner their right to the peaceful enjoyment of their property.
5. It is the case that an alternative to felling such as pruning or significant 'pollarding' of the tree would not provide a reliable or sustainable remedy to the subsidence in this case. We do not consider that any other potential means of mitigation, including root barriers, would be effective or appropriate in the circumstances.
6. We are satisfied that the evidence obtained following completion of our Arboricultural Implication Assessment report completed 11/11/2020 clearly links the Oak T2 as a cause of damage to the risk address.
7. Insurers understanding the requirement to offer replacement planting in the event consent to fell is granted.
8. Should you wish to visit the address or to discuss any technical matters your technical liaison in this instance is Henry Collings who can be contacted on 07740 737412. We stress we would be happy to meet or to have any discussion if this allows the Council to fully understand our application and the issues surrounding this. Your technical liaison can also handle any technical information or clarification regarding technical matters.
9. Please read this as part of a dual submission alongside application to fell and treat stump of Oak T1 at 77 Ladygate Lane, Ruislip HA4 7QX.

Helen Klarner
Mitigation Co-Ordinator
PRI Insurance Services

Tel: 01206 751 626
Email: insurance@propertyriskinspection.co.uk
Website: www.propertyriskinspection.co.uk

Version control:
20240625 PRI TPO Statement of Reasons V5.1

A Limited Company Registration: 09116918

2 The Courtyards, Phoenix Square, Wyncolls Road,
Severals Park, Colchester, Essex
CO4 9PE

VAT Registration Number: 202 5315 61