

Site Inspection Report

**Single storey side and rear extension part two storey
side and rear extension at existing two storey dwelling**

**191 Long Lane, Hillingdon, Uxbridge, Middlesex, UB10
9JW**

UL235731

Inspection Number: 1
Inspection Date: 25/03/2021
Inspected By: Raj Singh

Excavations

Excavations dug to strip foundations

CLIENT AND CONTRACTOR PRESENT FOR INSPECTION

FOUNDATIONS COMMENCED AND FIRST SECTION DUG 1M DEEP, 1.2M IN LENGTH AND 700MM WIDE.

GROUND APPEARS TO BE CONSISTENT DARK CLAY THROUGHOUT

2NO DRAINS FOUND WHICH APPEAR TO BE PRIVATE DRAINS WITH A SEPERATE STORM AND FOUL SYSTEM

ADVISED THE CLIENT TO SEEK ADVICE FROM HER ARCHITECT/ ENGINEER IN REGARDS TO THE DEPTH OF THE REMAINING FOUNDATIONS DUE TO THE CLOSE PROXIMITY OF A BROAD LEAF TREE.

PROPOSAL TO BE SUBMITTED BEFORE CONTINUING WITH WORKS.



NOTE : This inspection report is restricted to requirements covered by Building Regulations current at that time. It does not constitute evidence that the Building Regulations have been satisfied until a Completion / Final Certificate has been issued for the project. It remains the responsibility of the person carrying out the work to ensure that the work complies with the Building Regulations.