LEGEND

BEL	Belisha Beacon	RWP	Rainwater Pipe
BOL	Bollard	SB	Shrub Bed
BRS	Brick Setts	SG	Strip Gully
BS	Bus Stop	SP	Sign Post
BSH	Bus Shelter	SPS	Stone Paving Slabs
CBX	Control Box	SRL	Single Red Line
CC	Coal Chute	STN	Survey Station
CH	Cellar Hatch	SWL	Single White Line
CL	Cover Level	SYL	Single Yellow Line
CONC	Concrete	TCB	Telephone Call Box
CPS	Concrete Paving Slabs	TL	Top Level
CR	Cycle Rail	TP	Telegraph Pole
CTV	Cable TV Valve	TPS	Tactile Paving Slabs
DRL	Double Red Line	TS	Traffic Signal
DWB	Dog Waste Bin	UN	Unmade
EL	Eaves Level	UTL	Unable To Lift
ER	Earthing Rod	VP	Vent Pipe
FB	Flower Bed	WL	Water Level
FH	Fire Hydrant	WV	Water Valve
FL	Floor Level		
G	Gully		
GRS	Granite Setts		
GV	Gas Valve		
H	High		
IC	Inspection Cover		
ICE	IC Electric		
ICG	IC Gas		
ICT	IC Telecom		
ICTC	IC Traffic Control		
ICTV	IC Cable TV		
ICW	IC Water		
IL	Invert Level		
KO	Kerb Outlet		
LB	Litter Bin		
LC	Lighting Column		
OH	Overhead		
P	Post		
PB	Post Box		
PDM	Pay & Display Machine		
PL	Pavement Light		
PM	Parking Meter		
PP	Pedestrian Push-point		
RE	Roding Eye		
RL	Road Level		
RS	Road Sign		

FENCES & WALLS

BAW	Barbed Wire
BBW	Breeze/brick Wall
BP	Brick Pillar
BRTW	Brick Retaining Wall
BW	Brick Wall
CB	Close Boarded
CI	Corrugated Iron
CLK	Chain Link
CP	Chestnut Paling
CRTW	Concrete Retaining Wall
CW	Concrete Wall
HDG	Heading
HR	Handrail
IR	Iron Railings
MS	Metal Security
OB	Open Boarded
PR	Post & Rail
PW	Post & Wire
SM	Steel Mesh
SW	Stone Wall
TR	Trellis
WM	Wire Mesh

TREES

Oak 100.4/12
Species Spread/Diameter/Height
MB ≥ 3.5Ob-Bole

NOTES

The accuracy of this survey drawing is dependent upon the scale at which it is produced. Users should not re-scale this drawing without consent.

The OS Co-ordinate grid and levels shown have been derived via multiple Network RTK GPS Observations.

This is an update of drawing 3898-1 with the trees which have been felled since the original survey removed. This update is based on the felled trees being shown on a plan by others. ALAN RHODES ARA have not undertaken a site visit to verify which trees have been removed. The sizes of the remaining trees have not been updated to reflect any growth. None of the other detail shown on the drawing has been checked for changes made since the time of the original survey.

DRAWING NO : 4288

DATE : 18/2/21	DRAWN : SV
SHEET NO : 1 of 1	CHECKED : MB
SCALE : 1:250	SHEET SIZE : A0

CLIENT :

NHS Property Services Ltd
99 Gresham Street
London
EC2V 7NG

PROJECT TITLE :

Topographic Survey
Former Northwood & Pinner Hospital
Pinner Road
Northwood, HA6 1DE

SURVEYED BY :

ALAN RHODES ASSOCIATES
Land & Measured Building Surveyors
8 Hurlingham Studios
Ranelagh Gardens
London SW6 3PA
Tel : 020 7731 0304
Fax: 020 7731 0314
email : office@ara-survey.co.uk

THE SURVEY ASSOCIATION