



93HMO-002.1 - View of the access road from Nicholls Avenue
(vehicular crossover in place for many decades)



93HMO-002.2 - Closer view of the access road – well worn car tracks are visible



93HMO-002.3 - Photo taken stood to the rear of a garage at the rear of Harlington Road and facing towards Nicholls Avenue. The access road is clearly visible. The blue clinker/hardcore is also clearly visible and has been in situ since the 1970's.