


APPENDIX C

Site Photographs



Photographic plate 1 – View of the existing property



Photographic plate 2 – Existing mature oak trees in the southwestern corner where WS07 was conducted



Photographic plate 3 – Soft landscaping along the northern boundary where WS01, WS02 and WS03 were conducted



Photographic plate 4 – WS01 backfilled after excavation



Photographic plate 5 – Samples collected between 1.3 to 1.6m bgl from WS01



Photographic plate 6 – Selenite crystals encountered from 2.5m bgl in WS01

Client

Hillingdon Borough Council



Project

Charville Lane


Job No


CGK/00808

Title

Site Photographs



Page 1 of 5

		
Photographic plate 7 – Location of WS02	Photographic plate 8 – WS02 backfilled after excavation	Photographic plate 9 – material excavated from WS02 between 2 to 2.45m bgl
		
Photographic plate 10 – material excavated from WS02 between 3.5 to 4m bgl	Photographic plate 11 – Spoil from WS02	Photographic plate 12 – WS03 backfilled after excavation
Hillingdon Borough Council	Charville Lane	CGK/00808
	Site Photographs	Page 2 of 5

		
Photographic plate 13 – Spoil from WS03 and view of the open exploratory hole	Photographic plate 14 – Core from 2.0 to 3.0m bgl from WS03	Photographic plate 15 – WS04 backfilled after excavation
		
Photographic plate 16 – WS04 backfilled after excavation	Photographic plate 17 – very coarse roots encountered in WS04 at ~0.45m bgl	Photographic plate 18 – Arisings from WS05
Client Hillingdon Borough Council	Project Charville Lane	Job No CGK/00808
	Site Photographs	
Page 3 of 5		

		
Photographic plate 19 – WS05 backfilled after excavation	Photographic plate 20 – material excavated from WS05 between 2.5 to 3m bgl	Photographic plate 21 – WS06 backfilled after excavation
		
Photographic plate 22 – material excavated from WS06 between 3.5 to 4m bgl	Photographic plate 23 – WS07 backfilled after excavation	Photographic plate 24 – View to the north of WS07

Hillingdon Borough Council	Charville Lane	CGK/00808
Client	Project	Job No
	Site Photographs	
Title		Page 4 of 5

		
Photographic plate 25 – Material excavated from WS07 between 1.8 to 2m bgl	Photographic plate 26 – Area to the west of the property which was inaccessible to the drilling rig. Approximate location of proposed garden of House C	Photographic plate 27 – Areas marked out for the GPR survey

Client

Hillingdon Borough Council

Project

Charville Lane

Job No

CGK/00808

Title



Site Photographs

Page 5 of 5