

SITE PHOTOGRAPHS

THE OLD WORKHOUSE
BREAKSPEAR ROAD NORTH
HAREFIELD
MIDDLESEX

MARCH 2024



ROAD VIEW OF THE OLD WORKHOUSE.



STREET VIEW OF TIMBER BOARDED ENTRANCE GATE.



STREET VIEW OF TIMBER BOARDED ENTRANCE GATE AND BRICK PIERS.



GARDEN VIEW OF TIMBER BOARDED ENTRANCE GATE.




FRONT VIEW OF HOUSE WITH DILAPIDATED TIMBER CONSERVATORY.



DILAPIDATED TIMBER CONSERVATORY TO FRONT OF HOUSE.



FRONT VIEW OF HOUSE WITH DILAPIDATED TIMBER CONSERVATORY.



VIEW OF FRONT PRINCIPAL ENTRANCE DOOR.



VIEW OF FRONT PRINCIPAL ENTRANCE DOOR.



VIEW OF FRONT PRINCIPAL ENTRANCE DOOR OPENING WITH DAMAGED BRICK REVEALS AND BRICK ARCH.