

Section A-A



Datum 80.00m

Important Information:
Any Drainage that has been investigated should be checked against statutory records to confirm details before proceeding with any design work.
We advise that an arborologist be appointed to correctly determine the species and condition of all trees surveyed prior to any design work.
All information contained in this drawing (including digital data) should be checked and verified prior to any fabrication or construction.

Survey Legend

FENCES		
BARBED WIRE FENCE	BW	Trees
CORRUGATED IRON FENCE	CI	
CLOSE BOARD FENCE	CB	
CHESTNUT PALING FENCE	CP	Hedges
IRON PALING FENCE	IR	
POST AND CHAIN FENCE	PC	
POST AND RAIL FENCE	PR	
POST AND WIRE FENCE	PW	
CHAIN LINK FENCE	CL	
LARCH LAP FENCE	LL	
INTERWOVEN FENCE	IW	
WIRE MESH FENCE	WM	
ABBREVIATIONS		
BOLLARD	Bu	MARKER
BRITISH TELECOM IC	BT	NOTICE BOARD
CONCRETE PAVING SLABS	CPS	PARKING METER
COVER LEVEL	CL	ROAD NAME PLATE
DROP KERB	DK	ROAD SIGN
ELECTRIC INSPECTION COVER	EC	RODDING EYE
ELECTRICITY POLE	EP	RETAINING WALL
FIRE HYDRANT	TH	RANWATER PIPE
FLOWER BED	FB	STOP VALVE
FOOTPATH	FP	TELEGRAPH POLE
GRAB VALVE	GV	TELEPHONE CALL BOX
GULLY	Gy	TRAFFIC LIGHT
INSPECTION COVER	IC	UNABLE TO LIFT
PIPE INVERT LEVEL	I	UNKNOWN
HEIR OUTLET	KO	VENT PIPE
MAN HOLE	MH	WATER METER
THRESHOLD	TH	DIAMETER
WINDOW SILL LEVEL	WSL	UNDER SEAM LEVEL
WINDOW HEAD LEVEL	WHL	FLOOR LEVEL
CEILING LEVEL	CL	DOOR HEAD LEVEL

Section Layout



Grid: (OSBG36) site centered on STN 1 with scale factor 1.
Values have been derived via GPS using OS active network using the OSGM15 transformation and OSGM15 Grid model.
Levelling: Ordnance Datum

Drawing Title:
Section A-A

Site Address:
24 Duck's Hill Rd
Northwood
HA6 2NR

Client:
YNS Properties Ltd

Surveyor	MSM	Drawn By	MSM	Verified By	ATS	Date	20.12.2024
----------	-----	----------	-----	-------------	-----	------	------------

MIC No: MIC/MBS0064	Rev: 001
Scale: 1:50m @ A1	Date: 31.12.2024