

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
05_Staff Base 006		-	87	-	75
05_Staff Base 007		-	87	-	78
05_Staff Base 008		-	199	-	5
05_Staff Change 001		-	64	-	208
05_Staff Change 002		-	74	-	153
05_Staff Rest/Bev 001		110	-	-	127
05_Staff Rest/Bev 002		104	-	-	150
05_Staff Rest/Bev 003		104	-	-	150
05_Stair A		-	69	-	154
05_Stair C 001		-	71	-	162
05_Stair C 002		-	72	-	160
05_Stair D		-	68	-	159
05_Store 001		114	-	-	67
05_Store 002		101	-	-	103
05_Store 003		167	-	-	28
05_Store 004		167	-	-	29
05_Store 005		141	-	-	63
05_Treatment (2-sided) 001		-	169	-	123
05_Treatment (2-sided) 002		-	170	-	122
05_Treatment (2-sided) 003		-	169	-	123
05_Unit Pantry 001		100	-	-	79
05_Unit Pantry 002		106	-	-	70
05_Unit Pantry 003		100	-	-	78
05_Visitor Lift Lobby 001		-	108	-	136
05_Visitor Lift Lobby 002		-	109	-	132
05_Visitor Lift Lobby 003		-	108	-	137
05_WC 001		-	134	-	20
05_WC 002		-	134	-	21
05_WC 003		-	134	-	14
05_WC 004		-	134	-	14
05_WC 005		-	134	-	18
05_WC 006		-	134	-	16
05_WC 007		-	134	-	21
05_WC 008		-	134	-	18
05_WC 009		-	134	-	16
05_WC 010		-	134	-	18
05_WC 011		-	134	-	14
05_WC 012		-	134	-	23
05_WC 013		-	134	-	24
05_WC 014		-	134	-	22
05_WC 015		-	134	-	20
05_WC 016		-	134	-	19
05_WC 017		-	134	-	19

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
05_WC 018		-	134	-	24
05_WC 019		-	134	-	15
05_WC/Shower: A. Trolley 001		-	80	-	98
05_WC/Shower: A. Trolley 002		-	79	-	101
05_WC/Shower: A. Trolley 003		-	80	-	100
05_WC: Semi amb 001		-	134	-	26
05_WC: Semi amb 002		-	134	-	26
05_WC: Semi amb 003		-	134	-	21
05_WC: Semi amb 004		-	134	-	27
05_WC: Semi amb 005		-	134	-	21
05_WC: Semi amb 006		-	134	-	26
06_4 Bed bay 001		-	75	-	477
06_4 Bed bay 002		-	78	-	441
06_4 Bed bay 003		-	78	-	442
06_4 Bed bay 004		-	78	-	443
06_4 Bed bay 005		-	78	-	443
06_4 Bed bay 006		-	76	-	476
06_A WC/Shower 001		-	86	-	94
06_A WC/Shower 002		-	111	-	64
06_A WC/Shower 003		-	110	-	65
06_A WC/Shower 004		-	100	-	64
06_A. WC 001		-	116	-	51
06_A. WC 002		-	113	-	53
06_A. WC 003		-	131	-	43
06_A. WC/Shower 001		-	101	-	63
06_A. WC/Shower 002		-	101	-	63
06_Bariatric Bedroom 001		-	143	-	115
06_Bariatric Bedroom 002		-	151	-	95
06_Bariatric Bedroom 003		-	147	-	103
06_BED/FM Lift Lobby 001		-	91	-	190
06_BED/FM Lift Lobby 002		-	92	-	186
06_BED/FM Lift Lobby 003		-	92	-	187
06_BED/FM Lift Lobby 004		-	92	-	186
06_Breast Feed		-	143	-	60
06_C.U. 001		141	-	-	45
06_C.U. 002		134	-	-	46
06_Circulation 001		-	76	-	411
06_Circulation 002		-	79	-	538
06_Circulation 003		-	79	-	567
06_Circulation 004		-	130	-	67
06_Circulation 005		-	84	-	319
06_Circulation 006		-	101	-	95
06_Circulation 007		-	76	-	410

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_Circulation 008		-	90	-	144
06_Circulation 009		-	140	-	53
06_Cleaners 001		167	-	-	21
06_Cleaners 002		134	-	-	35
06_Cleaners 003		128	-	-	37
06_Cleaners 004		155	-	-	28
06_Clinical Psychology Office		173	-	-	101
06_Corporate Office 001		239	-	-	42
06_Corporate Office 002		235	-	-	43
06_Corporate Office 003		239	-	-	42
06_Corridor 001		-	104	-	357
06_Corridor 002		-	93	-	88
06_Corridor 003		-	87	-	640
06_Corridor 004		-	104	-	234
06_Corridor 005		-	102	-	241
06_Corridor 006		-	130	-	31
06_Corridor 007		-	188	-	16
06_Corridor 008		-	98	-	626
06_Corridor 009		-	83	-	305
06_Corridor 010		-	141	-	47
06_Corridor 011		-	101	-	257
06_Corridor 012		-	89	-	323
06_Corridor 013		-	121	-	70
06_Corridor 014		-	89	-	304
06_Corridor 015		-	88	-	353
06_Corridor 016		-	91	-	811
06_Corridor 017		-	93	-	794
06_Corridor 018		-	89	-	351
06_Corridor 019		-	88	-	633
06_Corridor 020		-	123	-	165
06_CU 001		129	-	-	50
06_CU 002		134	-	-	46
06_CU 003		140	-	-	46
06_CU 004		133	-	-	48
06_D.U. 001		113	-	-	63
06_D.U. 002		107	-	-	70
06_Disposal 001		152	-	-	38
06_Disposal 002		134	-	-	47
06_Disposal 003		167	-	-	29
06_Disposal 004		131	-	-	48
06_DU 001		106	-	-	69
06_DU 002		112	-	-	64
06_DU 003		108	-	-	69

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_DU 004		105	-	-	71
06_Elec Cup 001		176	-	-	18
06_Elec Cup 002		176	-	-	22
06_Elec Cup 003		176	-	-	13
06_Elec Cup 004		176	-	-	13
06_Elec Cup 005		176	-	-	18
06_Ensuite 001		-	131	-	28
06_Ensuite 002		-	131	-	28
06_Ensuite 003		-	131	-	28
06_Ensuite 004		-	131	-	27
06_Ensuite 005		-	131	-	27
06_Ensuite 006		-	131	-	27
06_Ensuite 007		-	131	-	28
06_Ensuite 008		-	131	-	28
06_Ensuite 009		-	131	-	27
06_Ensuite 010		-	131	-	28
06_Ensuite 011		-	131	-	29
06_Ensuite 012		-	131	-	27
06_Ensuite 013		-	131	-	27
06_Ensuite 014		-	131	-	28
06_Ensuite 015		-	131	-	28
06_Ensuite 016		-	131	-	28
06_Ensuite 017		-	131	-	28
06_Ensuite 018		-	131	-	28
06_Ensuite 019		-	131	-	28
06_Ensuite 020		-	131	-	27
06_Ensuite 021		-	131	-	27
06_Ensuite 022		-	131	-	27
06_Ensuite 023		-	131	-	28
06_Ensuite 024		-	131	-	28
06_Ensuite 025		-	131	-	27
06_Ensuite 026		-	131	-	28
06_Ensuite 027		-	131	-	28
06_Ensuite 028		-	131	-	28
06_Ensuite 029		-	131	-	28
06_Ensuite 030		-	131	-	27
06_Ensuite 031		-	131	-	28
06_Ensuite 032		-	131	-	28
06_Ensuite 033		-	131	-	29
06_Ensuite 034		-	131	-	28
06_Ensuite 035		-	131	-	28
06_Ensuite 036		-	131	-	27
06_Ensuite 037		-	131	-	26

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_Ensuite 038		-	131	-	27
06_Ensuite 039		-	131	-	28
06_Ensuite 040		-	131	-	27
06_Ensuite 041		-	131	-	27
06_Ensuite 042		-	131	-	26
06_Ensuite 043		-	131	-	27
06_Ensuite 044		-	131	-	27
06_Ensuite 045		-	131	-	28
06_Ensuite 046		-	131	-	28
06_Ensuite 047		-	131	-	27
06_Ensuite 048		-	131	-	28
06_Ensuite 049		-	131	-	28
06_Ensuite 050		-	131	-	28
06_Ensuite 051		-	131	-	27
06_Ensuite 052		-	131	-	27
06_Ensuite 053		-	131	-	28
06_Ensuite 054		-	131	-	28
06_Ensuite 055		-	131	-	28
06_Ensuite 056		-	131	-	27
06_Ensuite 057		-	131	-	28
06_Ensuite Bariatric 001		-	116	-	37
06_Ensuite Bariatric		-	111	-	40
06_Ensuite Bariatric		-	107	-	43
06_Eq Bay 001		167	-	-	6
06_Eq Bay 002		135	-	-	11
06_Eq Bay 003		167	-	-	6
06_Eq Bay 004		167	-	-	6
06_Eq Store 001		113	-	-	68
06_Eq Bay 005		167	-	-	5
06_Eq Bay 006		150	-	-	6
06_Eq Store 002		114	-	-	67
06_Food Court Seating		-	136	-	734
06_Interview 001		211	-	-	54
06_Interview 002		224	-	-	48
06_Interview 003		212	-	-	50
06_Interview 004		195	-	-	57
06_Interview 005		178	-	-	68
06_Interview 006		190	-	-	73
06_Iso Lobby 001		-	145	-	43
06_Iso Lobby 002		-	176	-	36
06_Iso Lobby 003		-	127	-	55
06_Iso Lobby 004		-	173	-	37
06_Iso Lobby 005		-	178	-	33

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_Iso Lobby 006		-	180	-	34
06_Iso Single Bedroom 001		-	154	-	88
06_Iso Single Bedroom 002		-	149	-	96
06_Iso Single Bedroom 003		-	149	-	96
06_IT HUB 001		274	-	-	83
06_IT HUB 002		276	-	-	82
06_IT HUB 003		276	-	-	82
06_Kitchens and Servery		-	80	-	2067
06_Linen 001		156	-	-	31
06_Linen 002		167	-	-	8
06_Linen 003		167	-	-	19
06_Linen 004		167	-	-	17
06_Linen 005		167	-	-	14
06_Linen 006		167	-	-	19
06_Linen 007		167	-	-	15
06_Lobby		-	150	-	61
06_Lockers 001		100	-	-	33
06_Lockers 002		109	-	-	47
06_Lockers 003		112	-	-	46
06_MDT Room 001		139	-	-	178
06_MDT Room 002		102	-	-	227
06_MDT Room 003		111	-	-	189
06_MDT Room 004		136	-	-	127
06_MDT Room 005		131	-	-	132
06_MDT Room 006		137	-	-	180
06_MDT Room 007		133	-	-	153
06_MDT Room 008		102	-	-	223
06_Meds Store/Prep 001		106	-	-	173
06_Meds Store/Prep 002		112	-	-	202
06_Meds Store/Prep 003		107	-	-	171
06_Meeting Room 001		107	-	-	238
06_Meeting Room 002		107	-	-	193
06_Meeting Room 003		103	-	-	215
06_Nappy Change		-	131	-	43
06_Office 001		173	-	-	82
06_Office 002		191	-	-	72
06_Office 003		201	-	-	54
06_Office 004		187	-	-	61
06_Office 005		146	-	-	102
06_On-Call Room 001		-	172	-	56
06_On-Call Room 002		-	172	-	56
06_Open Plan for 14 people 001		112	-	-	299
06_Open Plan for 14 people 002		111	-	-	305

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_Open Plan for 6 people		137	-	-	170
06_POD		-	293	-	19
06_Resus Bay 001		-	293	-	5
06_Resus Bay 002		-	293	-	3
06_Resus Bay 003		-	293	-	6
06_Resus Bay 004		-	180	-	4
06_Resus Bay 005		-	293	-	5
06_Resus Bay 006		-	293	-	3
06_Shared Admin 001		115	-	-	210
06_Shared Admin 002		117	-	-	236
06_Shared Admin 003		123	-	-	177
06_Shared Admin 004		115	-	-	207
06_Shared Admin 005		119	-	-	191
06_Shared Day Space		120	-	-	193
06_Shower		-	131	-	29
06_Single Bedroom 001		-	155	-	104
06_Single Bedroom 002		-	155	-	103
06_Single Bedroom 003		-	155	-	103
06_Single Bedroom 004		-	156	-	102
06_Single Bedroom 005		-	157	-	100
06_Single Bedroom 006		-	155	-	103
06_Single Bedroom 007		-	154	-	104
06_Single Bedroom 008		-	156	-	101
06_Single Bedroom 009		-	155	-	103
06_Single Bedroom 010		-	154	-	104
06_Single Bedroom 011		-	155	-	102
06_Single Bedroom 012		-	155	-	102
06_Single Bedroom 013		-	155	-	102
06_Single Bedroom 014		-	155	-	103
06_Single Bedroom 015		-	155	-	104
06_Single Bedroom 016		-	156	-	102
06_Single Bedroom 017		-	155	-	102
06_Single Bedroom 018		-	156	-	102
06_Single Bedroom 019		-	155	-	103
06_Single Bedroom 020		-	156	-	102
06_Single Bedroom 021		-	156	-	101
06_Single Bedroom 022		-	156	-	102
06_Single Bedroom 023		-	155	-	103
06_Single Bedroom 024		-	156	-	102
06_Single Bedroom 025		-	156	-	102
06_Single Bedroom 026		-	156	-	102
06_Single Bedroom 027		-	156	-	102
06_Single Bedroom 028		-	157	-	101

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_Single Bedroom 029		-	154	-	103
06_Single Bedroom 030		-	155	-	103
06_Single Bedroom 031		-	155	-	103
06_Single Bedroom 032		-	155	-	102
06_Single Bedroom 033		-	154	-	105
06_Single Bedroom 034		-	156	-	101
06_Single Bedroom 035		-	155	-	103
06_Single Bedroom 036		-	157	-	100
06_Single Bedroom 037		-	155	-	103
06_Single Bedroom 038		-	154	-	105
06_Single Bedroom 039		-	154	-	104
06_Single Bedroom 040		-	154	-	104
06_Single Bedroom 041		-	151	-	107
06_Single Bedroom 042		-	157	-	100
06_Single Bedroom 043		-	155	-	103
06_Single Bedroom 044		-	158	-	99
06_Single Bedroom 045		-	155	-	103
06_Single Bedroom 046		-	155	-	103
06_Single Bedroom 047		-	156	-	101
06_Single Bedroom 048		-	155	-	103
06_Single Bedroom 049		-	156	-	102
06_Single Bedroom 050		-	151	-	108
06_Single Bedroom 051		-	156	-	102
06_Single Bedroom 052		-	156	-	102
06_Single Bedroom 053		-	156	-	102
06_Single Bedroom 054		-	157	-	100
06_Staff Base 001		-	78	-	78
06_Staff Base 002		-	71	-	76
06_Staff Base 003		-	76	-	76
06_Staff Base 004		-	77	-	75
06_Staff Base 005		-	87	-	78
06_Staff Base 006		-	71	-	75
06_Staff Breakout		94	-	-	253
06_Staff Change		-	69	-	138
06_Staff Rest (wellbeing)		94	-	-	327
06_Staff Rest/Bev 001		104	-	-	151
06_Staff Rest/Bev 002		104	-	-	150
06_Staff Rest/Bev 003		104	-	-	149
06_Stair		-	64	-	614
06_Stair A		-	69	-	154
06_Stair C 001		-	71	-	162
06_Stair C 002		-	72	-	160
06_Stair D		-	68	-	159

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_Store 001		102	-	-	101
06_Store 002		141	-	-	63
06_Store 003		161	-	-	34
06_Store 004		167	-	-	28
06_Store 005		158	-	-	41
06_Store 006		101	-	-	103
06_Therapy Assmnt & Treat 001		-	166	-	135
06_Therapy Assmnt & Treat 002		-	165	-	130
06_Therapy Office: 6 workstations 001		151	-	-	159
06_Therapy Office: 6 workstations 002		142	-	-	176
06_Treatment (2 sided) 001		-	170	-	122
06_Treatment (2 sided) 002		-	169	-	123
06_Treatment (2 sided) 003		-	170	-	122
06_TSU Gym		-	110	-	349
06_Unit Pantry 001		106	-	-	70
06_Unit Pantry 002		100	-	-	79
06_Unit Pantry 003		100	-	-	78
06_Virtual Booth 001		-	293	-	34
06_Virtual Booth 002		-	293	-	34
06_Virtual Booth 003		-	293	-	33
06_Visitor Lift Lobby 001		-	109	-	132
06_Visitor Lift Lobby 002		-	108	-	137
06_Visitor Lift Lobby 003		-	108	-	136
06_WC 001		-	120	-	50
06_WC 002		-	134	-	41
06_WC 003		-	134	-	31
06_WC 004		-	134	-	31
06_WC 005		-	134	-	18
06_WC 006		-	134	-	18
06_WC 007		-	134	-	21
06_WC 008		-	134	-	27
06_WC 009		-	134	-	27
06_WC 010		-	134	-	14
06_WC 011		-	134	-	31
06_WC 012		-	134	-	33
06_WC 013		-	134	-	26
06_WC 014		-	134	-	23
06_WC 015		-	134	-	15
06_WC 016		-	134	-	24
06_WC 017		-	134	-	17
06_WC 018		-	134	-	20
06_WC 019		-	134	-	28
06_WC 020		-	134	-	20

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
06_WC 021		-	134	-	21
06_WC 022		-	134	-	17
06_WC 023		-	134	-	14
06_WC 024		-	134	-	21
06_WC 025		-	134	-	14
06_WC 026		-	134	-	19
06_WC Semi amb 001		-	134	-	21
06_WC Semi amb 002		-	134	-	26
06_WC Semi amb 003		-	134	-	27
06_WC/Shower A Trolley 001		-	79	-	102
06_WC/Shower A Trolley 002		-	79	-	101
06_WC/Shower A Trolley 003		-	80	-	98
06_WC Semi amb 004		-	134	-	21
06_WC Semi amb 005		-	134	-	26
06_WC Semi amb 006		-	134	-	26
06_Zone Hub St.		112	-	-	63
07_Bed/FM Lift Lobby 001		-	88	-	186
07_Bed/FM Lift Lobby 002		-	88	-	186
07_Bed/FM Lift Lobby 003		-	87	-	190
07_Bed/FM Lift Lobby 004		-	87	-	187
07_Circulation 001		-	74	-	410
07_Circulation 002		-	80	-	286
07_Circulation 003		-	95	-	95
07_Circulation 004		-	77	-	442
07_Circulation 005		-	77	-	534
07_Circulation 006		-	74	-	411
07_Corridor		-	127	-	50
07_Decontamination Room: Inc Bed Washer		-	94	-	248
07_IT Hub 001		189	-	-	325
07_IT Hub 002		198	-	-	226
07_IT Store		63	-	-	890
07_Library/Decontamination		138	-	-	76
07_MEP Plant 001		58	-	-	14982
07_MEP Plant 002		60	-	-	4731
07_MEP Plant 003		60	-	-	139
07_MEP Plant 004		102	-	-	71
07_Stair A		-	66	-	156
07_Stair C 001		-	69	-	160
07_Stair C 002		-	68	-	162
07_Store		74	-	-	162
07_Store: Beds		72	-	-	259
B1_A. WC 001		-	127	-	44
B1_A. WC 002		-	132	-	42

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
B1_A. WC 003		-	122	-	47
B1_A. WC 004		-	134	-	39
B1_A. WC 005		-	126	-	45
B1_BED/FM Lift Lobby 001		-	91	-	190
B1_BED/FM Lift Lobby 002		-	92	-	187
B1_BED/FM Lift Lobby 003		-	92	-	186
B1_BED/FM Lift Lobby 004		-	92	-	186
B1_Bev Bay		-	173	-	16
B1_Bulk Fluid Store		70	-	-	222
B1_Central Consumables St		75	-	-	170
B1_Circulation 001		-	76	-	410
B1_Circulation 002		-	90	-	144
B1_Circulation 003		-	80	-	369
B1_Circulation 004		-	101	-	95
B1_Circulation 005		-	83	-	325
B1_Circulation 006		-	88	-	171
B1_Circulation 007		-	77	-	398
B1_Circulation 008		-	81	-	633
B1_Cleaners 001		128	-	-	37
B1_Cleaners 002		134	-	-	38
B1_Cleaners 003		133	-	-	39
B1_Cleaners 004		139	-	-	37
B1_Cleaning Equipment St		72	-	-	203
B1_Clinical Trials St.		112	-	-	65
B1_Cold Room St		65	-	-	449
B1_Cold St.		111	-	-	73
B1_Cons. St.		131	-	-	49
B1_Controlled Drugs		119	-	-	228
B1_Corridor 001		-	90	-	268
B1_Corridor 002		-	98	-	769
B1_Corridor 003		-	101	-	344
B1_Corridor 004		-	106	-	151
B1_Corridor 005		-	119	-	69
B1_Corridor 006		-	178	-	39
B1_Corridor 007		-	146	-	91
B1_Corridor 008		-	137	-	62
B1_Dispensary		77	-	-	3419
B1_Disposal 001		121	-	-	61
B1_Disposal 002		139	-	-	47
B1_Disposal 003		80	-	-	137
B1_Disposal 004		130	-	-	48
B1_Distribution St.		113	-	-	96
B1_Drug Cupboard Secure		114	-	-	61

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
B1_Dry Goods St		70	-	-	230
B1_Entrance Lobby		-	188	-	19
B1_Eq. Store 001		105	-	-	71
B1_Eq. Store 002		123	-	-	60
B1_Freezer St.		88	-	-	112
B1_Fridge Bariatric		105	-	-	78
B1_Goods Inward		83	-	-	142
B1_IT HUB 001		286	-	-	75
B1_IT HUB 002		303	-	-	66
B1_IT HUB 003		321	-	-	58
B1_IT HUB 004		270	-	-	87
B1_IT HUB 005		264	-	-	91
B1_IT HUB 006		264	-	-	91
B1_Linen		106	-	-	146
B1_Linen & Disposables		118	-	-	45
B1_Lobby 001		-	150	-	61
B1_Lobby 002		-	123	-	80
B1_Management		150	-	-	129
B1_MEP PLANT 001		58	-	-	3263
B1_MEP PLANT 002		78	-	-	846
B1_MEP PLANT 003		68	-	-	379
B1_MEP PLANT 004		66	-	-	429
B1_MEP PLANT 005		74	-	-	216
B1_MEP PLANT 006		67	-	-	395
B1_MEP PLANT 007		74	-	-	241
B1_MEP PLANT 008		73	-	-	225
B1_MEP PLANT 009		73	-	-	223
B1_MEP PLANT 010		68	-	-	366
B1_MEP PLANT 011		76	-	-	198
B1_MEP PLANT 012		78	-	-	852
B1_MEP PLANT 013		67	-	-	397
B1_MEP PLANT 014		77	-	-	189
B1_MEP PLANT 015		73	-	-	234
B1_MEP PLANT 016		75	-	-	207
B1_MEP PLANT 017		73	-	-	227
B1_MEP PLANT 018		69	-	-	350
B1_MEP PLANT 019		67	-	-	410
B1_MEP PLANT 020		70	-	-	327
B1_MEP PLANT 021		65	-	-	602
B1_MEP PLANT 022		77	-	-	249
B1_MEP PLANT 023		72	-	-	245
B1_MEP PLANT 024		67	-	-	390
B1_Micro Fibre Laundry		-	49	-	458

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
B1_Office		146	-	-	100
B1_Office (Admin) 001		117	-	-	204
B1_Office (Admin) 002		159	-	-	84
B1_Office (Managnt) 001		185	-	-	80
B1_Office (Managnt) 002		183	-	-	62
B1_Office (Managnt) 003		187	-	-	63
B1_Office (Managnt) 004		166	-	-	82
B1_Office (Managnt) 005		162	-	-	84
B1_Office: Open Plan 001		106	-	-	148
B1_Office: Open Plan 002		135	-	-	106
B1_Office; Medical Examiner		228	-	-	63
B1_Patient Handling/Body Store		-	65	-	2749
B1_Post Room		87	-	-	285
B1_Prep: Diet Bay		-	88	-	686
B1_Preparation Area		-	99	-	372
B1_Regeneration		-	93	-	423
B1_Secure Goods St		124	-	-	59
B1_Secure Lobby		-	124	-	49
B1_Shower: Staff 001		-	131	-	21
B1_Shower: Staff 002		-	131	-	22
B1_St Clean Consm & Chem		106	-	-	81
B1_Staff Change 001		-	71	-	150
B1_Staff Change 002		-	72	-	148
B1_Staff Lobby		-	94	-	119
B1_Staff Rest/Bev 001		128	-	-	152
B1_Staff Rest/Bev 002		125	-	-	151
B1_Staff Rest/Bev 003		148	-	-	141
B1_Stair		-	124	-	61
B1_Stair A		-	69	-	154
B1_Stair C 001		-	73	-	152
B1_Stair C 002		-	73	-	154
B1_Stair D		-	68	-	159
B1_Store		131	-	-	61
B1_Store: In		62	-	-	581
B1_Store: Out/Transit		65	-	-	338
B1_Switchgear 001		176	-	-	22
B1_Switchgear 002		176	-	-	15
B1_Switchgear 003		176	-	-	44
B1_Switchgear 004		176	-	-	31
B1_Viewing Room		-	170	-	31
B1_Visitor Entrance/Wait		-	147	60	144
B1_Visitor Lift Lobby		-	108	-	136
B1_Wash Area		-	90	-	323

General lighting and display lighting		Luminous efficacy [lm/W]			General lighting [W]
Zone name		Luminaire	Lamp	Display lamp	
	Standard value	60	60	22	
B1_Washing Room		-	87	-	127
B1_WC 001		-	134	-	28
B1_WC 002		-	134	-	25
B1_WC 003		-	134	-	28
B1_WC 004		-	134	-	35
B1_WC 005		-	134	-	32
B1_WC 006		-	134	-	28
B1_Workspace		111	-	-	265
01_Lobby 001		-	154	-	39
CP_00_Cafe		-	35	-	1181

Criterion 3: The spaces in the building should have appropriate passive control measures to limit solar gains

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_4 Bed Bay 001	NO (-86.9%)	NO
00_4 Bed Bay 002	NO (-86.8%)	NO
00_4 Bed Bay 003	NO (-86.8%)	NO
00_4 Bed Bay 004	NO (-86.8%)	NO
00_4 Bed Bay 005	NO (-60.5%)	NO
00_4 Bed Bay 006	NO (-86.8%)	NO
00_4 Bed Bay 007	NO (-73.1%)	NO
00_4 Bed Bay 008	NO (-59.9%)	NO
00_4 Bed Bay 009	NO (-86.8%)	NO
00_Adult Resus 001	NO (-80.9%)	NO
00_Adult Resus 002	N/A	N/A
00_Adult Resus 003	NO (-89.4%)	NO
00_Adult Resus 004	N/A	N/A
00_Adult Resus 005	N/A	N/A
00_Adult Resus 006	NO (-91.6%)	NO
00_Amb. Triage/Transfer 001	N/A	N/A
00_Amb. Triage/Transfer 002	N/A	N/A
00_Amb. Triage/Transfer 003	N/A	N/A
00_Amb. Triage/Transfer 004	N/A	N/A
00_Amb. Triage/Transfer 005	N/A	N/A
00_Amb. Triage/Transfer 006	N/A	N/A
00_Baby Feed	NO (-74.7%)	NO
00_Beds: Single Room 001	NO (-72.5%)	NO
00_Beds: Single Room 002	NO (-63.4%)	NO
00_Beds: Single Room 003	NO (-46.5%)	NO
00_Beds: Single Room 004	NO (-26.7%)	NO
00_Bier View	N/A	N/A
00_Breast Feed	N/A	N/A
00_C.U. 006	NO (-77.5%)	NO
00_C.U. 009	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_Cafe	NO (-45.5%)	NO
00_Cashier Office	NO (-29%)	NO
00_CE/Treat 001	N/A	N/A
00_CE/Treat 002	N/A	N/A
00_CE/Treat 003	N/A	N/A
00_CE/Treat 004	N/A	N/A
00_Child Wait	NO (-90.5%)	NO
00_Corridor 024	NO (-86.3%)	NO
00_CT Control	NO (-71.9%)	NO
00_CT Scanner	NO (-86.1%)	NO
00_Decon. Lobby	N/A	N/A
00_E-Triage 001	NO (-99.9%)	NO
00_E-Triage 002	NO (-99.9%)	NO
00_E-Triage 003	NO (-99.9%)	NO
00_Ensuite 001	NO (-97%)	NO
00_Ensuite 002	NO (-89.4%)	NO
00_Ensuite 003	NO (-83.3%)	NO
00_Ensuite 004	NO (-56.9%)	NO
00_Ensuite 005	NO (-84.8%)	NO
00_Ensuite 006	NO (-85.4%)	NO
00_Ensuite 007	NO (-88.9%)	NO
00_Ensuite 008	NO (-41.3%)	NO
00_Ensuite 009	NO (-92.5%)	NO
00_Ensuite 010	N/A	N/A
00_Ensuite 011	NO (-47.8%)	NO
00_Ensuite 012	NO (-88.5%)	NO
00_Ensuite 013	NO (-80.9%)	NO
00_Ensuite 014	NO (-96.6%)	NO
00_Ensuite 015	N/A	N/A
00_Ensuite 016	N/A	N/A
00_Ensuite 017	N/A	N/A
00_Ensuite 018	N/A	N/A
00_Ensuite 019	NO (-81.7%)	NO
00_Ensuite 020	N/A	N/A
00_Ensuite 021	NO (-80.7%)	NO
00_Ensuite 022	NO (-100%)	NO
00_Ensuite 023	NO (-57.5%)	NO
00_Ensuite 024	NO (-96.3%)	NO
00_Ensuite 025	NO (-88.5%)	NO
00_Ensuite 026	N/A	N/A
00_Ensuite 027	NO (-33.1%)	NO
00_Ensuite 028	N/A	N/A
00_Ensuite 029	N/A	N/A
00_Ensuite 030	NO (-40.5%)	NO
00_Ensuite 031	N/A	N/A
00_Ensuite 032	NO (-44.4%)	NO
00_Ensuite 033	NO (-63.2%)	NO
00_Ensuite 034	NO (-81.4%)	NO
00_Ensuite 035	NO (-78.7%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_Ensuite 036	NO (-87%)	NO
00_Ensuite 037	NO (-50.1%)	NO
00_Ensuite 038	NO (-90.2%)	NO
00_Ensuite 039	N/A	N/A
00_Ensuite 040	NO (-74.9%)	NO
00_Ensuite 041	N/A	N/A
00_Ensuite 042	N/A	N/A
00_Ensuite 043	NO (-92.1%)	NO
00_Ensuite 044	N/A	N/A
00_Ensuite 045	NO (-91.9%)	NO
00_Ensuite 046	N/A	N/A
00_Ensuite 047	N/A	N/A
00_Ensuite 048	NO (-41.6%)	NO
00_Ensuite 049	NO (-82.1%)	NO
00_Ensuite 050	NO (-74.1%)	NO
00_Ensuite 051	N/A	N/A
00_Ensuite 052	N/A	N/A
00_Ensuite 053	NO (-59.2%)	NO
00_Entrance Concourse/Waiting 001	NO (-99.9%)	NO
00_Entrance Concourse/Waiting 002	NO (-99.7%)	NO
00_Entrance Concourse/Waiting 003	NO (-99.6%)	NO
00_Entrance Concourse/Waiting 004	NO (-94.1%)	NO
00_Exam (Decontamination)	NO (-72.3%)	NO
00_Exam/Treat 001	N/A	N/A
00_Exam/Treat 002	N/A	N/A
00_Exam/Treat 003	N/A	N/A
00_Exam/Treat 004	N/A	N/A
00_Exam/Treat 005	N/A	N/A
00_Exam/Treat 006	N/A	N/A
00_Exam/Treat 007	N/A	N/A
00_Exam/Treat 008	N/A	N/A
00_Exam/Treat 009	N/A	N/A
00_Exam/Treat 010	N/A	N/A
00_Exam/Treat 011	N/A	N/A
00_Exam/Treat 012	N/A	N/A
00_Exam/Treat 013	N/A	N/A
00_Exam/Treat 014	N/A	N/A
00_Exam/Treat 015	NO (-85.4%)	NO
00_Exam/Treat 016	N/A	N/A
00_Exam/Treat 017	N/A	N/A
00_Exam/Treat 018	N/A	N/A
00_Exam/Treat 019	NO (-71%)	NO
00_Exam/Treat 020	N/A	N/A
00_Exam/Treat 021	N/A	N/A
00_Exam/Treat 022	NO (-89.8%)	NO
00_Exam/Treat 023	N/A	N/A
00_Exam/Treat 024	NO (-94.2%)	NO
00_Exam/Treat 025	N/A	N/A
00_Exam/Treat 026	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_Exam/Treat 027	N/A	N/A
00_Exam/Treat 028	NO (-89.2%)	NO
00_Exam/Treat 029	N/A	N/A
00_Exam/Treat 030	N/A	N/A
00_Exam/Treat 031	N/A	N/A
00_Exam/Treat 032	N/A	N/A
00_Exam/Treat 033	NO (-82.2%)	NO
00_Exam/Treat 034	NO (-89.4%)	NO
00_Exam/Treat 035	NO (-85%)	NO
00_Exam/Treat 036	NO (-89.1%)	NO
00_Exam/Treat 037	N/A	N/A
00_Exam/Treat 038	N/A	N/A
00_Exam/Treat 039	N/A	N/A
00_Exam/Treat 040	NO (-100%)	NO
00_Exam/Treat 041	N/A	N/A
00_Exam/Treat 042	N/A	N/A
00_Exam/Treat 043	NO (-24.9%)	NO
00_Exam/Treat 044	N/A	N/A
00_Exam/Treat 045	N/A	N/A
00_Exam/Treat 046	N/A	N/A
00_Exam/Treat 047	N/A	N/A
00_Exam/Treat 048	N/A	N/A
00_Exam/Treat 049	N/A	N/A
00_Exam/Treat 050	NO (-82.4%)	NO
00_Exam/Treat 051	N/A	N/A
00_Exam/Treat 052	NO (-58.7%)	NO
00_Exam/Treat: Mental Health 001	N/A	N/A
00_Exam/Treat: Mental Health 002	N/A	N/A
00_Exam/Treat: Spec Diags 001	N/A	N/A
00_Exam/Treat: Spec Diags 002	N/A	N/A
00_Exam/Treat: Spec Diags 003	NO (-90.6%)	NO
00_Exam/Treat: Spec Diags 004	N/A	N/A
00_Exam/Treat: Spec Diags 005	N/A	N/A
00_Exam/Treat: Specialist Diahs - Gynae	NO (-95.5%)	NO
00_Exam/Treat: US 001	N/A	N/A
00_Exam/Treat: US 002	N/A	N/A
00_Floor Coord.n Hub	N/A	N/A
00_HDU/Larger Bed 001	NO (-46.8%)	NO
00_HDU/Larger Bed 002	NO (-67.2%)	NO
00_HUB/Office	N/A	N/A
00_HUB/Reception	N/A	N/A
00_Interview 001	N/A	N/A
00_Interview 002	N/A	N/A
00_Interview 003	N/A	N/A
00_Interview 004	N/A	N/A
00_Interview 005	N/A	N/A
00_Interview 006	N/A	N/A
00_Interview 007	N/A	N/A
00_Interview 008	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_Interview 009	N/A	N/A
00_Interview 010	N/A	N/A
00_Interview 011	N/A	N/A
00_Interview 012	N/A	N/A
00_Interview 013	N/A	N/A
00_Interview 014	N/A	N/A
00_Interview 015	N/A	N/A
00_Interview 016	N/A	N/A
00_Interview 017	N/A	N/A
00_Interview 018	N/A	N/A
00_Iso Lobby 001	N/A	N/A
00_Iso Lobby 002	N/A	N/A
00_Iso Lobby 002	N/A	N/A
00_Iso Lobby 003	N/A	N/A
00_Iso Lobby 004	N/A	N/A
00_Iso Lobby 005	N/A	N/A
00_Iso Lobby 006	NO (-100%)	NO
00_IT HUB 001	N/A	N/A
00_IT HUB 002	N/A	N/A
00_IT HUB 003	N/A	N/A
00_IT HUB 004	N/A	N/A
00_IT HUB 005	N/A	N/A
00_Kitchen/Bev Bay	N/A	N/A
00_Lounge W Seating/6 001	NO (-86.8%)	NO
00_Lounge W Seating/6 002	NO (-86.8%)	NO
00_Lounge W Seating/6 003	NO (-88.9%)	NO
00_Lounge W Seating/6 004	NO (-89.8%)	NO
00_Lounge W Seating/10	NO (-86.5%)	NO
00_Lounge W Seating/6 005	NO (-95.5%)	NO
00_MDT Room 001	N/A	N/A
00_MDT Room 002	N/A	N/A
00_MDT Room 003	NO (-70.8%)	NO
00_MDT Room 004	N/A	N/A
00_MDT Room 005	N/A	N/A
00_Med. room	N/A	N/A
00_Milk Kitchen	N/A	N/A
00_Office 001	N/A	N/A
00_Office 002	N/A	N/A
00_Office 003	N/A	N/A
00_Office 004	N/A	N/A
00_Office 005	N/A	N/A
00_Office 006	N/A	N/A
00_Office 007	N/A	N/A
00_Office 008	N/A	N/A
00_Office 009	N/A	N/A
00_Office 010	N/A	N/A
00_Office 011	NO (-72.7%)	NO
00_Office 012	N/A	N/A
00_Office 013	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_Office (Patch Team)	NO (-76.5%)	NO
00_Office - managers	N/A	N/A
00_Office Complaints	NO (-71.5%)	NO
00_Office Pals	NO (-26.6%)	NO
00_Office: Open Plan	NO (-94.6%)	NO
00_PeAD RESUS 001	N/A	N/A
00_PeAD RESUS 002	N/A	N/A
00_Phleb bay	N/A	N/A
00_Photo Pass Room	N/A	N/A
00_Plaster	N/A	N/A
00_Play	NO (-33%)	NO
00_PoCT 001	N/A	N/A
00_PoCT 002	N/A	N/A
00_PoCT 003	N/A	N/A
00_PoCT 004	N/A	N/A
00_PoCT 005	N/A	N/A
00_PoCT 006	N/A	N/A
00_PoCT 007	N/A	N/A
00_PoCT 008	N/A	N/A
00_PoCT 009	N/A	N/A
00_Police/Security Room	N/A	N/A
00_PTS Office	NO (-92.7%)	NO
00_Radiology Report	N/A	N/A
00_Recep/Wait	N/A	N/A
00_Reception 001	NO (-99.7%)	NO
00_Reception 002	N/A	N/A
00_Reception 003	NO (-95.3%)	NO
00_Reception 004	N/A	N/A
00_Reception/Office	N/A	N/A
00_Reception/Wait	NO (-100%)	NO
00_Recliners	NO (-88.8%)	NO
00_Resus Bay 002	N/A	N/A
00_Security Change	N/A	N/A
00_Security Office	NO (-80.3%)	NO
00_Security Room: CCTV	NO (-70.8%)	NO
00_Seminar	NO (-95.6%)	NO
00_Seminar ED Floor	NO (-83.7%)	NO
00_Shared Treat	N/A	N/A
00_Single Bedroom 001	N/A	N/A
00_Single Bedroom 002	NO (-77.6%)	NO
00_Single Bedroom 003	N/A	N/A
00_Single Bedroom 004	N/A	N/A
00_Single Bedroom 005	N/A	N/A
00_Single Bedroom 006	N/A	N/A
00_Single Bedroom 007	NO (-88.2%)	NO
00_Single Bedroom 008	N/A	N/A
00_Single Bedroom 009	NO (-94.7%)	NO
00_Single Bedroom 010	NO (-87.2%)	NO
00_Single Bedroom 011	NO (-87.1%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_Single Bedroom 012	NO (-32.3%)	NO
00_Single Bedroom 013	NO (-71.9%)	NO
00_Single Bedroom 014	NO (-86.6%)	NO
00_Single Bedroom 015	NO (-38.2%)	NO
00_Single Bedroom 016	NO (-94.1%)	NO
00_Single Bedroom 017	N/A	N/A
00_Single Bedroom 018	NO (-82.4%)	NO
00_Single Bedroom 019	N/A	N/A
00_Single Bedroom 020	NO (-83.3%)	NO
00_Single Bedroom 021	NO (-36.4%)	NO
00_Single Bedroom 022	NO (-73.2%)	NO
00_Single Bedroom 023	NO (-98.6%)	NO
00_Single Bedroom 024	NO (-88%)	NO
00_Single Bedroom 025	N/A	N/A
00_Single Bedroom 026	NO (-87.5%)	NO
00_Single Bedroom 027	NO (-94.1%)	NO
00_Single Bedroom 028	NO (-94.8%)	NO
00_Single Bedroom 029	NO (-81.2%)	NO
00_Single Bedroom 030	NO (-87.5%)	NO
00_Single Bedroom 031	NO (-61.8%)	NO
00_Single Bedroom 032	NO (-91.2%)	NO
00_Single Bedroom 033	NO (-20%)	NO
00_Single Bedroom 034	NO (-87.9%)	NO
00_Single Bedroom 035	NO (-92.6%)	NO
00_Single Bedroom 036	N/A	N/A
00_Single Bedroom 037	NO (-95.9%)	NO
00_Single Bedroom 038	NO (-93.7%)	NO
00_Single Bedroom 039	NO (-61.9%)	NO
00_Single Bedroom 040	N/A	N/A
00_Single Bedroom 041	N/A	N/A
00_Single Bedroom 042	NO (-88.9%)	NO
00_Sister Office	NO (-80.8%)	NO
00_Staff Base 001	N/A	N/A
00_Staff Base 002	N/A	N/A
00_Staff Base 003	NO (-99.8%)	NO
00_Staff Base 004	N/A	N/A
00_Staff Base 005	N/A	N/A
00_Staff Base 006	N/A	N/A
00_Staff Base 007	N/A	N/A
00_Staff Base 008	N/A	N/A
00_Staff Base 009	N/A	N/A
00_Staff Base 010	N/A	N/A
00_Staff Base 011	N/A	N/A
00_Staff Base 012	NO (-99.2%)	NO
00_Staff Base 013	N/A	N/A
00_Staff Base - Gynae	N/A	N/A
00_Staff Base with Pneumt Tube 001	N/A	N/A
00_Staff Base with Pneumt Tube 002	NO (-97.7%)	NO
00_Staff Base with Pneumt Tube 003	NO (-95.6%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
00_Staff Rest 001	NO (-95.3%)	NO
00_Staff Rest002	N/A	N/A
00_Staff Rest/Bev 001	NO (-62.8%)	NO
00_Staff Rest/Bev 002	N/A	N/A
00_Streaming 001	N/A	N/A
00_Streaming 002	N/A	N/A
00_Streaming 003	N/A	N/A
00_Streaming 004	NO (-99.9%)	NO
00_Sub-Wait	N/A	N/A
00_Transport Wait (Inc Transport Liason)	NO (-98.1%)	NO
00_Treat/Plaster	N/A	N/A
00_Treat: Procedures 001	N/A	N/A
00_Treat: Procedures 002	N/A	N/A
00_Treatment 001	N/A	N/A
00_Treatment 002	NO (-73.2%)	NO
00_Treatment (2-sided) 001	N/A	N/A
00_Treatment (2-sided) 002	N/A	N/A
00_Treatment: Proc	N/A	N/A
00_Treatment: Procedures - Gynae	NO (-95.6%)	NO
00_Treatment: Specialist Diags 001	N/A	N/A
00_Treatment: Specialist Diags 002	N/A	N/A
00_Triage	N/A	N/A
00_Triage/Streaming 001	N/A	N/A
00_Triage/Streaming 002	N/A	N/A
00_Triage/Streaming 003	N/A	N/A
00_Triage/Streaming 004	N/A	N/A
00_Ultrasound	N/A	N/A
00_Unit Office	N/A	N/A
00_Unit Pantry 001	N/A	N/A
00_Unit Pantry 002	N/A	N/A
00_Unit Pantry 003	N/A	N/A
00_Wait 001	N/A	N/A
00_Wait 002	NO (-96.5%)	NO
00_Wait 003	NO (-86.8%)	NO
00_Wait 004	NO (-91.2%)	NO
00_Wait 005	N/A	N/A
00_Waiting: 15 places 001	NO (-65.6%)	NO
00_Waiting; 15 places002	N/A	N/A
00_Waiting: 4 places	NO (-99.9%)	NO
00_Waiting: 5 places	NO (-99.9%)	NO
00_Waiting: Bed Bay 001	NO (-94%)	NO
00_Waiting: Bed Bay 002	N/A	N/A
00_Waiting: Bed Bay 003	NO (-99.8%)	NO
00_Waiting: Bed Bay 004	NO (-92%)	NO
00_Waiting: Bed Bay 005	NO (-99.7%)	NO
00_Waiting: Bed Bay 006	NO (-92.6%)	NO
00_X-Ray 001	NO (-78.1%)	NO
00_X-Ray 002	N/A	N/A
00_X-Ray 003	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
01_Admin Office	NO (-69.4%)	NO
01_Admin Space	NO (-87.1%)	NO
01_Anaesthetic Room	NO (-42.3%)	NO
01_Audiology Manager	N/A	N/A
01_Breast Treat	N/A	N/A
01_C.U. 004	NO (-77.2%)	NO
01_C.U. 005	NO (-62%)	NO
01_C.U. 010	N/A	N/A
01_C.U. scope Decont	N/A	N/A
01_C.U./Med Store/Prep	N/A	N/A
01_C/E 001	NO (-84.3%)	NO
01_C/E 002	NO (-87.3%)	NO
01_C/E 003	NO (-88.6%)	NO
01_C/E 004	N/A	N/A
01_C/E 005	NO (-85%)	NO
01_C/E 006	N/A	N/A
01_C/E 007	NO (-85.1%)	NO
01_C/E 008	NO (-38.6%)	NO
01_C/E 009	NO (-88.1%)	NO
01_C/E 010	N/A	N/A
01_C/E 011	N/A	N/A
01_C/E 012	NO (-88%)	NO
01_C/E 013	NO (-84.9%)	NO
01_C/E 014	NO (-69.5%)	NO
01_C/E 015	NO (-88.3%)	NO
01_C/E 016	NO (-69%)	NO
01_C/E 017	N/A	N/A
01_C/E 018	NO (-86.4%)	NO
01_C/E 019	NO (-86.8%)	NO
01_C/E 020	NO (-86.5%)	NO
01_C/E 021	NO (-87.9%)	NO
01_C/E 022	NO (-82.7%)	NO
01_C/E 023	NO (-86.1%)	NO
01_C/E 024	NO (-95.2%)	NO
01_C/E - Optometrist 001	N/A	N/A
01_C/E - Optometrist 002	N/A	N/A
01_C/E Large/MDT 001	N/A	N/A
01_C/E Large/MDT 002	N/A	N/A
01_C/E Large/MDT 003	N/A	N/A
01_Cannualtion room 001	N/A	N/A
01_Cannualtion room 002	N/A	N/A
01_Cannualtion room 003	N/A	N/A
01_Cannualtion room 004	N/A	N/A
01_Cardiac/ECG 001	NO (-88.9%)	NO
01_Cardiac/ECG 002	N/A	N/A
01_Cardiac/Echo 001	NO (-69.5%)	NO
01_Cardiac/Echo 002	NO (-69.1%)	NO
01_Cardiac/Echo 003	NO (-68.1%)	NO
01_Cardiac/Echo 004	NO (-69.5%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
01_Child Wait	NO (-98.9%)	NO
01_Clean St.	N/A	N/A
01_Clinical Room	N/A	N/A
01_Coffee Shop	NO (-99.8%)	NO
01_Coffee Shop Seating 001	N/A	N/A
01_Coffee Shop Seating 002	NO (-99.5%)	NO
01_Colposcopy	NO (-86.6%)	NO
01_Complementary Therapy/Group Meeting	NO (-89%)	NO
01_Consult Booth	N/A	N/A
01_Contrast Prep Room	N/A	N/A
01_Control 001	NO (-17.5%)	NO
01_Control 002	NO (-69.6%)	NO
01_Control 003	N/A	N/A
01_Control 004	NO (-75%)	NO
01_Corridor 023	N/A	N/A
01_Corridor 030	NO (-32.7%)	NO
01_CT Control 001	NO (-68.5%)	NO
01_CT Control 002	N/A	N/A
01_CT Scanner 001	NO (-71.6%)	NO
01_CT Scanner 002	N/A	N/A
01_CT Scanner 003	NO (-76.5%)	NO
01_CT Scanner 004	N/A	N/A
01_Cubicle 001	N/A	N/A
01_Cubicle 002	N/A	N/A
01_Cubicle 003	N/A	N/A
01_Cubicle 004	N/A	N/A
01_Cubicle 005	N/A	N/A
01_Cubicle 006	N/A	N/A
01_Day treat (recliner) 001	NO (-93.9%)	NO
01_Day treat (recliner) 002	NO (-90.3%)	NO
01_Day treat (recliner) 003	NO (-94.4%)	NO
01_Day treat (recliner) 004	NO (-90.2%)	NO
01_Day treat (recliner) 005	NO (-93.5%)	NO
01_Day treat (recliner) 006	NO (-94.7%)	NO
01_Day treat (recliner) 007	NO (-93.5%)	NO
01_Day treat (recliner) 008	N/A	N/A
01_Day treat (recliner) 009	NO (-60.3%)	NO
01_Day treat (recliner) 010	NO (-88.3%)	NO
01_Day treat (recliner) 011	NO (-94.7%)	NO
01_Day treat (recliner) 012	NO (-94.5%)	NO
01_Day treat (recliner) 013	NO (-95.5%)	NO
01_Day treat (recliner) 014	NO (-88.7%)	NO
01_Day treat (recliner) 015	N/A	N/A
01_Day treat (recliner) 016	N/A	N/A
01_Day treat (recliner) 017	NO (-83.4%)	NO
01_Day treat (recliner) 018	NO (-78.3%)	NO
01_Day treat (recliner) 019	NO (-83.8%)	NO
01_Day treat (recliner) 020	N/A	N/A
01_Day treat (recliner) 021	NO (-90.9%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
01_Day treat (recliner) 022	N/A	N/A
01_Day treat (recliner) 023	NO (-63.2%)	NO
01_Day treat (recliner) 024	NO (-67%)	NO
01_Day treat (recliner) 025	N/A	N/A
01_Dental Surgery 001	NO (-86.7%)	NO
01_Dental Surgery 002	NO (-60.9%)	NO
01_Dental Surgery 003	NO (-59.7%)	NO
01_Donation/Contact Point	N/A	N/A
01_Endoscopy Suites 001	N/A	N/A
01_Endoscopy Suites 002	N/A	N/A
01_Endoscopy Suites 003	N/A	N/A
01_Ensuite 001	N/A	N/A
01_Ensuite 002	NO (-86.6%)	NO
01_Ensuite 003	N/A	N/A
01_Ensuite 004	N/A	N/A
01_Ensuite 005	N/A	N/A
01_Ensuite 006	N/A	N/A
01_Ensuite 007	N/A	N/A
01_Ensuite 008	N/A	N/A
01_Ensuite 009	N/A	N/A
01_Ensuite 010	N/A	N/A
01_Exam room 001	NO (-91.9%)	NO
01_Exam room 002	NO (-91.4%)	NO
01_Exam room 003	NO (-62.6%)	NO
01_Exam room 004	NO (-92.2%)	NO
01_Exam room 005	NO (-62.6%)	NO
01_Fitting Room 001	N/A	N/A
01_Fitting Room 002	N/A	N/A
01_Fitting Room 003	N/A	N/A
01_Fitting Room 004	N/A	N/A
01_General Office	NO (-74.6%)	NO
01_Group Room	NO (-94.9%)	NO
01_Hearing Test Room/Booth	NO (-75.5%)	NO
01_Hearing Therapist	NO (-73.9%)	NO
01_Hot Desk	N/A	N/A
01_Hot Desks	N/A	N/A
01_Hysteroscopy	NO (-84.7%)	NO
01_ICC (Incident Coordination Centre)	NO (-61.3%)	NO
01_Imaging: Fluoro	NO (-90.9%)	NO
01_Imaging: Gamma	N/A	N/A
01_Imaging: IR	YES (+82.5%)	NO
01_Imaging: X-Ray inpatient	N/A	N/A
01_Inj Room	N/A	N/A
01_Inpatient hold 001	NO (-81.4%)	NO
01_Inpatient hold 002	NO (-91.4%)	NO
01_Inpatient hold 003	NO (-51.7%)	NO
01_Inpatient hold for 3	NO (-98.3%)	NO
01_Interview 001	N/A	N/A
01_Interview 002	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
01_Interview 003	N/A	N/A
01_Interview 004	N/A	N/A
01_Interview 005	N/A	N/A
01_Interview 006	N/A	N/A
01_Interview 007	N/A	N/A
01_Interview 008	N/A	N/A
01_Interview 009	NO (-83.5%)	NO
01_Interview 010	N/A	N/A
01_Interview 011	N/A	N/A
01_Interview 012	NO (-93.4%)	NO
01_Interview & Virtual Cnslt	N/A	N/A
01_IT HUB 001	N/A	N/A
01_IT HUB 002	N/A	N/A
01_IT HUB 003	N/A	N/A
01_IT HUB 004	N/A	N/A
01_IT HUB 005	N/A	N/A
01_IT HUB 006	N/A	N/A
01_IT HUB 007	NO (-95.3%)	NO
01_Laboratory	N/A	N/A
01_Laser	N/A	N/A
01_Linen 003	NO (-46.8%)	NO
01_Management Office: Fluoro/IT (4)	NO (-66.9%)	NO
01_Management Office: US (4)	N/A	N/A
01_Measure Bay 001	N/A	N/A
01_Measure Bay 002	N/A	N/A
01_Medical Examiner Office	N/A	N/A
01_Meds Store/Prep	NO (-72.6%)	NO
01_Meeting Room	NO (-43.8%)	NO
01_Mohs lab	NO (-88.8%)	NO
01_MRI 001	NO (-69.7%)	NO
01_MRI 002	NO (-74.8%)	NO
01_MRI 003	NO (-72.9%)	NO
01_Multi Faith Room	NO (-73.7%)	NO
01_Muslin Prayer Room	NO (-70.4%)	NO
01_Office 001	N/A	N/A
01_Office 002	NO (-54.5%)	NO
01_Office 003	N/A	N/A
01_Office 004	N/A	N/A
01_Office 005	NO (-75.7%)	NO
01_Office 006	NO (-90.3%)	NO
01_Office 007	N/A	N/A
01_Office 008	N/A	N/A
01_Office 009	N/A	N/A
01_Office 010	NO (-93%)	NO
01_Office 011	NO (-72.9%)	NO
01_Office 012	NO (-26.1%)	NO
01_Office 013	NO (-76.4%)	NO
01_Office 014	NO (-41.3%)	NO
01_Office 015	NO (-85.9%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
01_Office Managers	N/A	N/A
01_Office Vetting	N/A	N/A
01_Office/Resource Base	N/A	N/A
01_Office: Analysis	NO (-90.2%)	NO
01_Office: Manager	N/A	N/A
01_Office: Open Plan 001	N/A	N/A
01_Office: Open Plan 002	N/A	N/A
01_Ops Centre 001	N/A	N/A
01_Ops Centre 002	N/A	N/A
01_Ophthalmic 001	NO (-85.4%)	NO
01_Ophthalmic 002	N/A	N/A
01_Ophthalmic 003	NO (-78.7%)	NO
01_Ophthalmic 004	N/A	N/A
01_Opthamology: Lanes 001	N/A	N/A
01_Opthamology: Lanes 002	N/A	N/A
01_Oral Surgery	NO (-87.6%)	NO
01_Outpatient Pharmacy	N/A	N/A
01_Overseas Office	NO (-82.6%)	NO
01_PAC's Team	N/A	N/A
01_Pass	N/A	N/A
01_PFT Test 001	N/A	N/A
01_PFT Test 002	N/A	N/A
01_Phototherapy 001	NO (-90.9%)	NO
01_Phototherapy 002	NO (-90.8%)	NO
01_Plaster	NO (-89.9%)	NO
01_Plebotomy 001	N/A	N/A
01_Plebotomy 002	N/A	N/A
01_Plebotomy 003	N/A	N/A
01_Plebotomy 004	N/A	N/A
01_Pre-assessment	NO (-76.7%)	NO
01_Pre-op assessment	N/A	N/A
01_Prep/Recovery Stage 1 001	NO (-69%)	NO
01_Prep/Recovery Stage 1 002	NO (-69.2%)	NO
01_Prep/Recovery Stage 1 003	NO (-70.7%)	NO
01_Prep/Recovery Stage 1 004	NO (-70.4%)	NO
01_Prep/Recovery Stage 1 005	NO (-38.6%)	NO
01_Prep/Recovery Stage 1 006	N/A	N/A
01_Prep/Recovery Stage 1 007	NO (-72.8%)	NO
01_Prep/Recovery Stage 1 008	NO (-69.3%)	NO
01_Prep/Recovery Stage 1 009	NO (-68.2%)	NO
01_Prep/Recovery Stage 1 010	NO (-70.7%)	NO
01_Radioactive open/closed sources	N/A	N/A
01_Radiology Office (6 MR/CT)	NO (-69.6%)	NO
01_Radiology View/Report	N/A	N/A
01_Recap	N/A	N/A
01_Reception	N/A	N/A
01_Reception office	N/A	N/A
01_Reception/Wait 001	NO (-94.5%)	NO
01_Reception/Wait 002	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
01_Reception/Wait 003	NO (-96.7%)	NO
01_Reception/Wait 004	NO (-98.6%)	NO
01_Reception/Wait 005	NO (-90.9%)	NO
01_Reception/Wait 006	N/A	N/A
01_Reception/Wait 007	N/A	N/A
01_Reception/Wait 008	NO (-68.1%)	NO
01_Reception/Wait 009	NO (-94.5%)	NO
01_Recovery 001	NO (-51.8%)	NO
01_Recovery 002	YES (+15.5%)	NO
01_Recovery 003	NO (-34.6%)	NO
01_Recovery 004	YES (+13.1%)	NO
01_Recovery 005	NO (-65.9%)	NO
01_Recovery 006	N/A	N/A
01_Recovery 007	NO (-80.2%)	NO
01_Recovery 008	NO (-18.2%)	NO
01_Recovery Stage 2	N/A	N/A
01_Repair Workshop	N/A	N/A
01_Reporting 001	N/A	N/A
01_Reporting 002	N/A	N/A
01_Reporting room: FLUORO	NO (-78.9%)	NO
01_Reporting room: Nuclear Medicine	N/A	N/A
01_Reporting room: Recovery	NO (-90.8%)	NO
01_Reporting Room: Ultrasound	N/A	N/A
01_Reporting Room: X-Ray	N/A	N/A
01_Reporting: Acute Team	N/A	N/A
01_RNIB	NO (-80.9%)	NO
01_Seminar	NO (-95.3%)	NO
01_Seminar/MDT 001	NO (-95.3%)	NO
01_Seminar/MDT 002	NO (-82.9%)	NO
01_Shop 001	N/A	N/A
01_Shop 002	N/A	N/A
01_Staff Base 001	N/A	N/A
01_Staff Base 002	N/A	N/A
01_Staff Base 003	NO (-98.7%)	NO
01_Staff Base 004	N/A	N/A
01_Staff Base 005	N/A	N/A
01_Staff Base 006	N/A	N/A
01_Staff Base 007	NO (-56%)	NO
01_Staff Base 008	NO (-98.7%)	NO
01_Staff Base 009	NO (-98.6%)	NO
01_Staff Base 010	NO (-99.2%)	NO
01_Staff Rest/Bev 001	N/A	N/A
01_Staff Rest/Bev 002	NO (-92.6%)	NO
01_Staff Rest/Bev 003	NO (-93.9%)	NO
01_Staff Rest/Bev 004	NO (-74.6%)	NO
01_Staff Rest/Bev (Combined)	NO (-84.7%)	NO
01_Sub-Wait	N/A	N/A
01_Therapies: Cardiac	NO (-95.6%)	NO
01_Therapy Female	NO (-79.6%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
01_Therapy/Gym	NO (-87.8%)	NO
01_Therapy/Treat 001	NO (-77.6%)	NO
01_Therapy/Treat 002	N/A	N/A
01_Therapy/Treat 003	NO (-75.4%)	NO
01_Therapy/Treat 004	NO (-74.8%)	NO
01_Therapy/Treat 005	NO (-81.1%)	NO
01_Therapy/Treat 006	NO (-73.8%)	NO
01_Treat: Procedures	NO (-91.2%)	NO
01_Treatment 001	N/A	N/A
01_Treatment 002	N/A	N/A
01_Treatment 003	N/A	N/A
01_Treatment 004	N/A	N/A
01_Treatment 005	N/A	N/A
01_Treatment 006	N/A	N/A
01_Treatment (2-sided) 001	N/A	N/A
01_Treatment (2-sided) 002	N/A	N/A
01_Treatment (2-sided) 003	NO (-80.7%)	NO
01_Treatment (2-sided) 004	NO (-87.7%)	NO
01_Ultrasound 001	N/A	N/A
01_Ultrasound 002	N/A	N/A
01_Ultrasound 003	N/A	N/A
01_Ultrasound 004	N/A	N/A
01_Unit Pantry 001	N/A	N/A
01_Unit Pantry 002	NO (-58%)	NO
01_US/Mammography 001	N/A	N/A
01_US/Mammography 002	NO (-84.8%)	NO
01_Viewing/Teaching area	N/A	N/A
01_Virtual Booth 001	N/A	N/A
01_Virtual Booth 002	N/A	N/A
01_Wait 001	N/A	N/A
01_Wait 002	N/A	N/A
01_Wait 003	N/A	N/A
01_Wait 004	N/A	N/A
01_Wait 005	N/A	N/A
01_Wait 006	N/A	N/A
01_Waiting Zone IR: 5 places	YES (+1.9%)	NO
01_Waiting: 10 places 001	N/A	N/A
01_Waiting: 10 places 002	N/A	N/A
01_Waiting: 10 places 003	NO (-85.8%)	NO
01_Waiting: 12 places	NO (-91%)	NO
01_Waiting: 15 places	NO (-74.8%)	NO
01_Waiting: 20 places	NO (-96.5%)	NO
01_X-Ray 001	NO (-100%)	NO
01_X-Ray 002	N/A	N/A
01_X-Ray: Inpatient	N/A	N/A
02_4-Bed Bay 001	NO (-85.3%)	NO
02_4-Bed Bay 002	NO (-85.2%)	NO
02_Anaesthetic Room 001	N/A	N/A
02_Anaesthetic Room 002	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
02_Anaesthetic Room 003	N/A	N/A
02_Anaesthetic Room 004	N/A	N/A
02_Anaesthetic Room 005	N/A	N/A
02_Anaesthetic Room 006	N/A	N/A
02_Anaesthetic Room 007	N/A	N/A
02_Bariatric Bedroom	NO (-95.3%)	NO
02_Blood Issue	N/A	N/A
02_Blood Transfusion	NO (-84.4%)	NO
02_Breakout Space 001	N/A	N/A
02_Breakout Space 002	N/A	N/A
02_Breakout Space 003	NO (-99.9%)	NO
02_Breakout Space 004	NO (-99.9%)	NO
02_Clean/Drug prep 001	N/A	N/A
02_Clean/Drug prep 002	N/A	N/A
02_Cold room	N/A	N/A
02_Control Point	N/A	N/A
02_Decont Unit	N/A	N/A
02_En-Suite Bariatric	N/A	N/A
02_Ensuite 001	N/A	N/A
02_Ensuite 002	NO (-86.8%)	NO
02_Ensuite 003	NO (-39.3%)	NO
02_Ensuite 004	NO (-73.8%)	NO
02_Ensuite 005	N/A	N/A
02_Ensuite 006	NO (-81.9%)	NO
02_Ensuite 007	NO (-86.1%)	NO
02_Ensuite 008	NO (-88.7%)	NO
02_Ensuite 009	NO (-96.5%)	NO
02_Ensuite 010	NO (-43.8%)	NO
02_Ensuite 011	N/A	N/A
02_Ensuite 012	N/A	N/A
02_Ensuite 013	NO (-82.6%)	NO
02_Ensuite 014	N/A	N/A
02_Ensuite 015	NO (-90.3%)	NO
02_Ensuite 016	NO (-91.9%)	NO
02_Ensuite 017	NO (-43.6%)	NO
02_Ensuite 018	NO (-86.9%)	NO
02_Ensuite 019	NO (-90.3%)	NO
02_Ensuite 020	N/A	N/A
02_Ensuite 021	N/A	N/A
02_Ensuite 022	N/A	N/A
02_Ensuite 023	N/A	N/A
02_Ensuite 024	NO (-96%)	NO
02_Ensuite oncall room	NO (-86.8%)	NO
02_Exam/Physical Therapy	NO (-82.5%)	NO
02_Family Room 001	NO (-93.2%)	NO
02_Family Room 002	NO (-93.4%)	NO
02_Hot Automated Laboratory	NO (-89%)	NO
02_Inpatient hold 001	N/A	N/A
02_Inpatient hold 002	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
02_Inpatient hold 003	N/A	N/A
02_Inpatient hold 004	N/A	N/A
02_Inpatient hold 005	N/A	N/A
02_Interview 001	NO (-96.9%)	NO
02_Interview 002	N/A	N/A
02_Interview 003	N/A	N/A
02_Interview 004	N/A	N/A
02_Iso Lobby 001	N/A	N/A
02_Iso Lobby 002	N/A	N/A
02_Iso Lobby 003	N/A	N/A
02_Iso Lobby 004	N/A	N/A
02_Iso Lobby 005	N/A	N/A
02_Iso Lobby 006	N/A	N/A
02_Iso Lobby 007	N/A	N/A
02_Iso Lobby 008	N/A	N/A
02_Iso Single Bedroom 001	NO (-93.8%)	NO
02_Iso Single Bedroom 002	NO (-95.6%)	NO
02_Iso Single Bedroom 003	NO (-95%)	NO
02_Iso Single Bedroom 004	NO (-94.2%)	NO
02_Iso Single Bedroom 005	NO (-95.6%)	NO
02_Iso Single Bedroom 006	NO (-94.5%)	NO
02_Iso Single Bedroom 007	NO (-94.4%)	NO
02_Isolation Recovery Room (Stage 1) 001	N/A	N/A
02_Isolation Recovery Room (Stage 1) 002	NO (-86.3%)	NO
02_IT HUB 001	N/A	N/A
02_IT HUB 002	N/A	N/A
02_IT HUB 003	N/A	N/A
02_IT HUB 004	N/A	N/A
02_IT HUB 005	N/A	N/A
02_IT HUB 006	N/A	N/A
02_IV Fluid Store	N/A	N/A
02_Linen 002	NO (-85.3%)	NO
02_MDT Room 001	N/A	N/A
02_MDT Room 002	N/A	N/A
02_MDT Room 003	N/A	N/A
02_MDT Room 004	NO (-83.6%)	NO
02_Office 001	NO (-60.3%)	NO
02_Office 002	N/A	N/A
02_Office 003	N/A	N/A
02_Office 004	N/A	N/A
02_Office 005	N/A	N/A
02_Office - 3 person	NO (-88.3%)	NO
02_Office: 1 person + Microscope 003	NO (-96.9%)	NO
02_Office Morphology	NO (-93.6%)	NO
02_Office/Reception	N/A	N/A
02_Office: 1 person + Meeting Space + Microscope	NO (-81.9%)	NO
02_Office: 1 person + Microscope 001	NO (-56.3%)	NO
02_Office: 1 person + Microscope 002	NO (-66.7%)	NO
02_Office: 2 staff	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
02_Office: 3 staff 001	N/A	N/A
02_Office: 3 staff 002	N/A	N/A
02_Office: 4 person	NO (-81.5%)	NO
02_Office: 6 person	NO (-79.2%)	NO
02_Office: Clinical Lead	N/A	N/A
02_Office: Manager	N/A	N/A
02_Office: Open Plan (Junior)	NO (-68.6%)	NO
02_Open Plan Office & Consultants	N/A	N/A
02_Operating Room 001	NO (-89.3%)	NO
02_Operating Room 002	NO (-80.3%)	NO
02_Operating Room 003	NO (-90.1%)	NO
02_Operating Room 004	NO (-84.5%)	NO
02_Operating Room Large 001	N/A	N/A
02_Operating Room Large 002	NO (-86.2%)	NO
02_Operating Room Large 003	NO (-87.1%)	NO
02_Photocopier Room	N/A	N/A
02_PoCT 001	N/A	N/A
02_PoCT 002	N/A	N/A
02_PoCT 003	N/A	N/A
02_PoCT 004	N/A	N/A
02_Prep Room 001	N/A	N/A
02_Prep Room 002	N/A	N/A
02_Prep Room 003	N/A	N/A
02_Prep Room 004	N/A	N/A
02_Prep Room 005	N/A	N/A
02_Prep Room 006	NO (-89.3%)	NO
02_Prep Room 007	N/A	N/A
02_Prep/Recovery (Stage 2) 001	NO (-89.9%)	NO
02_Prep/Recovery (Stage 2) 002	NO (-89.4%)	NO
02_Prep/Recovery (Stage 2) 003	NO (-84.9%)	NO
02_Prep/Recovery (Stage 2) 004	NO (-84.1%)	NO
02_Prep/Recovery (Stage 2) 005	NO (-93.9%)	NO
02_Prep/Recovery (Stage 2) 006	NO (-88.9%)	NO
02_Prep/Recovery (Stage 2) 007	N/A	N/A
02_Prep/Recovery (Stage 2) 008	NO (-82.5%)	NO
02_Prep/Recovery (Stage 2) 009	NO (-73.2%)	NO
02_Prep/Recovery (Stage 2) 010	NO (-84.3%)	NO
02_Prep/Recovery (Stage 2) 011	NO (-89.5%)	NO
02_Prep/Recovery (Stage 2) 012	NO (-91.7%)	NO
02_Prep/Recovery (Stage 2) 013	NO (-92.8%)	NO
02_Prep/Recovery (Stage 2) 014	NO (-89.8%)	NO
02_Prep/Recovery (Stage 2) 015	NO (-89.4%)	NO
02_Prep/Recovery (Stage 2) 016	N/A	N/A
02_Prep/Recovery (Stage 2) 017	N/A	N/A
02_Prep/Recovery (Stage 2) 018	N/A	N/A
02_Prep/Recovery (Stage 2) 019	N/A	N/A
02_Prep/Recovery (Stage 2) 020	N/A	N/A
02_Prep/Recovery (Stage 2) 021	NO (-89.5%)	NO
02_Prep/Recovery (Stage 2) 022	NO (-89.8%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
02_Prep/Recovery (Stage 2) 023	NO (-95.6%)	NO
02_Prep/Recovery (Stage 2) 024	NO (-89.6%)	NO
02_Prep/Recovery (Stage 2) 025	N/A	N/A
02_Prep/Recovery (Stage 2) 026	NO (-81.7%)	NO
02_Quiet Workspace 001	N/A	N/A
02_Quiet Workspace 002	N/A	N/A
02_Reception 001	NO (-99.5%)	NO
02_Reception 002	NO (-95.6%)	NO
02_Recovery (Stage 1) 001	NO (-86.7%)	NO
02_Recovery (Stage 1) 002	NO (-86.6%)	NO
02_Recovery (Stage 1) 003	NO (-87.1%)	NO
02_Recovery (Stage 1) 004	NO (-86.6%)	NO
02_Recovery (Stage 1) 005	NO (-86.7%)	NO
02_Recovery (Stage 1) 006	NO (-86.3%)	NO
02_Recovery (Stage 1) 007	NO (-74.2%)	NO
02_Recovery (Stage 1) 008	NO (-64.2%)	NO
02_Recovery (Stage 1) 009	NO (-97.6%)	NO
02_Recovery (Stage 1) 010	NO (-98.8%)	NO
02_Recovery (Stage 1) 011	NO (-98.6%)	NO
02_Recovery (Stage 1) 012	N/A	N/A
02_Scrub 001	NO (-97.7%)	NO
02_Scrub 002	N/A	N/A
02_Scrub 003	NO (-97.3%)	NO
02_Scrub 004	N/A	N/A
02_Scrub 005	NO (-98.9%)	NO
02_Scrub 006	NO (-96.3%)	NO
02_Scrub 007	NO (-97.2%)	NO
02_Seminar 001	N/A	N/A
02_Seminar 002	NO (-70.9%)	NO
02_Seminar 003	N/A	N/A
02_Shared Admin (Combined)	NO (-86.5%)	NO
02_Single Bedroom 001	N/A	N/A
02_Single Bedroom 002	NO (-79.1%)	NO
02_Single Bedroom 003	NO (-82.7%)	NO
02_Single Bedroom 004	N/A	N/A
02_Single Bedroom 005	NO (-82.8%)	NO
02_Single Bedroom 006	NO (-85.1%)	NO
02_Single Bedroom 007	NO (-83%)	NO
02_Single Bedroom 008	N/A	N/A
02_Single Bedroom 009	NO (-83.4%)	NO
02_Single Bedroom 010	NO (-95%)	NO
02_Single Bedroom 011	NO (-77.1%)	NO
02_Single Bedroom 012	NO (-68.1%)	NO
02_Single Bedroom 013	NO (-76.3%)	NO
02_Single Bedroom 014	NO (-85.1%)	NO
02_Single Bedroom 015	NO (-84.5%)	NO
02_Single Bedroom 016	NO (-73.4%)	NO
02_Single Bedroom 017	NO (-90.9%)	NO
02_Single Bedroom 018	NO (-90.7%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
02_Single Bedroom 019	NO (-30.9%)	NO
02_Single Bedroom 020	NO (-90.3%)	NO
02_Single Bedroom 021	NO (-73.8%)	NO
02_Single Bedroom 022	N/A	N/A
02_Single Bedroom 023	NO (-92.8%)	NO
02_Single Bedroom 024	NO (-81.9%)	NO
02_Single Bedroom 025	NO (-73.1%)	NO
02_Single Bedroom 026	NO (-95.6%)	NO
02_Single Bedroom 027	NO (-80.6%)	NO
02_Single Bedroom 028	NO (-58.4%)	NO
02_Single Bedroom 029	NO (-83.5%)	NO
02_Single Bedroom 030	N/A	N/A
02_Single Bedroom 031	NO (-42.5%)	NO
02_Single Bedroom 032	NO (-87.7%)	NO
02_Staff Base 001	NO (-96.8%)	NO
02_Staff Base 002	NO (-97.3%)	NO
02_Staff Base 003	NO (-96.6%)	NO
02_Staff Base 004	NO (-97.2%)	NO
02_Staff Base 005	N/A	N/A
02_Staff Base 006	NO (-98%)	NO
02_Staff Base 007	NO (-97%)	NO
02_Staff Base 008	NO (-98.2%)	NO
02_Staff Base 009	NO (-97.4%)	NO
02_Staff Base 010	NO (-97.1%)	NO
02_Staff Base 011	NO (-98.8%)	NO
02_Staff Base 012	NO (-98.7%)	NO
02_Staff Base 013	N/A	N/A
02_Staff Rest (Combined)	NO (-96.2%)	NO
02_Staff Rest Room (Night)	N/A	N/A
02_Staff Rest/Bev 001	NO (-61.1%)	NO
02_Staff Rest/Bev 002	NO (-75.3%)	NO
02_Staff Rest/Bev 003	N/A	N/A
02_Staff Rest/Bev 004	NO (-82.1%)	NO
02_Stage 2 Lounge	N/A	N/A
02_Sterile St Clean	N/A	N/A
02_Sterile St Supplies	NO (-93.5%)	NO
02_Treatment (2-sided)	N/A	N/A
02_Unit Pantry 001	N/A	N/A
02_Unit Pantry 002	N/A	N/A
02_Unit Pantry 003	N/A	N/A
02_Unit Pantry 004	NO (-84.9%)	NO
02_Unit Pantry 005	N/A	N/A
02_UPS 001	N/A	N/A
02_UPS 002	N/A	N/A
02_UPS 003	N/A	N/A
02_UPS 004	N/A	N/A
02_UPS 005	N/A	N/A
02_UPS 006	N/A	N/A
02_UPS 007	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
02_Wait 001	N/A	N/A
02_Wait 002	N/A	N/A
02_Waiting: 20 Places	NO (-95.7%)	NO
03_2 Bed Bay 001	NO (-94.5%)	NO
03_2 Bed Bay 002	NO (-91.2%)	NO
03_2 Bed Bay 003	NO (-91.1%)	NO
03_4 Bed Bay 001	N/A	N/A
03_4 Bed Bay 002	NO (-86.8%)	NO
03_4 Bed Bay 003	NO (-86.6%)	NO
03_4 Bed Bay 004	NO (-86.6%)	NO
03_4 Bed Bay 005	NO (-86.6%)	NO
03_Bariatric Bedroom 001	NO (-94.5%)	NO
03_Bariatric Bedroom 002	NO (-75%)	NO
03_C.U. 001	N/A	N/A
03_C.U. 004	N/A	N/A
03_C.U./CSSD St.	N/A	N/A
03_Child Play 001	N/A	N/A
03_Child Play 002	N/A	N/A
03_Child Play 003	N/A	N/A
03_Clinical Psychology Office	N/A	N/A
03_Consult/Exam 001	NO (-85.3%)	NO
03_Consult/Exam 002	N/A	N/A
03_Consult/Exam 003	NO (-71.3%)	NO
03_Consult/Exam 004	N/A	N/A
03_Consult/Exam 005	N/A	N/A
03_Consult/Exam 006	NO (-71.1%)	NO
03_Consult/Exam (Larger)	N/A	N/A
03_Educational Area 001	NO (-91.8%)	NO
03_Educational Area 002	NO (-87.8%)	NO
03_En-Suite Bariatric 001	N/A	N/A
03_En-Suite Bariatric 002	N/A	N/A
03_Ensuite 001	NO (-20.5%)	NO
03_Ensuite 002	N/A	N/A
03_Ensuite 003	N/A	N/A
03_Ensuite 004	N/A	N/A
03_Ensuite 005	N/A	N/A
03_Ensuite 006	NO (-26.8%)	NO
03_Ensuite 007	NO (-86.1%)	NO
03_Ensuite 008	NO (-85.5%)	NO
03_Ensuite 009	NO (-90.8%)	NO
03_Ensuite 010	NO (-76.2%)	NO
03_Ensuite 011	NO (-95.4%)	NO
03_Ensuite 012	NO (-59.8%)	NO
03_Ensuite 013	N/A	N/A
03_Ensuite 014	N/A	N/A
03_Ensuite 015	N/A	N/A
03_Ensuite 016	N/A	N/A
03_Ensuite 017	N/A	N/A
03_Ensuite 018	NO (-29.4%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
03_Ensuite 019	NO (-76.8%)	NO
03_Ensuite 020	NO (-84.6%)	NO
03_Ensuite 021	N/A	N/A
03_Ensuite 022	NO (-79.6%)	NO
03_Ensuite 023	NO (-14.1%)	NO
03_Ensuite 024	N/A	N/A
03_Ensuite 025	NO (-18.4%)	NO
03_Ensuite 026	NO (-15.2%)	NO
03_Ensuite 027	N/A	N/A
03_Ensuite 028	NO (-76.5%)	NO
03_Ensuite 029	NO (-62.9%)	NO
03_Ensuite 030	NO (-85%)	NO
03_Ensuite 031	N/A	N/A
03_Ensuite 032	N/A	N/A
03_Ensuite 033	N/A	N/A
03_Ensuite 034	N/A	N/A
03_Ensuite 035	NO (-62.4%)	NO
03_Ensuite 036	NO (-85.3%)	NO
03_Ensuite 037	N/A	N/A
03_Ensuite 038	N/A	N/A
03_Ensuite 039	NO (-72.7%)	NO
03_Ensuite 040	N/A	N/A
03_Ensuite 041	N/A	N/A
03_Ensuite 042	N/A	N/A
03_Ensuite 043	N/A	N/A
03_Ensuite 044	N/A	N/A
03_Ensuite 045	N/A	N/A
03_Ensuite 046	N/A	N/A
03_Ensuite 047	NO (-60.8%)	NO
03_Ensuite 048	NO (-78.5%)	NO
03_Ensuite 049	NO (-73.8%)	NO
03_Ensuite 050	N/A	N/A
03_Ensuite 051	NO (-86.4%)	NO
03_Ensuite 052	NO (-77.2%)	NO
03_Ensuite 053	NO (-74.7%)	NO
03_Ensuite 054	NO (-84.7%)	NO
03_Ensuite 055	N/A	N/A
03_Ensuite 056	NO (-78.7%)	NO
03_Ensuite 057	NO (-15.7%)	NO
03_Ensuite 058	N/A	N/A
03_Ensuite 059	N/A	N/A
03_Ensuite 060	NO (-21.7%)	NO
03_Ensuite 061	N/A	N/A
03_Ensuite 062	NO (-79.4%)	NO
03_Ensuite 063	N/A	N/A
03_Ensuite 064	NO (-63.2%)	NO
03_Ensuite 065	N/A	N/A
03_Ensuite 066	NO (-77%)	NO
03_Ensuite 067	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
03_Ensuite 068	NO (-76.4%)	NO
03_Ensuite 069	N/A	N/A
03_Ensuite 070	NO (-96.4%)	NO
03_Ensuite 071	N/A	N/A
03_Ensuite 072	N/A	N/A
03_Ensuite 073	N/A	N/A
03_HDU Lobby 001	N/A	N/A
03_HDU Lobby 002	N/A	N/A
03_HDU Lobby 003	N/A	N/A
03_HDU Lobby 004	N/A	N/A
03_Interview 001	N/A	N/A
03_Interview 002	N/A	N/A
03_Interview 003	N/A	N/A
03_Interview 004	N/A	N/A
03_Interview 005	N/A	N/A
03_Iso Lobby 001	N/A	N/A
03_Iso Lobby 002	N/A	N/A
03_IT HUB 001	N/A	N/A
03_IT HUB 002	N/A	N/A
03_IT HUB 003	N/A	N/A
03_IT HUB 004	N/A	N/A
03_Larger Therapy Store	NO (-93.3%)	NO
03_MDT Room 001	NO (-96.2%)	NO
03_MDT Room 002	NO (-85.4%)	NO
03_MDT Room 003	NO (-85.4%)	NO
03_MDT Room 004	NO (-96.2%)	NO
03_NPT Lab	N/A	N/A
03_Office 001	N/A	N/A
03_Office 002	N/A	N/A
03_Office 003	NO (-76.2%)	NO
03_Office 004	N/A	N/A
03_Office: Open Plan 001	N/A	N/A
03_Office: Open Plan 002	NO (-91.3%)	NO
03_On-Call+Ensuite 001	N/A	N/A
03_On-Call+Ensuite 002	N/A	N/A
03_On-Call+Ensuite 003	N/A	N/A
03_Oncology Waiting	N/A	N/A
03_Pantry/Kitchen 002	N/A	N/A
03_Pantry/Kitchen 003	N/A	N/A
03_Patient Pods 001	NO (-67.5%)	NO
03_Patient Pods 002	NO (-69.2%)	NO
03_Patient Pods 003	NO (-70.5%)	NO
03_Patient Pods 004	NO (-67.9%)	NO
03_Patient Pods 005	NO (-70.8%)	NO
03_Patient Pods 006	NO (-67.5%)	NO
03_Patient Weigh/Assessment	N/A	N/A
03_Phebotomy Chair	N/A	N/A
03_Play	NO (-84.6%)	NO
03_Quiet room	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
03_Quiet room/int	N/A	N/A
03_Reception	N/A	N/A
03_Resus Bay 004	N/A	N/A
03_Seminar	N/A	N/A
03_SERVER ROOM	N/A	N/A
03_Shared Admin	N/A	N/A
03_Shared Day Space	N/A	N/A
03_Single Bedroom 001	N/A	N/A
03_Single Bedroom 002	NO (-74.7%)	NO
03_Single Bedroom 003	N/A	N/A
03_Single Bedroom 004	NO (-51.5%)	NO
03_Single Bedroom 005	NO (-63.3%)	NO
03_Single Bedroom 006	NO (-57.4%)	NO
03_Single Bedroom 007	N/A	N/A
03_Single Bedroom 008	N/A	N/A
03_Single Bedroom 009	NO (-79.7%)	NO
03_Single Bedroom 010	NO (-85.4%)	NO
03_Single Bedroom 011	NO (-85.5%)	NO
03_Single Bedroom 012	NO (-86.1%)	NO
03_Single Bedroom 013	NO (-81.1%)	NO
03_Single Bedroom 014	NO (-86.4%)	NO
03_Single Bedroom 015	NO (-84.8%)	NO
03_Single Bedroom 016	NO (-98.3%)	NO
03_Single Bedroom 017	N/A	N/A
03_Single Bedroom 018	NO (-91.2%)	NO
03_Single Bedroom 019	NO (-70.9%)	NO
03_Single Bedroom 020	NO (-86.3%)	NO
03_Single Bedroom 021	NO (-81.1%)	NO
03_Single Bedroom 022	NO (-4.7%)	NO
03_Single Bedroom 023	NO (-85.7%)	NO
03_Single Bedroom 024	NO (-92.2%)	NO
03_Single Bedroom 025	NO (-79%)	NO
03_Single Bedroom 026	NO (-26.1%)	NO
03_Single Bedroom 027	NO (-78.3%)	NO
03_Single Bedroom 028	NO (-86.1%)	NO
03_Single Bedroom 029	N/A	N/A
03_Single Bedroom 030	NO (-64.5%)	NO
03_Single Bedroom 031	N/A	N/A
03_Single Bedroom 032	N/A	N/A
03_Single Bedroom 033	NO (-73.5%)	NO
03_Single Bedroom 034	NO (-94.3%)	NO
03_Single Bedroom 035	NO (-73.4%)	NO
03_Single Bedroom 036	N/A	N/A
03_Single Bedroom 037	NO (-76.7%)	NO
03_Single Bedroom 038	NO (-69.9%)	NO
03_Single Bedroom 039	NO (-72.3%)	NO
03_Single Bedroom 040	NO (-85.5%)	NO
03_Single Bedroom 041	NO (-73.5%)	NO
03_Single Bedroom 042	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
03_Single Bedroom 043	N/A	N/A
03_Single Bedroom 044	NO (-84.2%)	NO
03_Single Bedroom 045	NO (-85.7%)	NO
03_Single Bedroom 046	NO (-86.8%)	NO
03_Single Bedroom 047	NO (-79.7%)	NO
03_Single Bedroom 048	N/A	N/A
03_Single Bedroom 049	N/A	N/A
03_Single Bedroom 050	NO (-93.2%)	NO
03_Single Bedroom 051	NO (-75.7%)	NO
03_Single Bedroom 052	NO (-4.6%)	NO
03_Single Bedroom 053	NO (-76.6%)	NO
03_Single Bedroom 054	NO (-79.3%)	NO
03_Single Bedroom 055	NO (-80%)	NO
03_Single Bedroom 056	N/A	N/A
03_Single Bedroom 057	NO (-87.6%)	NO
03_Single Room 001	NO (-33%)	NO
03_Single Room 002	NO (-79.7%)	NO
03_Single Room 003	NO (-5.8%)	NO
03_Single Room 004	NO (-71.6%)	NO
03_Single Room 005	NO (-96.5%)	NO
03_Single Room 006	N/A	N/A
03_Single room (HDU) 001	NO (-85.7%)	NO
03_Single room (HDU) 002	NO (-85.8%)	NO
03_Single room (HDU) 003	NO (-87.5%)	NO
03_Social Space/Dining 001	NO (-90.4%)	NO
03_Social Space/Dining 002	NO (-93.1%)	NO
03_Staff Base 001	N/A	N/A
03_Staff Base 002	N/A	N/A
03_Staff Base 003	N/A	N/A
03_Staff Base 004	N/A	N/A
03_Staff Base 005	N/A	N/A
03_Staff Base 006	N/A	N/A
03_Staff Base with Pneumt Tube 001	N/A	N/A
03_Staff Base with Pneumt Tube 002	NO (-98.9%)	NO
03_Staff Base with Pneumt Tube 003	N/A	N/A
03_Staff Base with Pneumt Tube 004	N/A	N/A
03_Staff Communal Changing Room 001	NO (-79.6%)	NO
03_Staff Rest/Base	NO (-87.6%)	NO
03_Staff Rest/Bev 001	NO (-87.6%)	NO
03_Staff Rest/Bev 002	N/A	N/A
03_Therapy Workbase	N/A	N/A
03_Treatment 001	N/A	N/A
03_Treatment 002	NO (-71.6%)	NO
03_Treatment (2-sided) 001	N/A	N/A
03_Treatment (2-sided) 002	N/A	N/A
03_Treatment Chemo	N/A	N/A
03_Unit Pantry 001	N/A	N/A
03_Unit Pantry 002	N/A	N/A
03_Wait 001	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
03_Wait 002	N/A	N/A
03_Wait 003	N/A	N/A
03_Ward Managers Office 001	N/A	N/A
03_Ward Managers Office 002	N/A	N/A
04_2-Bed Bay w cot 001	NO (-90.8%)	NO
04_2-Bed Bay w cot 002	NO (-90.7%)	NO
04_4-cot bay 001	NO (-74.1%)	NO
04_4-cot bay 002	NO (-93.2%)	NO
04_Admin/Staff Base	NO (-82.6%)	NO
04_Anaesthetic Room 001	N/A	N/A
04_Anaesthetic Room 002	N/A	N/A
04_Bereavement: Labour 001	NO (-77.1%)	NO
04_Bereavement: Labour 002	NO (-76.8%)	NO
04_Bereavement: Neonates	NO (-76.8%)	NO
04_C/E 001	NO (-88.2%)	NO
04_C/E 002	N/A	N/A
04_C/E 003	N/A	N/A
04_C/E 004	NO (-87.6%)	NO
04_C/E 005	NO (-87.5%)	NO
04_C/E 006	N/A	N/A
04_C/E 007	N/A	N/A
04_C/E 008	NO (-72.5%)	NO
04_C/E 009	N/A	N/A
04_C/E 010	N/A	N/A
04_Cots: Single room 001	NO (-62.9%)	NO
04_Cots: Single room 002	NO (-80.8%)	NO
04_Cots: Single room 003	NO (-83%)	NO
04_Cots: Single room 004	NO (-88.3%)	NO
04_Cots: Single room 005	NO (-88.3%)	NO
04_Cots: Single room 006	NO (-93.8%)	NO
04_Cots: Single room 007	NO (-86.6%)	NO
04_Cots: Single room 008	NO (-87.4%)	NO
04_Cots: Single room 009	NO (-74.9%)	NO
04_Cots: Single room 010	NO (-68.1%)	NO
04_Delivery Room 001	NO (-78%)	NO
04_Delivery Room 002	NO (-80.1%)	NO
04_Delivery Room 003	NO (-78.2%)	NO
04_Delivery Room 004	NO (-80.2%)	NO
04_Delivery Room 005	NO (-78.2%)	NO
04_Delivery Room 006	NO (-78.2%)	NO
04_Delivery: Large 001	NO (-81.2%)	NO
04_Delivery: Large 002	NO (-82.4%)	NO
04_Delivery: Large 003	NO (-82.3%)	NO
04_Delivery: Large 004	NO (-81.7%)	NO
04_Delivery: Large 005	NO (-63.6%)	NO
04_Delivery: Large 006	NO (-81.3%)	NO
04_Delivery: Large 007	NO (-86%)	NO
04_Delivery: Large 008	NO (-88.2%)	NO
04_Delivery: Large 009	NO (-81.8%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
04_Delivery: Large 010	N/A	N/A
04_Ensuite 001	N/A	N/A
04_Ensuite 002	NO (-87.2%)	NO
04_Ensuite 003	NO (-90.4%)	NO
04_Ensuite 004	N/A	N/A
04_Ensuite 005	NO (-85.5%)	NO
04_Ensuite 006	NO (-82.2%)	NO
04_Ensuite 007	N/A	N/A
04_Ensuite 009	NO (-79.8%)	NO
04_Ensuite 010	N/A	N/A
04_Ensuite 011	NO (-66.8%)	NO
04_Ensuite 012	NO (-72%)	NO
04_Ensuite 013	NO (-69.9%)	NO
04_Ensuite 014	N/A	N/A
04_Ensuite 015	N/A	N/A
04_Ensuite 016	N/A	N/A
04_Ensuite 017	N/A	N/A
04_Ensuite 018	N/A	N/A
04_Ensuite 019	NO (-50.7%)	NO
04_Ensuite 020	N/A	N/A
04_Ensuite 021	N/A	N/A
04_Ensuite 022	NO (-80.6%)	NO
04_Ensuite 023	N/A	N/A
04_Ensuite 024	N/A	N/A
04_Ensuite 025	NO (-84.6%)	NO
04_Ensuite 026	NO (-90.1%)	NO
04_Ensuite 027	N/A	N/A
04_Ensuite 028	N/A	N/A
04_Ensuite 029	N/A	N/A
04_Ensuite 030	N/A	N/A
04_Ensuite 031	N/A	N/A
04_Ensuite 032	N/A	N/A
04_Ensuite 033	NO (-65.9%)	NO
04_Ensuite 034	NO (-80.7%)	NO
04_Ensuite 035	N/A	N/A
04_Ensuite 036	NO (-69%)	NO
04_Ensuite 037	NO (-73%)	NO
04_Ensuite 038	N/A	N/A
04_Ensuite 039	NO (-73.6%)	NO
04_Ensuite 040	NO (-88.5%)	NO
04_Ensuite 041	N/A	N/A
04_Ensuite 042	N/A	N/A
04_Ensuite 043	N/A	N/A
04_Ensuite 044	N/A	N/A
04_Ensuite 045	NO (-77%)	NO
04_Ensuite 046	NO (-85.2%)	NO
04_Ensuite 047	N/A	N/A
04_Ensuite 048	N/A	N/A
04_Ensuite 049	NO (-81.9%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
04_Ensuite 050	NO (-85.1%)	NO
04_Ensuite 051	NO (-58.9%)	NO
04_Ensuite 052	N/A	N/A
04_Ensuite 053	N/A	N/A
04_Ensuite 054	N/A	N/A
04_Ensuite 055	N/A	N/A
04_Ensuite 056	N/A	N/A
04_Ensuite 057	NO (-82%)	NO
04_Ensuite 058	N/A	N/A
04_Ensuite 059	N/A	N/A
04_Ensuite 060	N/A	N/A
04_Ensuite 061	N/A	N/A
04_Ensuite 062	N/A	N/A
04_Ensuite 063	N/A	N/A
04_Ensuite 064	NO (-76.3%)	NO
04_Ensuite 065	NO (-76.3%)	NO
04_Ensuite 066	N/A	N/A
04_Ensuite 068	N/A	N/A
04_Ensuite 069	NO (-51.8%)	NO
04_Ensuite 070	N/A	N/A
04_Ensuite 071	N/A	N/A
04_Ensuite 072	N/A	N/A
04_Ensuite 073	N/A	N/A
04_Ensuite 074	N/A	N/A
04_Ensuite 075	N/A	N/A
04_Ensuite 076	NO (-74.9%)	NO
04_Group Room	N/A	N/A
04_HDU Room	NO (-79.7%)	NO
04_Hearing test room 001	N/A	N/A
04_Hearing test room 002	N/A	N/A
04_Interview/Quiet Room	NO (-87.9%)	NO
04_Iso Lobby 003	N/A	N/A
04_Iso Lobby 004	N/A	N/A
04_IT HUB 001	N/A	N/A
04_IT HUB 002	N/A	N/A
04_IT HUB 003	N/A	N/A
04_Junior Doctor Office	NO (-79.8%)	NO
04_Office 001	NO (-83.7%)	NO
04_Office 002	NO (-87%)	NO
04_Office 003	NO (-91.4%)	NO
04_Office 004	NO (-84.8%)	NO
04_Office 005	N/A	N/A
04_Office 006	N/A	N/A
04_Office 007	N/A	N/A
04_Office 008	N/A	N/A
04_Office 009	N/A	N/A
04_Office 010	NO (-59.8%)	NO
04_Office 011	N/A	N/A
04_Office 012	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
04_Office 013	NO (-88.3%)	NO
04_Office 014	N/A	N/A
04_Office 015	N/A	N/A
04_Office 016	N/A	N/A
04_Office 017	NO (-85%)	NO
04_Office - Manager	N/A	N/A
04_Office - reporting (4)	N/A	N/A
04_Office/Teams 001	N/A	N/A
04_Office/Teams 002	N/A	N/A
04_On-Call Room 001	N/A	N/A
04_On-Call Room 002	N/A	N/A
04_Parent's Kitchen/Dining Room	NO (-95.7%)	NO
04_Parent's Lounge	NO (-62.9%)	NO
04_Parents: ONS	NO (-70.7%)	NO
04_PoCT 001	N/A	N/A
04_PoCT 002	N/A	N/A
04_PoCT 003	N/A	N/A
04_PoCT 004	N/A	N/A
04_Prep Room	N/A	N/A
04_Reception	NO (-93.5%)	NO
04_Reception/Wait 001	N/A	N/A
04_Reception/Wait 002	N/A	N/A
04_Reception/Wait 003	NO (-92.2%)	NO
04_Reception/Wait 004	NO (-91.6%)	NO
04_Recovery (Stage 1) 001	NO (-73.5%)	NO
04_Recovery (Stage 1) 002	NO (-80%)	NO
04_Recovery (Stage 1) 003	NO (-94.6%)	NO
04_Recovery (Stage 1) 004	NO (-78.8%)	NO
04_Rooming-In	NO (-93.9%)	NO
04_Seminar 001	N/A	N/A
04_Seminar 002	NO (-86.6%)	NO
04_Seminar 003	N/A	N/A
04_Single bedroom AN 001	NO (-63.9%)	NO
04_Single bedroom AN 002	NO (-31.2%)	NO
04_Single bedroom AN 003	NO (-87.3%)	NO
04_Single bedroom AN 004	NO (-35.2%)	NO
04_Single bedroom AN 005	NO (-89.8%)	NO
04_Single bedroom AN 006	NO (-37.7%)	NO
04_Single bedroom AN 007	NO (-88.9%)	NO
04_Single bedroom AN 008	NO (-72.9%)	NO
04_Single bedroom AN 009	NO (-92.4%)	NO
04_Single bedroom w cot 001	NO (-86.5%)	NO
04_Single bedroom w cot 002	NO (-89.5%)	NO
04_Single bedroom w cot 003	NO (-35.3%)	NO
04_Single bedroom w cot 004	NO (-85%)	NO
04_Single bedroom w cot 005	N/A	N/A
04_Single bedroom w cot 006	NO (-76.3%)	NO
04_Single bedroom w cot 007	NO (-36.8%)	NO
04_Single bedroom w cot 008	NO (-74.5%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
04_Single bedroom w cot 009	NO (-83%)	NO
04_Single bedroom w cot 010	N/A	N/A
04_Single bedroom w cot 011	NO (-83.7%)	NO
04_Single bedroom w cot 012	N/A	N/A
04_Single bedroom w cot 013	NO (-65.3%)	NO
04_Single bedroom w cot 014	NO (-74.8%)	NO
04_Single bedroom w cot 015	NO (-90.2%)	NO
04_Single bedroom w cot 016	NO (-91%)	NO
04_Single bedroom w cot 017	NO (-87.4%)	NO
04_Single bedroom w cot 018	NO (-83.9%)	NO
04_Single day space AN 001	NO (-87.3%)	NO
04_Single day space AN 002	NO (-87.3%)	NO
04_Single day space AN 003	NO (-70.3%)	NO
04_Single day space AN 004	NO (-70.3%)	NO
04_Single day space AN 005	NO (-84.9%)	NO
04_Single day space AN 006	NO (-84.9%)	NO
04_Skills Lab	NO (-73.9%)	NO
04_Staff Base 001	N/A	N/A
04_Staff Base 002	N/A	N/A
04_Staff Base 003	N/A	N/A
04_Staff Base 004	N/A	N/A
04_Staff Base 005	N/A	N/A
04_Staff Base 006	NO (-99.4%)	NO
04_Staff Base 007	NO (-99.6%)	NO
04_Staff Base 008	N/A	N/A
04_Staff Base 009	N/A	N/A
04_Staff Base 010	N/A	N/A
04_Staff Office	N/A	N/A
04_Staff Rest/Bev 001	NO (-85.3%)	NO
04_Staff Rest/Bev 002	NO (-64.1%)	NO
04_Staff Rest/Bev 003	NO (-84.7%)	NO
04_Staff Rest/Bev 004	NO (-89.6%)	NO
04_Staff Rest/Bev 005	N/A	N/A
04_Staff Rest/Bev 006	NO (-94.6%)	NO
04_TCU Office	N/A	N/A
04_TCU/single room w cot 001	NO (-86.6%)	NO
04_TCU/single room w cot 002	NO (-47.4%)	NO
04_TCU/single room w cot 003	NO (-31.3%)	NO
04_TCU/single room w cot 004	N/A	N/A
04_TCU/single room w cot 005	NO (-72.4%)	NO
04_TCU/single room w cot 006	NO (-88.5%)	NO
04_Theatre: C-section 001	N/A	N/A
04_Theatre: C-section 002	N/A	N/A
04_Treat: Procedures	N/A	N/A
04_Treatment (2-sided)	NO (-82.4%)	NO
04_Treatment: Phleb/Vacc 001	N/A	N/A
04_Treatment: Phleb/Vacc 002	N/A	N/A
04_Treatment: Phleb/Vacc 003	N/A	N/A
04_Treatment: Phleb/Vacc 004	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
04_Triage 001	N/A	N/A
04_Triage 002	N/A	N/A
04_Triage 003	N/A	N/A
04_Triage 004	N/A	N/A
04_Triage 005	N/A	N/A
04_Ultrasound 001	NO (-92.1%)	NO
04_Ultrasound 002	NO (-92.2%)	NO
04_Ultrasound 003	NO (-83.9%)	NO
04_Ultrasound 004	NO (-79.2%)	NO
04_Ultrasound 005	NO (-54.2%)	NO
04_Ultrasound 006	NO (-82.2%)	NO
04_Unit Pantry 004	N/A	N/A
04_Unit Pantry 001	N/A	N/A
04_Unit Pantry 002	N/A	N/A
04_Unit Pantry 003	N/A	N/A
04_Waiting: 10 places 001	N/A	N/A
04_Waiting: 10 places 002	N/A	N/A
05_4-Bed Bay 001	NO (-86.7%)	NO
05_4-Bed Bay 002	NO (-86.7%)	NO
05_4-Bed Bay 003	NO (-86.7%)	NO
05_4-Bed Bay 004	NO (-86.7%)	NO
05_4-Bed Bay 005	NO (-86.7%)	NO
05_4-Bed Bay 006	NO (-86.7%)	NO
05_ARU Gym	N/A	N/A
05_Bariatric Bedroom 001	NO (-73.7%)	NO
05_Bariatric Bedroom 002	NO (-92.7%)	NO
05_Bariatric Bedroom 003	NO (-91.5%)	NO
05_En-suite Bariatric 001	N/A	N/A
05_En-suite Bariatric 002	N/A	N/A
05_En-suite Bariatric 003	N/A	N/A
05_Ensuite 001	N/A	N/A
05_Ensuite 002	NO (-42.5%)	NO
05_Ensuite 003	NO (-42.1%)	NO
05_Ensuite 004	N/A	N/A
05_Ensuite 005	N/A	N/A
05_Ensuite 006	N/A	N/A
05_Ensuite 007	N/A	N/A
05_Ensuite 008	NO (-93.3%)	NO
05_Ensuite 009	NO (-60.5%)	NO
05_Ensuite 010	NO (-38.3%)	NO
05_Ensuite 011	NO (-85.1%)	NO
05_Ensuite 012	NO (-90.5%)	NO
05_Ensuite 013	NO (-73.4%)	NO
05_Ensuite 014	NO (-82.4%)	NO
05_Ensuite 015	N/A	N/A
05_Ensuite 016	NO (-47.8%)	NO
05_Ensuite 017	NO (-72.1%)	NO
05_Ensuite 018	N/A	N/A
05_Ensuite 019	NO (-59.7%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
05_Ensuite 020	N/A	N/A
05_Ensuite 021	N/A	N/A
05_Ensuite 022	NO (-84.8%)	NO
05_Ensuite 023	NO (-90.3%)	NO
05_Ensuite 024	N/A	N/A
05_Ensuite 025	NO (-81.1%)	NO
05_Ensuite 026	NO (-84.2%)	NO
05_Ensuite 027	NO (-93.5%)	NO
05_Ensuite 028	NO (-37.2%)	NO
05_Ensuite 029	N/A	N/A
05_Ensuite 030	N/A	N/A
05_Ensuite 031	NO (-60.9%)	NO
05_Ensuite 032	NO (-67.3%)	NO
05_Ensuite 033	N/A	N/A
05_Ensuite 034	NO (-60.2%)	NO
05_Ensuite 035	NO (-21.8%)	NO
05_Ensuite 036	N/A	N/A
05_Ensuite 037	NO (-70.9%)	NO
05_Ensuite 038	N/A	N/A
05_Ensuite 039	N/A	N/A
05_Ensuite 040	NO (-68.3%)	NO
05_Ensuite 041	NO (-73.7%)	NO
05_Ensuite 042	NO (-94.7%)	NO
05_Ensuite 043	N/A	N/A
05_Ensuite 044	NO (-83%)	NO
05_Ensuite 045	NO (-71.6%)	NO
05_Ensuite 046	N/A	N/A
05_Ensuite 047	NO (-83.2%)	NO
05_Ensuite 048	NO (-72.8%)	NO
05_Ensuite 049	NO (-68.6%)	NO
05_Ensuite 050	N/A	N/A
05_Ensuite 051	NO (-90%)	NO
05_Ensuite 052	N/A	N/A
05_Ensuite 053	N/A	N/A
05_Ensuite 054	NO (-73.3%)	NO
05_Ensuite 055	NO (-62.1%)	NO
05_Ensuite 056	NO (-70.9%)	NO
05_Ensuite 057	NO (-71%)	NO
05_Interview 001	N/A	N/A
05_Interview 002	NO (-92.6%)	NO
05_Interview 003	NO (-92.6%)	NO
05_Interview 004	N/A	N/A
05_Interview 005	N/A	N/A
05_Interview 006	N/A	N/A
05_Iso Lobby 001	N/A	N/A
05_Iso Lobby 002	N/A	N/A
05_Iso Lobby 003	N/A	N/A
05_IT HUB 001	N/A	N/A
05_IT HUB 002	N/A	N/A

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
05_IT HUB 003	N/A	N/A
05_IT HUB 004	N/A	N/A
05_IT HUB 005	N/A	N/A
05_MDT Room 001	NO (-89.9%)	NO
05_MDT Room 002	NO (-95.4%)	NO
05_MDT Room 003	NO (-95.6%)	NO
05_MDT Room 004	NO (-87.7%)	NO
05_MDT Room 005	NO (-85.4%)	NO
05_MDT Room 006	NO (-85.4%)	NO
05_Meds Store/Prep 001	N/A	N/A
05_Meds Store/Prep 002	N/A	N/A
05_Meds Store/Prep 003	N/A	N/A
05_Meeting Room	N/A	N/A
05_Office 001	N/A	N/A
05_Office 002	N/A	N/A
05_Office 003	N/A	N/A
05_OT Office: 6 Workstations	N/A	N/A
05_Physio office: 6 workstations	N/A	N/A
05_Resus Bay 002	N/A	N/A
05_Shared Admin 001	N/A	N/A
05_Shared Admin 002	N/A	N/A
05_Shared Day Space	N/A	N/A
05_Single Bedroom 001	NO (-89%)	NO
05_Single Bedroom 002	NO (-73.5%)	NO
05_Single Bedroom 003	NO (-53.9%)	NO
05_Single Bedroom 004	NO (-46.6%)	NO
05_Single Bedroom 005	NO (-79.8%)	NO
05_Single Bedroom 006	NO (-96.1%)	NO
05_Single Bedroom 007	NO (-52%)	NO
05_Single Bedroom 008	NO (-29.2%)	NO
05_Single Bedroom 009	NO (-90.4%)	NO
05_Single Bedroom 010	NO (-44.9%)	NO
05_Single Bedroom 011	N/A	N/A
05_Single Bedroom 012	NO (-86.5%)	NO
05_Single Bedroom 013	NO (-88.6%)	NO
05_Single Bedroom 014	NO (-59.3%)	NO
05_Single Bedroom 015	NO (-54%)	NO
05_Single Bedroom 016	N/A	N/A
05_Single Bedroom 017	N/A	N/A
05_Single Bedroom 018	NO (-86.3%)	NO
05_Single Bedroom 019	NO (-70.7%)	NO
05_Single Bedroom 020	NO (-73.3%)	NO
05_Single Bedroom 021	NO (-87.5%)	NO
05_Single Bedroom 022	NO (-67.8%)	NO
05_Single Bedroom 023	NO (-48.3%)	NO
05_Single Bedroom 024	NO (-61.9%)	NO
05_Single Bedroom 025	NO (-81.3%)	NO
05_Single Bedroom 026	NO (-86.5%)	NO
05_Single Bedroom 027	NO (-29.1%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
05_Single Bedroom 028	N/A	N/A
05_Single Bedroom 029	NO (-85.6%)	NO
05_Single Bedroom 030	NO (-26.4%)	NO
05_Single Bedroom 031	NO (-82.6%)	NO
05_Single Bedroom 032	NO (-81.8%)	NO
05_Single Bedroom 033	NO (-81.5%)	NO
05_Single Bedroom 034	NO (-72.8%)	NO
05_Single Bedroom 035	NO (-71.6%)	NO
05_Single Bedroom 036	NO (-44.4%)	NO
05_Single Bedroom 037	NO (-69.4%)	NO
05_Single Bedroom 038	NO (-53.9%)	NO
05_Single Bedroom 039	NO (-34.6%)	NO
05_Single Bedroom 040	NO (-82.9%)	NO
05_Single Bedroom 041	NO (-70.8%)	NO
05_Single Bedroom 042	NO (-82.1%)	NO
05_Single Bedroom 043	NO (-88.7%)	NO
05_Single Bedroom 044	N/A	N/A
05_Single Bedroom 045	NO (-67.7%)	NO
05_Single Bedroom 046	NO (-81.6%)	NO
05_Single Bedroom 047	NO (-32.5%)	NO
05_Single Bedroom 048	NO (-81.8%)	NO
05_Single Bedroom 049	NO (-81.5%)	NO
05_Single Bedroom 050	N/A	N/A
05_Single Bedroom 051	N/A	N/A
05_Single Bedroom 052	NO (-68.8%)	NO
05_Single Bedroom 053	N/A	N/A
05_Single Bedroom 054	N/A	N/A
05_Single Bedroom 055	NO (-59.1%)	NO
05_Single Bedroom 056	NO (-55.8%)	NO
05_Single Bedroom 057	NO (-97.4%)	NO
05_Staff Base 001	N/A	N/A
05_Staff Base 002	NO (-95.9%)	NO
05_Staff Base 003	NO (-100%)	NO
05_Staff Base 004	NO (-100%)	NO
05_Staff Base 005	N/A	N/A
05_Staff Base 006	N/A	N/A
05_Staff Base 007	N/A	N/A
05_Staff Base 008	NO (-100%)	NO
05_Staff Rest/Bev 001	NO (-87.7%)	NO
05_Staff Rest/Bev 002	NO (-89.5%)	NO
05_Staff Rest/Bev 003	NO (-89.6%)	NO
05_Treatment (2-sided) 001	N/A	N/A
05_Treatment (2-sided) 002	N/A	N/A
05_Treatment (2-sided) 003	N/A	N/A
05_Unit Pantry 001	N/A	N/A
05_Unit Pantry 002	N/A	N/A
05_Unit Pantry 003	N/A	N/A
06_4 Bed bay 001	NO (-85%)	NO
06_4 Bed bay 002	NO (-85%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
06_4 Bed bay 003	NO (-85%)	NO
06_4 Bed bay 004	NO (-85%)	NO
06_4 Bed bay 005	NO (-85%)	NO
06_4 Bed bay 006	NO (-85%)	NO
06_Bariatric Bedroom 001	NO (-91.9%)	NO
06_Bariatric Bedroom 002	NO (-66.3%)	NO
06_Bariatric Bedroom 003	NO (-89.1%)	NO
06_Clinical Psychology Office	N/A	N/A
06_Corporate Office 001	N/A	N/A
06_Corporate Office 002	N/A	N/A
06_Corporate Office 003	N/A	N/A
06_Corridor 009	NO (-93.4%)	NO
06_Ensuite 001	NO (-63.9%)	NO
06_Ensuite 002	NO (-89.4%)	NO
06_Ensuite 003	N/A	N/A
06_Ensuite 004	NO (-58.7%)	NO
06_Ensuite 005	NO (-63.1%)	NO
06_Ensuite 006	NO (-40.2%)	NO
06_Ensuite 007	NO (-84.2%)	NO
06_Ensuite 008	NO (-41.5%)	NO
06_Ensuite 009	NO (-52.5%)	NO
06_Ensuite 010	NO (-39%)	NO
06_Ensuite 011	NO (-57.6%)	NO
06_Ensuite 012	NO (-88.9%)	NO
06_Ensuite 013	NO (-92.4%)	NO
06_Ensuite 014	NO (-60.6%)	NO
06_Ensuite 015	NO (-63%)	NO
06_Ensuite 016	NO (-52%)	NO
06_Ensuite 017	N/A	N/A
06_Ensuite 018	NO (-39.2%)	NO
06_Ensuite 019	NO (-82.6%)	NO
06_Ensuite 020	NO (-82.5%)	NO
06_Ensuite 021	NO (-93.3%)	NO
06_Ensuite 022	NO (-68.5%)	NO
06_Ensuite 023	NO (-14.8%)	NO
06_Ensuite 024	NO (-58.2%)	NO
06_Ensuite 025	NO (-78.8%)	NO
06_Ensuite 026	N/A	N/A
06_Ensuite 027	N/A	N/A
06_Ensuite 028	N/A	N/A
06_Ensuite 029	N/A	N/A
06_Ensuite 030	N/A	N/A
06_Ensuite 031	N/A	N/A
06_Ensuite 032	NO (-72.4%)	NO
06_Ensuite 033	N/A	N/A
06_Ensuite 034	NO (-83.6%)	NO
06_Ensuite 035	NO (-35.5%)	NO
06_Ensuite 036	NO (-36.7%)	NO
06_Ensuite 037	NO (-90.3%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
06_Ensuite 038	N/A	N/A
06_Ensuite 039	N/A	N/A
06_Ensuite 040	N/A	N/A
06_Ensuite 041	N/A	N/A
06_Ensuite 042	N/A	N/A
06_Ensuite 043	NO (-81.5%)	NO
06_Ensuite 044	N/A	N/A
06_Ensuite 045	NO (-72.7%)	NO
06_Ensuite 046	NO (-82.3%)	NO
06_Ensuite 047	N/A	N/A
06_Ensuite 048	N/A	N/A
06_Ensuite 049	N/A	N/A
06_Ensuite 050	N/A	N/A
06_Ensuite 051	NO (-71.5%)	NO
06_Ensuite 052	NO (-63.1%)	NO
06_Ensuite 053	N/A	N/A
06_Ensuite 054	N/A	N/A
06_Ensuite 055	NO (-90.4%)	NO
06_Ensuite 056	NO (-40.7%)	NO
06_Ensuite 057	NO (-67.8%)	NO
06_Ensuite Bariatric 001	N/A	N/A
06_Ensuite Bariatric	N/A	N/A
06_Ensuite Bariatric	N/A	N/A
06_Food Court Seating	NO (-75.8%)	NO
06_Interview 001	N/A	N/A
06_Interview 002	N/A	N/A
06_Interview 003	N/A	N/A
06_Interview 004	N/A	N/A
06_Interview 005	N/A	N/A
06_Interview 006	NO (-90.4%)	NO
06_Iso Lobby 001	N/A	N/A
06_Iso Lobby 002	N/A	N/A
06_Iso Lobby 003	N/A	N/A
06_Iso Lobby 004	N/A	N/A
06_Iso Lobby 005	N/A	N/A
06_Iso Lobby 006	N/A	N/A
06_Iso Single Bedroom 001	NO (-86%)	NO
06_Iso Single Bedroom 002	NO (-93.3%)	NO
06_Iso Single Bedroom 003	NO (-93.5%)	NO
06_IT HUB 001	N/A	N/A
06_IT HUB 002	N/A	N/A
06_IT HUB 003	N/A	N/A
06_Kitchens and Servery	NO (-91.2%)	NO
06_MDT Room 001	NO (-83.6%)	NO
06_MDT Room 002	NO (-74.4%)	NO
06_MDT Room 003	NO (-87%)	NO
06_MDT Room 004	NO (-94.8%)	NO
06_MDT Room 005	NO (-94.4%)	NO
06_MDT Room 006	NO (-83.8%)	NO

Zone	Solar gain limit exceeded? (%)	Internal blinds used?
06_MDT Room 007	NO (-83.6%)	NO
06_MDT Room 008	NO (-87%)	NO
06_Meeting Room 001	NO (-69.3%)	NO
06_Meeting Room 002	N/A	N/A
06_Meeting Room 003	N/A	N/A
06_Office 001	N/A	N/A
06_Office 002	N/A	N/A
06_Office 003	N/A	N/A
06_Office 004	N/A	N/A
06_Office 005	N/A	N/A
06_On-Call Room 001	NO (-70.4%)	NO
06_On-Call Room 002	N/A	N/A
06_Open Plan for 14 people 001	NO (-84.7%)	NO
06_Open Plan for 14 people 002	NO (-80.3%)	NO
06_Open Plan for 6 people	N/A	N/A
06_POD	NO (-93.5%)	NO
06_Resus Bay 001	N/A	N/A
06_Resus Bay 002	NO (-96.2%)	NO
06_Shared Admin 001	NO (-74.6%)	NO
06_Shared Admin 002	N/A	N/A
06_Shared Admin 003	NO (-69.7%)	NO
06_Shared Admin 004	NO (-74.1%)	NO
06_Shared Admin 005	NO (-71.7%)	NO
06_Shared Day Space	N/A	N/A
06_Single Bedroom 001	N/A	N/A
06_Single Bedroom 002	N/A	N/A
06_Single Bedroom 003	NO (-95.9%)	NO
06_Single Bedroom 004	NO (-41.1%)	NO
06_Single Bedroom 005	NO (-88%)	NO
06_Single Bedroom 006	N/A	N/A
06_Single Bedroom 007	NO (-37.1%)	NO
06_Single Bedroom 008	NO (-36.9%)	NO
06_Single Bedroom 009	NO (-85.5%)	NO
06_Single Bedroom 010	NO (-86.2%)	NO
06_Single Bedroom 011	NO (-85.1%)	NO
06_Single Bedroom 012	NO (-25.9%)	NO
06_Single Bedroom 013	N/A	N/A
06_Single Bedroom 014	NO (-84.3%)	NO
06_Single Bedroom 015	NO (-77.6%)	NO
06_Single Bedroom 016	N/A	N/A
06_Single Bedroom 017	NO (-36%)	NO
06_Single Bedroom 018	N/A	N/A
06_Single Bedroom 019	NO (-63.5%)	NO
06_Single Bedroom 020	NO (-68.2%)	NO
06_Single Bedroom 021	NO (-60%)	NO
06_Single Bedroom 022	NO (-60.3%)	NO
06_Single Bedroom 023	NO (-38.1%)	NO
06_Single Bedroom 024	NO (-77.3%)	NO
06_Single Bedroom 025	NO (-38.6%)	NO