

<b>Desk Study Photograph 1</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  A bridge crossing Tunnel Road West provides access to the site from the neighbouring Radisson Hotel & Conference Centre London Heathrow.  This photo is taken from the site entrance facing north-eastward.	

<b>Desk Study Photograph 2</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  The neighbouring Tunnel Road West as seen facing northwards from the bridge to the east of the site.  The road has been built within a cutting, creating a slope downward from the site to the road. This is vegetated as seen.	



<b>Desk Study Photograph 3</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  Former Customer Services building associated with the NCP Car Parking facility. This was boarded up and inaccessible.  A disused bus stop can be seen next to this structure.  Services facilitate this structure. It is unknown if they are live.	

<b>Desk Study Photograph 4</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  Outdoor plug sockets to the north-east of the Customer Service building. It is unknown if these facilities are live.	



<b>Desk Study Photograph 5</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  Disused metal shed at the north-east corner of the site. This was unlocked and empty at the time of the walkover.	

<b>Desk Study Photograph 6</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  The building immediately north of the site boundary as seen from a gap in the fencing. This appears to be disused and derelict.	



<b>Desk Study Photograph 7</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  Electrical vehicle charging points are present to the west of the Customer Service building. It is unknown whether this is live.	

<b>Desk Study Photograph 8</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  Mechanical barriers at the entrance of the site towards the north-east. The screen on the barriers was working at the time of the walkover, indicating live power on site.  Photograph taken from the barrier facing eastwards to the bridge.	



<b>Desk Study Photograph 9</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  Residential dwellings seen beyond the western site boundary, separated from the site via fencing and vegetation.  Photograph taken facing westwards.	

<b>Desk Study Photograph 10</b>	
<b>Date:</b> 16/05/2022	
<b>Description:</b>  Car park seen from the south-east corner of the site.	