

Reference G = Group H = Hedge	Age & Species	Height (m)	Crown Ht (m)	Diameter (cm)	Crown Spread (m) N W E S	Scaled Tree Diagram (m) 	Notes	Recommendations (Independent of any development proposals)		Vigour	Amenity Value
								Priority	Inspect Freq (yrs)	Physiological Condition	Life Expectancy (yrs)
										Structural Condition	Retention Category
T001	Early-Mature <b>Crab Apple</b> <i>Malus sylvestris.</i>	10	3	30	3 3.5 2.5		Form: Multiple stemmed with a compact crown. History: Crown lifted. Defects: <b>Minor Included bark at stem junctions.</b>	No action required.		Moderate	Moderate
								n/a	3	Good	40+
T002	Early-Mature <b>Crab Apple</b> <i>Malus sylvestris.</i>	10	3	27	2 3 2		Form: Multiple stemmed with a compact crown. History: Crown lifted. Defects: <b>Minor Included bark at stem junctions.</b>	No action required.		Moderate	Moderate
								n/a	3	Good	40+
T003	Early-Mature <b>Norway Maple</b> <i>Acer platanoides.</i>	13	3	48	5.5 4.5 5		Form: Multiple stemmed at 2m. History: No significant pruning. Defects: <b>No significant defects observed.</b> Other: Ivy prevented a detailed inspection.	No action required.		Moderate	Moderate
								n/a	3	Good	40+
T004	Semi-Mature <b>Field Maple</b> <i>Acer campestre.</i>	5.5	1.5	21	1.5 4 3		Form: Multiple stemmed at ground level. Defects: <b>Minor deadwood.</b> Other: Ivy prevented a detailed inspection.	No action required.		Moderate	Low
								n/a	3	Fair	20-40
T005	Semi-Mature <b>Norway Maple</b> <i>Acer platanoides.</i>	11	2	28	5 3.5 4		Form: Multiple stemmed at 1.5m. History: Crown lifted. Defects: <b>No significant defects observed.</b>	No action required.		Moderate	Moderate
								n/a	1.5	Good	40+
T006	Early-Mature <b>Norway Maple</b> <i>Acer platanoides.</i>	15	2.5	35	4.5 3.5 4.5		Form: Multiple stemmed at 2m. History: Crown lifted. Defects: <b>Minor cavities at old pruning wounds.</b>	No action required.		Moderate	Moderate
								n/a	1.5	Good	40+
T007	Semi-Mature <b>Norway Maple</b> <i>Acer platanoides.</i>	15	3.5	29	3.5 3.5 3.5		Form: Multiple stemmed at 1.5m. History: Crown lifted. Defects: <b>No significant defects observed.</b> Other: Ivy prevented a detailed inspection.	No action required.		Moderate	Moderate
								n/a	1.5	Good	40+

Reference G = Group H = Hedge	Age & Species	Height (m)	Crown Ht (m)	Diameter (cm)	Crown Spread (m) N W E S	Scaled Tree Diagram (m) 	Notes	Recommendations (Independent of any development proposals)		Vigour	Amenity Value
								Priority	Inspect Freq (yrs)	Physiological Condition	Life Expectancy (yrs)
										Structural Condition	Retention Category
G008	Early-Mature <b>Field Maple</b> Acer campestre.	av 15	av 4	av 30	av 5 5 5 each		Position: Top of embankment. Form: Group of similar specimens. History: No significant pruning. Defects: <b>No significant defects observed.</b> Other: Limited inspection, dimensions estimated. Ivy prevented a detailed inspection.	No action required.	1.5	Moderate  Good  Fair	Moderate  40+  <b>B -</b>
	n/a	1.5	Moderate  Good  Good	Moderate  40+  <b>B</b>							
G009	Early-Mature <b>Field Maple</b> Acer campestre.	av 16	av 4	av 35	av 4 4 5 each		Position: On top of embankment. Form: Group of four similar specimens. Defects: <b>Minor deadwood.</b>	No action required.	1.5	Moderate  Good  Good	Moderate  40+  <b>B</b>
	n/a	1.5	Moderate  Good  Good	Moderate  40+  <b>B</b>							
G010	Semi-Mature <b>Field Maple</b> Acer campestre.	av 16	av 1.5	av 18	av 4 4 5 each		Position: Situated on third party land. Form: Three close growing specimens, all twin stemmed. Defects: <b>No significant defects observed.</b>	No action required.	3	Moderate  Good  Good	Moderate  40+  <b>B</b>
	n/a	3	Moderate  Good  Good	Moderate  40+  <b>B</b>							
T011	Semi-Mature <b>Field Maple</b> Acer campestre.	6	1	15	2 2 2		Form: Balanced crown. Defects: <b>No significant defects observed.</b> Other: Vegetation prevented a detailed inspection.	No action required.	3	Moderate  Good  Good	Low  40+  <b>C</b>
	n/a	3	Moderate  Good  Good	Low  40+  <b>C</b>							
T012	Early-Mature <b>Sycamore</b> Acer pseudoplatanus.	10	2	40	4 5 5		Position: Ownership unclear. Form: Multiple stemmed. Defects: <b>No significant defects observed.</b> Other: Limited inspection, dimensions estimated. Vegetation prevented a detailed inspection.	No action required.	3	Moderate  Good  Good	Moderate  40+  <b>C+</b>
	n/a	3	Moderate  Good  Good	Moderate  40+  <b>C+</b>							
T013	Early-Mature <b>Sycamore</b> Acer pseudoplatanus.	8.5	0.5	35	3.5 4.5 5		Position: On canal embankment. Form: Multiple stemmed. Defects: <b>No significant defects observed.</b> Other: Access prevented a detailed inspection, some dimensions estimated.	No action required.	3	Moderate  Good  Good	Moderate  40+  <b>C+</b>
	n/a	3	Moderate  Good  Good	Moderate  40+  <b>C+</b>							
T014	Early-Mature <b>Sycamore</b> Acer pseudoplatanus.	8.5	1.5	22	2.5 4 4		Position: On canal embankment. Form: Multiple stemmed. Defects: <b>No significant defects observed.</b> Other: Access prevented a detailed inspection, some dimensions estimated.	No action required.	3	Moderate  Good  Good	Moderate  40+  <b>C+</b>
	n/a	3	Moderate  Good  Good	Moderate  40+  <b>C+</b>							