



## ALLARBORICULTURE

23 Southernhay Avenue, Bristol, BS8 4TJ

07375110399 | 0800 107 3652

e – info@allarboriculture.co.uk

# ARBORICULTURAL IMPACT ASSESSMENT AND METHOD STATEMENT

BS5837:2012

On behalf of:  
Mr. Davinder Lachhar

Site address:  
26 Parkway,  
Hillingdon, UB10 9JX

Prepared by:  
Kristian Chesterman  
BSc (Hons)

Report Reference:  
AAAI A26PA

Report Date:  
16th July 2023

## Contents

Chapters	Content	Page no.
1.0	Instruction	3
2.0	Statement Of Purpose	3
3.0	Associated Documents	3
4.0	Site Description	3
5.0	Vegetation Description	3
6.0	Arboricultural Impact	4
7.0	Assessment Method Statement	6

Appendix 1	Tree Survey Schedule
Appendix 2	Tree Protection
Appendix 3	Tree Protection Plan

## 1.0 Instruction

All Arboriculture has been instructed by Mr. Davinder Lachhar to undertake a tree survey in accordance with BS5837:2012 *Trees In relation to design, demolition and construction – Recommendations*, and to produce an Arboricultural Impact Assessment, Arboricultural Method Statement and Tree Protection Plan. The instruction was received on the 11th July 2023. The tree survey was carried out on the 13th July 2023.

## 2.0 Statement of purpose

The purpose of this report is to provide local planning authorities with sufficient arboricultural information to consider the effect of the proposed development on nearby trees, and to demonstrate that trees have been carefully considered throughout the development process.

The report includes an arboricultural method statement that describes how work will be undertaken to provide adequate protection of retained trees.

## 3.0 Associated documents and drawings

This report should be read in conjunction with the following documents and drawings:

1. MA All in One Rev A
2. British Standards Institute - BS5837:2012 *Trees in relation to design, demolition and construction – Recommendations*
3. Tree Protection Plan – AATPP26PA

## 4.0 Site Description

The site is in the urban area of Hillingdon. The site is relatively flat with no abrupt changes in levels. The proposal is the erection of a detached residential dwelling. The site falls under the jurisdiction of London Borough of Hillingdon Council who have not been approached to ascertain whether any of the trees on site are protected by a tree preservation order or conservation area.

## 5.0 Vegetation Description

There are no trees within the site, but there are trees just beyond the boundary. Some basic tree protection measures and working methodology (in accordance with BS 5837:2012) will ensure they are not detrimentally affected during construction.

## 6.0 Arboricultural impact assessment

**Table 1: Summary of impacts**

Tree removal	None
Facilitation pruning	None
Demolition within RPA	None
New surfacing within RPA	None
New structures within RPA	None

**Building construction in relation to tree roots:** No tree removal or facilitation pruning is required to facilitate the development. Traditional foundations may be used and will not impact any of the off site trees. There is an existing hard standing around the site which will remain in place during the development.

**Building construction in relation to tree crowns:** It is important that sufficient growing space is allowed between the mature crown extent of each tree and the roof edge of the proposed structures. This is to reduce conflicts of interest in the future and to reduce the pressure to prune trees to keep them clear of roofs: A clearance of two metres from the mature tree crown is generally considered acceptable which is the case with this proposal.

**Tree root and canopy protection:** The RPA (Root protection area) of the retained tree should be protected during the development phase with heras fencing to ensure heavy machinery is not operated, or materials stored within the rooting area. This can be detrimental to the tree, causing soil compaction and root die back. The crowns of retained trees also require protection to avoid damaging branches. The heras fencing should follow the line of the RPA, or crown extent, whichever is greater. Where access is required within the RPA, the heras fencing may be temporarily pulled back and the exposed ground augmented with alternative protection as detailed in the method statement. Alternatively, if hard surfacing is required within the RPA, it may be laid prior to heavy machinery entering the site and following appropriate protocol, in order to provide a hard surface from which to operate. The protection of the RPA and canopy spread is detailed in the Arboricultural Method Statement below.

**Special surfacing:** To avoid the roots of the retained trees being affected by soil compaction, all existing hard surfaces (within the RPAs of retained trees) will be left in situ during demolition and construction and only be removed (by small machinery) at the landscaping stage. For any new surfacing the existing ground will be graded up to form a no dig surface utilising a 3D load spreader, a no-fines aggregate and a porous wearing course. All works close to and within the RPAs will need to be carried out strictly by hand.

**Materials delivery, storage and handling:** Materials should not be handled or stored within the RPAs of retained trees; the load exerted can result in soil compaction and leachate from spills can be toxic to trees.

**Surface drains, soakaways and services:** It is important that services, surface drains and soakaways avoid the RPAs of retained trees as roots can be damaged during trench excavations which is the case for this proposal.

## 7.0 Arboricultural Method Statement

**Implementation and phasing of the proposed development:** Prior to any building work commencing on site, a meeting will be held with the Arboricultural Consultant and Site Manager present. During the meeting details regarding the location of Trunk Protection will be discussed and a time to reconvene in order to assess the protection will be agreed. The schedule of events during the development phase will be as follows:

Tree Protection will be installed as indicated in plan AATPP26PA.

During the development phase, the arboricultural consultant will be notified and asked to supervise any excavating within the RPA of retained trees.

**Protective fencing:** Protective fencing will not be required as the contractors have erected high boarding around the site preventing damage to tree crowns of the off site trees.

**Ground protection:** Temporary ground protection will not be required as there is an existing hard standing around the site. To avoid the roots of the retained trees being affected by soil compaction, all existing hard surfaces (within the RPAs of retained trees) will be left in situ during demolition and construction and only be removed (by small machinery) at the landscaping stage.

**Storage and handling of materials:** This site has sufficient space for materials to be stored and handled.

**Contractors Parking:** There is sufficient space for parking on Parkway.

**Welfare Facilities:** Toilets and hand washing facilities shall be made available within the existing building and there is space for temporary facilities on site.

**Surface drains, soak aways and services:** RPAs will be avoided in the drainage design however, in the unlikely event that existing cables need to be unearthed within an RPA, the method for doing so will accord with the recommendations in the NJUG Publication: Volume 4: Issue 2: 16/11/2007: Guidelines for the planning, installation and maintenance of utility apparatus in proximity to trees. Trenches will be dug by hand and any roots over 2.5cm in diameter will be retained undamaged. Smaller roots may be cut back to the proximal face with a clean, sharp pair of secateurs. The trench backfill around the roots shall be a granular material that can be compacted to the point where it can bear the new surfacing without subsiding but without abrasion of tree roots and without raising the soil bulk density to the point where root growth cannot take place. Should it be necessary, this operation will be overseen by the project arboriculturist.

**Supervision:** Supervision will not be required.

**Treeworks:** No tree works are required.

**Tree planting:** It is respectfully suggested that if additional tree planting is required then this should be secured through an appropriately worded planning condition. Details of size and species should also be agreed with the LA prior to planting.

## Sequencing of Works

Site clearance of a light nature  
Main construction phase  
Hard and soft landscaping  
Removal of all non-essential equipment  
Landscaping hard and soft (if required)  
Completion

## Contacts

### **Architect and Agent:**

Name: V-Design Cad Services Ltd  
Tel: 0203 488 4890  
E: [Info@vdesigncad.co.uk](mailto:Info@vdesigncad.co.uk)

### **Arboricultural Consultant:**

Name: K Chesterman  
Tel: 07375110399  
E: [info@allarboriculture.co.uk](mailto:info@allarboriculture.co.uk)

APPENDIX 1 - Tree Schedule Schedule

Tree No	Species	Height (m)	Trunk Diameter (cm)	Crown spread (m)		Crown height above ground (m)	Life stage	General observations	BS 5837 cat	Root protection area (m)	
1	Oak <i>Quercus robur</i>	8	50	3	3	3	Early Mature	Off site tree. Previously reduced.		C	6.0
				3	3						
2	Cypress Group <i>Cupressus x leylandii</i>	5	20	2	2	1	Early Mature	Off site group. Previously reduced.		C	2.4
				2	2						

## APPENDIX 1 - Tree Schedule Schedule

### Survey Key

#### Diameter (mm)

Stem diameter in millimetres measured at 1.5m above ground level. Where the stem is divided below 1.5m, measurement is taken as directed by BS:5837 Annex C.

#### RPA - Root Protection Area

RPA circle radius is determined from Annex D of BS:5837. R- Radius

#### A – Area

#### Branch Spread (m)

Radial crown spread in metres, measured for each of the four cardinal points of the compass from the centre of the trunk.

N	E
W	S

#### Low branches

Height above ground in metres of the lowest branch and use of the 4 cardinal points of the compass.

#### Age class

(NP) Newly planted – a tree within 3 years after planting

(Y) Young – a tree within its first one third of life expectancy

(EM) Early Mature – a tree within its second third of life expectancy

(M) Mature – a tree in its final one third of life expectancy

(OM) Over Mature – a tree having reached its maximum life span and is declining in health and size due to old age

(V) Veteran – a tree in the second or mature stage of its life and has important wildlife and habitat features including; hollowing or associated decay fungi, holes, wounds and large dead branches.

(A) Ancient – a tree in the ancient or third and final stage of their life that is of interest biologically, aesthetically or culturally because of its age, size and condition

#### Physiological Condition

GOOD – a tree in a healthy condition with no significant problems

FAIR – a tree generally in good health with some problems that can be remediated  
POOR – a tree in poor health with significant problems that can't be remediated  
DEAD – a tree without sufficient live material to sustain life

#### Structural Condition

An assessment of the structural/safe condition of the tree categorised into:

GOOD – a tree in a safe condition with no significant defects

FAIR – a tree in a safe condition at present but with defects or with significant defects that can be remediated  
POOR – a tree with significant defects that can't be remediated.

#### EC - Estimated remaining contribution in years (based on the species and its current condition)

<10 Up to 10 years

10+ 10 years or more

20+ 20 years or more

40+ 40 years or more

#### Category (Tree quality assessment)

Category U – Tree in poor condition that cannot realistically be retained for longer than 10

years Category A – Trees of high quality

Category B – Trees of moderate quality Category


C – Trees of low quality

## APPENDIX 2 – Protective Fencing


Protective fencing should be erected before any construction commences on site. It should also be in position to protect important trees prior to demolition.

Protective fencing should stay in position until all construction activity has finished.

‘Fencing should be established at the minimum distance set out in British Standard 5837:2012 ‘Trees in relation to design, demolition and construction - Recommendations’. Excavations should not encroach into the fence position and it is appropriate to keep at least 0.5m between the fence and any changes in level.



## APPENDIX 3 – Tree Protection Plan



	<b>All Arboriculture</b>	23 Southernhay Avenue	
		Bristol	<b>ALLARBORICULTURE</b>
		BS8 4TJ	
Client:	Mr. Davinder Lachhar		
Consultant:	Kristian Chesterman		
Site:	26 Parkway, Hillingdon, UB10 9JX		
Title:	Tree Protection Plan		
Scale at A2:	1:100	Date:	16/07/2023
		Document Ref.	AATPP26PA