



t: 07884 056 025
e: glen@ghatrees.co.uk
www.ghatrees.co.uk

Site: 9 Linksway, Northwood, HA6 2XA	1:250@A2
Drawing Title: Arboricultural Impact Assessment	Rev B, Dec 2024

Key:

- Category A (Green dot)
- Category B (Blue dot)
- Category C (Grey dot)
- Category U (Red dot)

Tree Number, Species, and Category:

- T1: Oak B1
- T2: Oak B1
- T3: Oak B1
- T4: Pine B1
- T5: Purple leaf plum C1
- T6: Hornbeam B1
- T7: Hornbeam B1
- T8: Oak B1
- T9: Oak B1
- T10: Birch C2
- T11: Birch C2
- T12: Cedar B1
- T13: Birch B2
- T14: Ash C1
- T15: Hornbeam B2
- T16: Beech C1
- T17: Hornbeam C1
- T18: Oak B1
- T19: Oak B1
- T20: Oak B1
- T21: Hornbeam C2
- T22: Leyland cypress C1
- T23: Oak B1
- T24: Hornbeam (340mm dia) B2

Other Features:

- Shrub
- Shrubs
- Dead beech
- Tree has suffered past fire damage on main stem
- Norway maple 400mm dia
- Declining apple tree
- 4.5 degree visibility splay shown dotted
- Proposed two storey
- Existing dwelling and garage shown dotted to be demolished
- Proposed single storey
- 4.5 degree visibility splay shown dotted
- Proposed wrought iron gates, brick piers and low level wall with hedging behind
- Proposed wrought iron gates, brick piers and low level wall with hedging behind
- Proposed garage with accommodation over
- Existing access to be retained
- Proposed access to be altered and re-position
- Linksway
- Lawn
- Patio
- 9 A
- 9 B
- 9 C
- 9 D
- 9 E
- 9 F
- 9 G
- 9 H
- 9 I
- 9 J
- 9 K
- 9 L
- 9 M
- 9 N
- 9 O
- 9 P
- 9 Q
- 9 R
- 9 S
- 9 T
- 9 U
- 9 V
- 9 W
- 9 X
- 9 Y
- 9 Z