

THE POPLARS SITE REPORT

After multiple visits to site to clear ongoing foul drainage issues we decided to run a cctv unit downstream from the blocked drains once cleared. On cctv surveying this drainage it was discovered that there was mass roots at 4mtrs from manhole 2. I then reset up jetting unit and carried out root cutting to remove the bulk of the roots. Due to the ongoing issues with this drainage I would recommend lining of the drainage to stop the roots from entering the system also we could remove some of the local vegetation to stop this becoming an ongoing issue.

