



Plate 5: View towards north-east, in south-eastern area of the site. Building 24, former telesales offices



Plate 6: View towards west, taken from the south-eastern area of the site. Building 25, former animal facilities.



Plate 7: View towards the east, taken from the south-eastern area of the site. Building 27, LV substation.



Plate 8: View towards the north-west, taken from the south-eastern area of the site. Showing decommissioned rectangular above ground storage tank adjacent to building 28.



Plate 9: View towards the north-east, taken from the eastern area of the site. Showing large cylindrical above ground fuel storage tanks within brickwork bund.



Plate 10: View towards the south-east, taken from the eastern area of the site. Showing large cylindrical above ground fuel storage tanks within brickwork bund.



Plate 11: View towards the north-east, taken from the eastern area of the site. Showing back up generator.



Plate 12: View towards the north-east, taken from the southern area of the site. Building 29, former engineering department/H&S.



Plate 13: View towards the north-east, taken from the eastern area of the site. Building 31, former engineering workshop.



Plate 14: View looking south, taken from the eastern area of the site. Showing small above ground fuel storage tank (decommissioned).



Plate 15: View looking east, taken from eastern area of the site. Building 28, boiler plant building.



Plate 16: View looking west, taken from eastern area of the site. Building 30, former animal facilities building.



Plate 17: View looking south-west, taken from eastern area of the site. Building 30, former animal facilities building.



Plate 18: View looking west, taken from eastern area of the site. Cages adjacent to building 30 to the east, which formerly stored clinical wastes.



Plate 19: View looking west, taken from eastern area of the site. Building 36, former hazardous materials store.



Plate 20: View looking north-west, taken from eastern area of the site. Building 33, former archive building.



Plate 21: View looking north-west, taken from north-eastern area of the site. Building 34, barn.



Plate 22: View looking north-east, taken from eastern area of the site. Concrete surface car parking area adjacent to building 22, with soil bund in the back ground.



Plate 23: View looking north, taken from eastern area of the site. Building 22, barn.



Plate 24: View looking north-east, taken from eastern area of the site. Building 22, barn.



Plate 25: View looking south, taken from north-eastern area of the site. Refuse in building 22.



Plate 26: View looking north-east, taken from north-eastern area of the site. Soil bund (approximately 440m³).



Plate 27: View looking south-west, taken from north-eastern area of the site. Showing roadway and building 35 on the right.



Plate 28: View looking north-east, taken from north-eastern area of the site. Building 35, barn.



Plate 29: View looking north-west, taken from northern area of the site. Showing entrance to the field.



Plate 30: View looking north-west, taken from northern area of the site. Field.



Plate 31: View looking south-east, taken from central area of the site.



Plate 32: View looking south-west, taken from central area of the site. Building 40, former offices.



Plate 33: View looking west, taken from central area of the site. Building 17, former offices associated with 'technical operations'.



Plate 34: View looking east, taken from central area of the site. Concrete roadway and soft landscaping.