



1. EXISTING GOOGLE EARTH IMAGERY



2. EXISTING FRONT ELEVATION OF DORMER AT NO.69
photo taken at 10:47 on 11/05/24



3. EXISTING FRONT ELEVATION OF DORMER AT NO.69
photo taken at 10:47 on 11/05/24



4. EXISTING FRONT ELEVATION OF DORMER AT NO.69
photo taken at 10:21 on 08/02/24



5. EXISTING REAR ELEVATION OF DORMER AT NO.69
photo taken at 10:24 on 08/02/24



6. POINT CLOUD SURVEY OF DORMER AT NO.69 (with dimensions)
survey completed on 08/02/24 using Leica BLK laser scanning hardware

				Revision	Date	Notes	<p>THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE PROPERTY OF BIR CONSULTING LTD AND MAY NOT BE REPRODUCED WITHOUT PERMISSION.</p> <p>ALL DIMENSIONS, LEVELS, SLOPES, POSITIONS AND LOCATIONS OF PARTICULARS AS INDICATED ON DRAWINGS ARE TO BE VERIFIED ON SITE PRIOR TO ENGAGING WORKS. ANY DISCREPANCIES MUST BE REPORTED TO THE DESIGN SURVEYOR ENGINEER OR RESPONSIBLE PERSONS IMMEDIATELY.</p>	Client MR & MRS DATTANI				
				Project 71 WOODFORD CRESCENT, PINNER, HA5 3UA				Drawing title EXISTING SITE PHOTOGRAPHS				
				Drawing no. 71WC-108				Scale 1:50@A2 / 1:100@A4	Revision -	Date 05.24		